

# EAST CAROLINA UNIVERSITY

## MENDENHALL STUDENT CENTER

ASSET CODE: MSCB

FACILITY CONDITION ANALYSIS

AUGUST 25, 2010





EAST CAROLINA UNIVERSITY  
Facility Condition Analysis

---

**TABLE OF CONTENTS**

**Section 1: GENERAL ASSET INFORMATION**

A. Asset Executive Summary.....	1.1.1
B. Asset Summary.....	1.2.1
C. Inspection Team Data.....	1.3.1
D. Facility Condition Analysis - Definitions .....	1.4.1
1. Report Description .....	1.4.1
2. Project Classification.....	1.4.2
3. Project Subclass Type .....	1.4.2
4. Priority Class / Sequence .....	1.4.2
5. Priority Class .....	1.4.3
6. City Index Material / Labor Cost / Cost Summaries.....	1.4.3
7. Project Number .....	1.4.4
8. Photo Number .....	1.4.4
9. Life Cycle Cost Model Description and Definitions .....	1.4.4
10. Category Code .....	1.4.5
E. Category Code Report.....	1.5.1

**Section 2: DETAILED PROJECT SUMMARIES AND TOTALS**

A. Detailed Project Totals – Matrix with FCNI Data and Associated Charts .....	2.1.1
B. Detailed Projects by Priority Class / Priority Sequence .....	2.2.1
C. Detailed Projects by Cost within range [ \$0 - < \$100,000 ] .....	2.3.1
D. Detailed Projects by Cost within range [ ≥ \$100,000 - < \$500,000 ].....	2.3.2
E. Detailed Projects by Cost within range [ ≥ \$500,000 ].....	2.3.3
F. Detailed Projects by Project Classification.....	2.4.1
G. Detailed Projects by Project Subclass - Energy Conservation.....	2.5.1
H. Detailed Projects by Category / System Code.....	2.6.1

**Section 3: SPECIFIC PROJECT DETAILS ILLUSTRATING DESCRIPTION / COST .....** 3.1.1

**Section 4: DRAWINGS / PROJECT LOCATIONS**

**Section 5: LIFE CYCLE MODEL SUMMARY AND PROJECTIONS**

A. Building Component Summary.....	5.1.1
B. Expenditure Projections.....	5.2.1

**Section 6: PHOTOGRAPHIC LOG .....** 6.1.1



# FACILITY CONDITION ANALYSIS

## SECTION 1


### GENERAL ASSET INFORMATION



## EXECUTIVE SUMMARY - MENDENHALL STUDENT CENTER

**Building Code:** MSCB  
**Building Name:** MENDENHALL STUDENT CENTER  
**Year Built:** 1974  
**Building Use:** Student Union  
**Square Feet:** 116,900

### PROJECT COSTS BY CLASSIFICATION




### Project Costs by Priority


**Priority 1:** \$6,881  
**Priority 2:** \$1,743,116  
**Priority 3:** \$8,577,207  
**Priority 4:** \$2,994,099  
**Total Project Costs:** **\$13,321,303**

**Facility Replacement Cost:** **\$37,108,237**


**Facility Condition Needs Index (FCNI):** **0.36**  
 (Project Costs / Replacement Cost)



### PROJECT COSTS BY SYSTEM CODE



### LIFE CYCLE MODEL EXPENDITURE PROJECTIONS



**Average Annual Renewal Cost Per SqFt \$5.17**





## B. ASSET SUMMARY

The Mendenhall Student Center was reportedly constructed in 1974, with multiple subsequent additions and renovations over the ensuing years. The last major refurbishment was reportedly completed in the main first floor dining room in 2008. The building is located in the central main campus area and supports the adjacent residential dormitory buildings as well as the general campus population. The modern styled building includes a large central atrium, dining and meeting facilities, and a large 760 fixed seat auditorium. The building exterior includes a facade with exposed concrete structural frame, ornamental architectural concrete panels, and brick masonry. The building incorporates distinctive vertical precast concrete fins at some of the exterior windows to provide sun screening of the glazing systems. This multi-purpose building contains approximately 116,900 square feet of area on three main floors, including a partially below grade basement ground level floor. The reinforced cast-in-place concrete foundation supports a reinforced concrete structural superstructure with exposed areas of waffle pan joists.

The information for this report was gathered during a site visit that concluded on September 14, 2009.

### SITE

The building sits on a sloped parcel of land in a wooded campus setting. Landscaping consists of ornamental planting beds, shrubbery, specimen trees, and areas of turf. Vehicular service access is from the south and southwest and leads to loading docks at the main kitchen and auditorium. Service aprons are concrete pavements in good condition. The building has no designated parking areas other than for Accessibility and service personnel. Irrigation systems were noted to serve the landscaped areas, and due to the overall good condition of the landscaping, they appear to be operating effectively.

Stormwater drainage systems around the building include graded swales, diversion curbs, underground collection and piping systems, and controlled surface runoff that appear to divert water away from the structure adequately. No significant stormwater issues were observed during the on-site review that appear to have negatively impacted the building.

Pedestrian access to the facility is supported by concrete and brick masonry sidewalk systems in the immediate area of the facility that provide compliant ADA access to and from adjacent buildings and parking areas. The pedestrian paving systems are in overall fair to good condition, with isolated areas of settlement and uneven pavements that may potentially represent a liability to the owner. In-place grinding, selective area replacements, and brick paver resets are recommended.

### EXTERIOR STRUCTURE

The building structure is apparently supported by soil bearing spread footings that show no visible evidence of displacement or structural distress. The primary building structural frame includes reinforced concrete, with the predominant building facade being comprised of poured-in-place concrete walls and exposed structural frame, architectural precast concrete panels, and brick masonry.

There is evidence of water infiltration through portions of the ground floor foundation wall in mechanical room G026. Excavation and waterproofing system upgrades are recommended. Improve the slope of grade away from the foundation prior to restoring the landscaping.

Brick masonry veneer is one of the primary exterior facade finishes. While the brick is fundamentally sound, exposure to the elements has caused some deterioration of the mortar joints and expansion joints. Cleaning, surface preparation, selective repairs, and applied finish or penetrating sealant upgrades are recommended to restore the aesthetics and integrity of the building envelope. Selective area work includes masonry wall repairs at the vertical crack located at the auditorium loading dock.

The secondary facade finish includes exposed natural concrete and architectural concrete panels. This exterior concrete has become visibly soiled, and the construction joints are failing. Cleaning, surface preparation, selective repairs, and applied finish upgrades are recommended to restore the aesthetics and integrity of the building envelope. Elastomeric coatings should be applied to all horizontal concrete and panel surfaces to improve water shed and reduce infiltration into the wall assembly.

Portions of the exterior soffits have a painted stucco finish system. The substrate is sound, but exposure to the elements has deteriorated the trowelled stucco finish. There are numerous cracks and substantial color variation. Selective substrate repairs, surface preparation, trowelled finish application, and painting are recommended.

Replacements are recommended for the aging exterior door systems. This project includes the primary and secondary entrance and service doors. The replacement units should maintain the architectural design aspects of this facility and be modern, energy-efficient applications.

Approximately 20 percent of the exterior window wall systems have been replaced since the original construction. The newer systems include insulated glazing units. It is recommended that the remaining older single pane, aluminum-framed window wall applications be upgraded to thermal pane systems. Such double pane systems will reduce the energy required to operate the building. Repair or replacement of the windowsills and trim may also be necessary.

While the west roof section over Hendrix Theatre is only ten years old, the existing multi-ply built-up roofing system over the east section has failed and places the building interior at risk. Future budget modeling should include a provision for the replacement of all failing roofing systems. Replace this roof with a similar application. Replacement or major repairs to flashings, parapets, sealants, and other associated roofing system components should be included with the primary roofing system replacement to achieve the full effective useful life of the new replacement roofing system.

The associated roof drainage inlets are showing signs of ineffective channeling of rainwater from the flat membrane roof to interior piping systems. Repairs or replacement of these drainage systems is recommended to prevent water damage to the building interior. This work should be included with the replacement of the overall membrane roofing system.

## INTERIOR FINISHES / SYSTEMS

The predominant interior finishes in this building are generally in a variety of conditions ranging from poor to fair to relatively new. Interior ceiling, wall, and floor finish applications vary in age and type. These finish systems include suspended acoustical tile ceilings, painted gypsum board, and exposed structure

ceilings, painted walls, exposed brick masonry walls, wood paneling, ceramic tile walls and wainscoting, vinyl flooring tiles, hardwood flooring, ceramic /porcelain floor tiles, and carpeting. Ongoing finish renewals based on their effective useful life cycles are necessary to maintain a quality institutional building interior. Finish upgrades should be considered as part of any future cosmetic improvements or major comprehensive renovation efforts.

The condition of the interior door systems is such that door system replacements are recommended as part of a comprehensive renovation effort. Complete demolition of existing door systems and replacement according to a code compliant plan to protect egress passages properly is recommended.

Portions of the kitchen pantry areas, equipment, and storage cabinetry are in overall poor condition. New fully ADA compliant cabinetry should be installed as part of any future renovation efforts. The fixed seating in the assembly area is showing signs of wear and abuse. These seats should be upgraded during this review period. Replace the existing seating with new folding fixed seats in a similar row configuration. Ensure that ADA requirements are followed with the new seating layout.

The majority of the public area restroom fixtures and finishes are mostly original to the year of construction or latest renovation and do not meet modern accessibility standards. The fixtures are sound but aged and inefficient. The finishes are outdated. A comprehensive restroom renovation, including new fixtures, finishes, partitions, accessories, and dual level drinking fountains, is recommended.

The ground floor employee locker room fixtures and finishes are mostly original to the year of construction or latest major renovation. The fixtures are sound but dated and are spaced such that clearances are not ADA compliant. A comprehensive locker room renovation, including new fixtures, finishes, partitions, and accessories, is recommended. Locker room expansion may be necessary in order to meet modern minimum fixture counts and accessibility legislation.

## ACCESSIBILITY

Current legislation related to accessibility requires that building entrances be wheelchair accessible. To comply with the intent of this legislation, it is recommended that compliant, painted metal handrails be installed at all entrances as required.

Current accessibility legislation requires that places of assembly be accessible to the handicapped. The auditorium has multiple barriers to accessibility. There are no seating spaces designated for wheelchair use. It is recommended that approximately eight seating areas be modified to accommodate persons in wheelchairs. Install transmitter and headphone receiver sets to accommodate those individuals that require audible assistance. The access steps at the auditorium stage lack supportive handrails. It is recommended that wall-mounted, compliant, painted metal handrails be installed.

Current legislation regarding building accessibility by the handicapped requires that stairs have graspable handrails on both sides, that the rails have a specific end geometry, and that the handrails continue horizontally at the landings. In addition, guardrails must prevent the passage of a 4 inch diameter sphere (6 inches in the triangle formed by the lower rail and tread / riser angle). Although the stairs are compliant with the code enforced at the time of construction until a major renovation occurs, they are deficient in handrail and guardrail design relative to current standards. The finishes on the stairs have

also deteriorated or are otherwise unsafe. Future renovation efforts should include comprehensive stair railing and finish upgrades. The installation of contrasting visual stair / step nosings should also be installed at all locations to improve stair safety.

Interior accessible routes generally have wall-mounted informational and directional signage designed for compliance with ADA accessibility standards. The antiquated drinking fountains throughout the building, however, are generally non-compliant with ADA standards and provide only single height fountains for public use. These older drinking fountains should be replaced with dual height units as part of recommended restroom renovations to provide ADA compliant fountains. The adjacent corridor walls at the newly installed fountains may require new alcove construction to provide adequate floor area access.

## HEALTH

Based on the availability of construction materials at the time the building structure was erected, it is possible that asbestos containing material (ACM), lead based paints, and other environmentally negative components may have been used in the original construction of the building. It is recommended that suspect items be tested and, if found to contain asbestos, abated and disposed of according to all applicable national, state, and local regulations.

Walk-in coolers / freezers are in service to support the needs of the food service facilities in this building. The mechanical components of these systems have been in service beyond their expected life cycles. It is recommended that they be replaced.

## FIRE / LIFE SAFETY

The facility appears to have adequate and reasonable egress paths consistent with its age and compliance with building codes at the time of construction / renovation. No apparent building egress deficiencies, obstructed egress pathways or visible compromises to fire-rated assemblies in the egress corridors were observed during the limited on-site review of the building, with some isolated exceptions. Structural fire separations are not maintained according to code requirements for new construction in some areas of this facility. Little or no regard has been given to the passive and active firestopping systems in the building. Moderate structural separation repairs and intumescent passive firestopping should be accomplished promptly. A few of the egress corridors, for example the corridor outside of mechanical room 130, are obstructed by inappropriately stored materials. All obstructive items throughout the building should be removed and an ongoing monitoring program implemented.

This facility is protected by a central fire alarm system. The devices for this system include manual pull stations, audible / visible devices, and smoke detectors. The model 4002 fire alarm panel, which is now obsolete, was manufactured by Simplex and is located in mechanical room G030. There are no visible strobe devices mounted in the restrooms. The fire alarm system is inadequate compared to the current campus standard. It is recommended that this system be replaced.

The building is not protected by any form of automatic fire suppression. Manual, dry chemical fire extinguishers are available. However, it is recommended that an automatic fire suppression system be installed. Install an automatic fire sprinkler system throughout the facility. This project will reduce overall liability and potential for loss.

The exit signs in this facility are LED-illuminated and are connected to the emergency power network. Emergency egress lighting is available through standard interior light fixtures that are connected to the network. All egress lighting systems are adequate and in good condition. There are no proposed projects.

## HVAC

This facility is on the campus steam loop. Hot water is circulated as the heating medium. Two chillers—one water-cooled and one air-cooled—generate chilled water for building cooling. The water-cooled unit is a Trane Centravac unit estimated to have a capacity of approximately 380 tons. This unit should provide good service through the life of this report. The Carrier air-cooled unit, rated 170 tons, was installed in 1988 with the new addition. It has used most of its expected service life and can be expected to require replacement during the period of this report. A Marley cooling tower provides heat rejection for the water-cooled chiller. This unit is approximately 500 tons capacity and is in good condition. With proper maintenance, it will outlast the scope of this report.

The facility is served by a forced air HVAC system with multizone air handling units. The air handling units have hot water heating coils and chilled water cooling coils. The air distribution network furnishes constant volume air to the occupied spaces. The controls for this system are electro-pneumatic. The components of the HVAC systems have aged beyond their statistical life cycles, and the system is inefficient compared to modern standards. It is recommended that the existing HVAC system be replaced and updated.

The food service facility in this building is served by a number of exhaust hoods, some of which are not currently in service and some that are in areas under alteration at the time of the inspection. Hoods 4 and 5 appear to have been in service beyond their expected life cycles and are recommended for replacement. For the replacement systems, provide adequate makeup air and include the required fire suppression systems.

## ELECTRICAL

Incoming 277/480 volt power is distributed by a 2,500 amp main switch added in 1988 when the building addition was constructed. The existing main distribution panel for the original portion of the building was retained along with a new main panel in the addition. These 1,200 amp and 1,600 amp main distribution panels, respectively, are supplied at 480/277 volts by the 2,500 amp switchgear, which is located by the original building main switchboard in mechanical room G030. The original and added portions of the building have a number of step-down transformers ranging from 30 to 500 kVA and 208/120 volt main distribution panels.

It should be anticipated that the 277/480 volt main switchgear and distribution panels will require replacement within the outlook of this report. The secondary transformers and main distribution panels are in satisfactory condition, but are projected to require scheduled replacement within the scope of this analysis.

The electrical distribution network in this facility is a dual voltage configuration. The lighting and major mechanical systems are supported by the 277/480 volt circuits. Original building panels were manufactured predominantly by General Electric. Most of those originally installed in the addition were

made by Westinghouse. The electrical devices in this facility are aged and visibly worn. It should be anticipated that major components of the distribution network will require replacement during the term of this report.

The interior spaces of this facility are illuminated by fixtures that use compact fluorescent and T12 fluorescent lamps. The fluorescent fixtures are predominantly lay-in applications with acrylic lenses. Some fixtures are still fitted with inefficient, incandescent lamps. The lenses on the light fixtures are aged and often discolored or cracked. The interior lighting has generally served beyond its expected life cycle and is recommended for replacement. Specify energy-efficient light fixtures for the new interior lighting systems, and install occupancy sensors where possible.

Exterior illumination is provided primarily by downlights under covered areas and one or more HID wall-mounted fixtures. A lighting contactor supplied by the new addition supports thirty pole lights in the area. These exterior lighting systems are expected to remain serviceable through the period of this report.

Emergency power for this facility is produced by a diesel-fired emergency generator located in mechanical room G030. This unit has a 50 kW capacity and was manufactured by Cummins. The generator is currently adequate. However, in order to provide reliable emergency power to the critical systems in this facility, it is recommended that this generator be replaced.

## PLUMBING

Potable water is distributed throughout this facility through a copper piping network. Sanitary waste and storm water piping is primarily of bell-and-spigot and no-hub cast-iron. Some plastic piping is also used. The supply piping network in the original portion of the facility is aged and should be replaced to preclude excessive deterioration leading to significant leaks and potential collateral damage. Plumbing fixtures are well into their service lives but are expected to remain serviceable with normal maintenance and selective component replacements until replaced as part of a major restroom renovation.

Domestic water for this facility is heated by steam to hot water heat exchangers with a 119 gallon tank and circulating pumps in the distribution network. The older of the two heat exchangers is approaching the end of its service life and is expected to require replacement within the life of this report.

## VERTICAL TRANSPORTATION

The University commissioned an outside contractor to perform an elevator condition study in 2009. The aforementioned study did not identify any deficiencies requiring capital funding.

Note: The deficiencies outlined in this report were noted from a visual inspection. ISES engineers and architects developed projects with related costs that are needed over the next ten-year period to bring the facility to “like-new” condition. The costs developed do not represent the cost of a complete facility renovation. Soft costs not represented in this report include telecommunications, furniture, window treatment, space change, program issues, relocation, swing space, contingency, or costs that could not be identified or determined from the visual inspection and available building information. However, existing fixed building components and systems were thoroughly inspected. The developed costs represent correcting existing deficiencies and anticipated life cycle failures (within a ten-year period) to bring the facility to modern standards without any anticipation of change to facility space layout or function. Please refer to Section Three of this report for recommended Specific Project Details.

### C. INSPECTION TEAM DATA

**DATE OF INSPECTION:** September 14, 2009

**INSPECTION TEAM PERSONNEL:**

<u>NAME</u>	<u>POSITION</u>	<u>SPECIALTY</u>
Thomas Ferguson, AIA, LEED® AP	Project Architect	Interior Finishes / Exterior / ADA- Handicapped Accessibility / Site / Fire Safety / Life Safety / Health
Rob Gasaway, Q.E.I.	Facility Analyst	Interior Finishes / Exterior / ADA- Handicapped Accessibility / Site / Fire Safety / Life Safety / Health
John Holder, Q.E.I.	Project Engineer	Mechanical / Electrical / Plumbing / Energy / Fire Safety / Life Safety / Health
Imelda Jordan	Project Engineer	Mechanical / Electrical / Plumbing / Energy / Fire Safety / Life Safety / Health
James Lewis	Project Engineer	Mechanical / Electrical / Plumbing / Energy / Fire Safety / Life Safety / Health
Carl Mason, PE, BSCP	Project Engineer	Interior Finishes / Exterior / ADA- Handicapped Accessibility / Site / Fire Safety / Life Safety / Health
Paul Southwell	Project Engineer	Mechanical / Electrical / Plumbing / Energy / Fire Safety / Life Safety / Health
Norm Teahan, RA, AIA, NCARB	Project Architect	Interior Finishes / Exterior / ADA- Handicapped Accessibility / Site / Fire Safety / Life Safety / Health

**FACILITY CONTACTS:**

<u>NAME</u>	<u>POSITION</u>
William Bagwell	Associate Vice Chancellor, Campus Operations

**REPORT DEVELOPMENT:**

Report Development by: ISES Corporation  
2165 West Park Court  
Suite N  
Stone Mountain, GA 30087

Contact: Kyle Thompson, Project Manager  
770-879-7376



## D. FACILITY CONDITION ANALYSIS - DEFINITIONS

The following information is a clarification of Asset Report Sections using example definitions.

### 1. REPORT DESCRIPTION

Section 1: Asset Executive Summary, Asset Summary, and General Report Information

Section 2: Detailed Project Summaries and Totals

- A. Detailed Project Totals – Matrix with FCNI Data and Associated Charts
- B. Detailed Projects by Priority Class / Priority Sequence
- C. Detailed Projects by Cost within range [ \$0 - < \$100,000 ]
- D. Detailed Projects by Cost within range [ ≥ \$100,000 - < \$500,000 ]
- E. Detailed Projects by Cost within range [ ≥ \$500,000 ]
- F. Detailed Projects by Project Classification
- G. Detailed Projects by Project Rating Type - Energy Conservation
- H. Detailed Projects by Category / System Code

FCNI = Facility Condition Needs Index, Total Cost vs. Replacement Cost. The FCNI provides a life cycle cost comparison. Facility replacement cost is based on replacement with current construction standards for facility use type, and not original design parameters. This index gives the University a comparison within all buildings for identifying worst case / best case building conditions.

$$\text{FCNI} = \frac{\text{Deferred Maintenance / Modernization} + \text{Capital Renewal} + \text{Plant Adaption}}{\text{Plant / Facility Replacement Cost}}$$

Section 3: Specific Project Details Illustrating Description / Cost

Section 4: Drawings with Iconography

The drawings for this facility are marked with ICONS (see legend), denoting the specific location(s) for each project. Within each ICON is the last four characters of the respective project number (e.g., 0001IS01 is marked on plan by IS01). There is one set of drawings marked with ICONS representing all priority classes (1, 2, 3, and 4).

Section 5: Life Cycle Model Summary and Projections

Section 6: Photographic Log

## 2. PROJECT CLASSIFICATION

- A. Plant / Program Adaption: Expenditures required to adapt the physical plant to the evolving needs of the institution and to changing codes or standards. These are expenditures beyond normal maintenance. Examples include compliance with changing codes (e.g. accessibility), facility alterations required by changed teaching or research methods, and improvements occasioned by the adoption of modern technology (e.g., the use of personal computer networks).
- B. Deferred Maintenance: Refers to expenditures for repairs which were not accomplished as a part of normal maintenance or capital repair which have accumulated to the point that facility deterioration is evident and could impair the proper functioning of the facility. Costs estimated for deferred maintenance projects should include compliance with applicable codes, even if such compliance requires expenditures beyond those essential to affect the needed repairs. Deferred maintenance projects represent catch up expenses.
- C. Capital Renewal: A subset of regular or normal facility maintenance which refers to major repairs or the replacement / rebuilding of major facility components (e.g., roof replacement at the end of its normal useful life is capital repair; roof replacement several years after its normal useful life is deferred maintenance).

## 3. PROJECT SUBCLASS TYPE

- A. Energy Conservation: Projects with energy conservation opportunities, based on simple payback analysis.

## 4. PRIORITY SEQUENCE BY PRIORITY CLASS (Shown in Sections 2 and 3)

All projects are assigned both a Priority Sequence number and Priority Class number for categorizing and sorting projects based on criticality and recommended execution order.

Example:

	<u>PRIORITY CLASS 1</u>	
CODE	PROJECT NO.	PRIORITY SEQUENCE
HV2C	0001HV04	01
PL1D	0001PL02	02

	<u>PRIORITY CLASS 2</u>	
CODE	PROJECT NO.	PRIORITY SEQUENCE
IS1E	0001IS06	03
EL4C	0001EL03	04

## 5. PRIORITY CLASS (Shown in Sections 2 and 3)

### PRIORITY 1 - Currently Critical (Immediate)

Projects in this category require immediate action to:

- a. return a facility to normal operation
- b. stop accelerated deterioration
- c. correct a cited safety hazard

### PRIORITY 2 - Potentially Critical (Year One)

Projects in this category, if not corrected expeditiously, will become critical within a year. Situations in this category include:

- a. intermittent interruptions
- b. rapid deterioration
- c. potential safety hazards

### PRIORITY 3 - Necessary - Not Yet Critical (Years Two to Five)

Projects in this category include conditions requiring appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further.

### PRIORITY 4 - Recommended (Years Six to Ten)

Projects in this category include items that represent a sensible improvement to existing conditions. These items are not required for the most basic function of a facility; however, Priority 4 projects will either improve overall usability and / or reduce long-term maintenance.

## 6. COST SUMMARIES AND TOTALS

The cost summaries and totals are illustrated by Detailed Projects sorted in multiple formats (shown in Sections 2 and 3).

City Index material / labor cost factors: (shown in Sections 2 and 3)

Cost factors are based on the Greenville City Index and are adjusted for material and labor cost factors (2009). Refer to the project related labor report found later in this section.

#### Global Markup Percentages

#### R.S. MEANS

Local Labor Index:	51.3 %	of National Average
Local Materials Index:	100.7 %	of National average
General Contractor Markup:	20.0 %	Contractor profit & overhead, bonds & insurance
Professional Fees:	16.0 %	Arch. / Eng. Firm design fees and in-house design cost

**7. PROJECT NUMBER** (Shown in Sections 2 and 3)

Example:

Project Number = 0001-EL-04 (unique for each independent project)

- 0001 - Building Identification Number
- EL - System Code, EL represents Electrical
- 04 - Sequential Assignment Project Number by Category / System

**8. PHOTO NUMBER** (Shown in Section 6)

A code shown on the Photographic Log identifies the building number, photo sequence, and architect, engineer, or vertical transportation.

Example: 0001006e

<u>Building Number</u>	<u>Photo Sequence</u>	<u>Arch / Eng / VT</u>
0001	006	e

**9. LIFE CYCLE COST MODEL DESCRIPTION AND DEFINITIONS** (Shown in Section 5)

Included in this report is a Life Cycle Cost Model. This model consists of two elements, one is the component listing (starting on page 5.1.1) and the other is the Life Cycle Cost Projections Graph (page 5.2.1). The component list is a summary of all major systems and components within the facility. Each indicated component has the following associated information:

Uniformat Code	This is the standard Uniformat Code that applies to the component
Component Description	This line item describes the individual component
Qty	The quantity of the listed component
Units	The unit of measure associated with the quantity
Unit Cost	The cost to replace each individual component unit (This cost is in today's dollars)
Total Cost	Unit cost multiplied by Quantity, also in today's dollars. Note that this is a one time renewal / replacement cost
Install Date	Year that the component was installed. Where this data is not available, it defaults to the year the asset was constructed
Life Exp	Average life expectancy for each individual component

The component listing forms the basis for the Life Cycle Cost Projections Graph shown on page 5.2.1. This graph represents a projection over a fifty-year period (starting from the date the report is run) of expected component renewals based on each individual item's renewal cost and life span. Some components might require renewal several times within the fifty-year model, while others might not occur at all. Each individual component is assigned a renewal year based on life cycles, and the costs for each item are inflated forward to the appropriate year. The vertical bars shown on the graph represent the accumulated (and inflated) total costs for each individual year. At the bottom of the graph, the average annual cost per gross square foot (\$/GSF) is shown for the facility. In this calculation, all costs are not inflated. This figure can be utilized to assess the adequacy of existing capital renewal and repair budgets.

**10. CATEGORY CODE** (Shown in Sections 2 and 3)

Refer to the following Category Code Report.

Example: Category Code = EL5A

EL = System Description  
5 = Component Description  
A = Element Description

**CATEGORY CODE**

AC1A - AC4B  
EL1A - EL8A  
ES1A - ES6E  
FS1A - FS6A  
HE1A - HE7A  
HV1A - HV8B  
IS1A - IS6D  
PL1A - PL5A  
SI1A - SI4A  
SS1A - SS7A  
VT1A - VT7A

**SYSTEM DESCRIPTION**

ACCESSIBILITY  
ELECTRICAL  
EXTERIOR STRUCTURE  
FIRE / LIFE SAFETY  
HEALTH  
HVAC  
INTERIOR FINISHES / SYSTEMS  
PLUMBING  
SITE  
SECURITY SYSTEMS  
VERTICAL TRANSPORTATION

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
<b>SYSTEM DESCRIPTION: ACCESSIBILITY</b>			
AC1A	SITE	STAIR AND RAILINGS	Includes exterior stairs and railings which are not part of the building entrance points.
AC1B	SITE	RAMPS AND WALKS	Includes sidewalks, grade change ramps (except for a building entrance), curb ramps, etc.
AC1C	SITE	PARKING	Designated parking spaces including striping, signage, access aisles and ramps, etc.
AC1D	SITE	TACTILE WARNINGS	Raised tactile warnings located at traffic crossing and elevation changes.
AC2A	BUILDING ENTRY	GENERAL	Covers all aspects of entry into the building itself including ramps, lifts, doors and hardware, power operators, etc.
AC3A	INTERIOR PATH OF TRAVEL	LIFTS/RAMPS/ELEVATORS	Interior lifts, ramps and elevators designed to accommodate level changes inside a building. Includes both installation and retrofitting.
AC3B	INTERIOR PATH OF TRAVEL	STAIRS AND RAILINGS	Upgrades to interior stairs and handrails for accessibility reasons.
AC3C	INTERIOR PATH OF TRAVEL	DOORS AND HARDWARE	Accessibility upgrades to the interior doors including widening, replacing hardware power, assisted operators, etc.
AC3D	INTERIOR PATH OF TRAVEL	SIGNAGE	Interior building signage upgrades for compliance with ADA.
AC3E	INTERIOR PATH OF TRAVEL	RESTROOMS/BATHROOMS	Modifications to and installation of accessible public restrooms and bathrooms. Bathrooms, which are an integral part of residential suites, are catalogued under HC4A.
AC3F	INTERIOR PATH OF TRAVEL	DRINKING FOUNTAINS	Upgrading/replacing drinking fountains for reasons of accessibility.
AC3G	INTERIOR PATH OF TRAVEL	PHONES	Replacement/modification of public access telephones.
AC4A	GENERAL	FUNCTIONAL SPACE MODIFICATIONS	This category covers all necessary interior modifications necessary to make the services and functions of a building accessible. It includes installation of assistive listening systems, modification of living quarters, modifications to laboratory workstations, etc. Bathrooms, which are integral to efficiency suites, are catalogued here.
AC4B	GENERAL	OTHER	All accessibility issues not catalogued elsewhere.
<b>SYSTEM DESCRIPTION: ELECTRICAL</b>			
EL1A	INCOMING SERVICE	TRANSFORMER	Main building service transformer.
EL1B	INCOMING SERVICE	DISCONNECTS	Main building disconnect and switchgear.
EL1C	INCOMING SERVICE	FEEDERS	Incoming service feeders. Complete incoming service upgrades, including transformers, feeders, and main distribution panels are catalogued here.
EL1D	INCOMING SERVICE	METERING	Installation of meters to record consumption and/or demand.
EL2A	MAIN DISTRIBUTION PANELS	CONDITION UPGRADE	Main distribution upgrade due to deficiencies in condition.
EL2B	MAIN DISTRIBUTION PANELS	CAPACITY UPGRADE	Main distribution upgrades due to inadequate capacity.
EL3A	SECONDARY DISTRIBUTION	STEP DOWN TRANSFORMERS	Secondary distribution stepdown and isolation transformers.
EL3B	SECONDARY DISTRIBUTION	DISTRIBUTION NETWORK	Includes conduit, conductors, sub-distribution panels, switches, outlets, etc. Complete interior rewiring of a facility is catalogued here.
EL3C	SECONDARY DISTRIBUTION	MOTOR CONTROLLERS	Mechanical equipment motor starters and control centers.
EL4A	DEVICES AND FIXTURES	EXTERIOR LIGHTING	Exterior building lighting fixtures including supply conductors and conduit.
EL4B	DEVICES AND FIXTURES	INTERIOR LIGHTING	Interior lighting fixtures (also system wide emergency lighting) including supply conductors and conduits.
EL4C	DEVICES AND FIXTURES	LIGHTING CONTROLLERS	Motion sensors, photocell controllers, lighting contactors, etc.

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
EL4D	DEVICES AND FIXTURES	GFCI PROTECTION	Ground fault protection including GFCI receptacles and breakers.
EL4E	DEVICES AND FIXTURES	LIGHTNING PROTECTION	Lightning arrestation systems including air terminals and grounding conductors.
EL5A	EMERGENCY POWER SYSTEM	GENERATION/DISTRIBUTION	Includes generators, central battery banks, transfer switches, emergency power grid, etc.
EL6A	SYSTEMS	UPS/DC POWER SUPPLY	Uninterruptible power supply systems and DC motor-generator sets and distribution systems.
EL7A	INFRASTRUCTURE	ABOVE GROUND TRANSMISSION	Includes poles, towers, conductors, insulators, fuses, disconnects, etc.
EL7B	INFRASTRUCTURE	UNDERGROUND TRANSMISSION	Includes direct buried feeders, ductbanks, conduit, manholes, feeders, switches, disconnects, etc.
EL7C	INFRASTRUCTURE	SUBSTATIONS	Includes incoming feeders, breakers, buses, switchgear, meters, CTs, PTs, battery systems, capacitor banks, and all associated auxiliary equipment.
EL7D	INFRASTRUCTURE	DISTRIBUTION SWITCHGEAR	Stand-alone sectionalizing switches, distribution switchboards, etc.
EL7F	INFRASTRUCTURE	AREA AND STREET LIGHTING	Area and street lighting systems including stanchions, fixtures, feeders, etc.
EL8A	GENERAL	OTHER	Electrical system components not catalogued elsewhere.
<b>SYSTEM DESCRIPTION: EXTERIOR</b>			
ES1A	FOUNDATION/FOOTING	STRUCTURE	Structural foundation improvements involving structural work on foundation wall/footing, piers, caissons, piles including crack repairs, shoring & pointing
ES1B	FOUNDATION/FOOTING	DAMPPROOFING/DEWATERING	Foundation/footing waterproofing work including, damp proofing, dewatering, insulation, etc.
ES2A	COLUMNS/BEAMS/WALLS	STRUCTURE	Structural work to primary load-bearing structural components aside from floors including columns, beams, bearing walls, lintels, arches, etc.
ES2B	COLUMNS/BEAMS/WALLS	FINISH	Work involving restoration of the appearance and weatherproof integrity of exterior wall/structural envelope components including masonry/pointing, expansion joints, efflorescence & stain removal, grouting, surfacing, chimney repairs, etc.
ES3A	FLOOR	STRUCTURE	Work concerning the structural integrity of the load supporting floors both exposed and unexposed including deformation, delamination, spalling, shoring, crack repair, etc.
ES4A	ROOF	REPAIR	Work on waterproof horizontal finish (roof) involving repair and/or limited replacement (<40% total) including membrane patching, flashing repair, coping caulk/resetting, PPT wall parging/coating, walkpad installation, skylight and roof hatch R&R, etc.
ES4B	ROOF	REPLACEMENT	Work involving total refurbishment of roofing system including related component rehab.
ES5A	FENESTRATIONS	DOORS	Work on exterior exit/access door including storefronts, airlocks, air curtains, vinyl slat doors, all power/manual operating hardware (except handicapped), etc.
ES5B	FENESTRATIONS	WINDOWS	Work on exterior fenestration closure & related components including glass/metal/wood curtain walls, fixed or operable window sashes, glazing, frames, sills, casings, stools, seats, coatings, treatments, screens, storm windows, etc.
ES6A	GENERAL	ATTACHED STRUCTURE	Work on attached exterior structure components not normally considered in above categories including porches, stoops, decks, monumental entrance stairs, cupolas, tower, etc.
ES6B	GENERAL	AREAWAYS	Work on attached grade level or below structural features including subterranean light wells, areaways, basement access stairs, etc.
ES6C	GENERAL	TRIM	Work on ornamental exterior (generally non-structural) elements including beltlines, quoins, porticos, soffits, cornices, moldings, trim, etc.
ES6D	GENERAL	SUPERSTRUCTURE	Finish and structural work on non-standard structures with exposed load-bearing elements such as stadiums, bag houses, bleachers, freestanding towers, etc.

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
ES6E	GENERAL	OTHER	Any exterior work not specifically categorized elsewhere including finish and structural work on freestanding boiler stacks.
<b>SYSTEM DESCRIPTION: FIRE / LIFE SAFETY</b>			
FS1A	LIGHTING	EGRESS LIGHTING/EXIT SIGNAGE	R & R work on exit signage and packaged AC/DC emergency lighting.
FS2A	DETECTION/ALARM	GENERAL	Repair or replacement of fire alarm/detection system/components including alarms, pull boxes, smoke/heat detectors, annunciator panels, central fire control stations, remote dialers, fire station communications, etc.
FS3A	SUPPRESSION	SPRINKLERS	Repair or installation of water sprinklers type automatic fire suppressions including wet pipe & dry pipe systems, heads, piping, deflectors, valves, monitors, associated fire pump, etc.
FS3B	SUPPRESSION	STANDPIPE/HOSE	Repair or installation of standpipe system or components including hardware, hoses, cabinets, nozzles, necessary fire pumping system, etc.
FS3C	SUPPRESSION	EXTINGUISHERS	Repairs or upgrades to F.E. cabinets/wall fastenings and handheld extinguisher testing/replacement.
FS3D	SUPPRESSION	OTHER	Other fire suppression items not specifically categorized elsewhere including fire blankets, carbon dioxide automatic systems, Halon systems, dry chemical systems, etc.
FS4A	HAZARDOUS MATERIALS	STORAGE ENVIRONMENT	Installation or repair of special storage environment for the safe holding of flammable or otherwise dangerous materials/supplies including vented flammables storage cabinets, holding pens/rooms, cages, fire safe chemical storage rooms, etc.
FS4B	HAZARDOUS MATERIALS	USER SAFETY	Improvements, repairs, installation, or testing of user safety equipment including emergency eyewashes, safety showers, emergency panic/shut-down system, etc.
FS5A	EGRESS PATH	DESIGNATION	Installation, relocation or repair of posted diagrammatic emergency evacuation routes.
FS5B	EGRESS PATH	DISTANCE/GEOMETRY	Work involving remediation of egress routing problems including elimination of dead end corridors, excessive egress distance modifications and egress routing inadequacies.
FS5C	EGRESS PATH	SEPARATION RATING	Restoration of required fire protective barriers including wall rating compromises, fire rated construction, structural fire proofing, wind/safety glazing, transom retrofitting, etc.
FS5D	EGRESS PATH	OBSTRUCTION	Clearance of items restricting the required egress routes.
FS5E	EGRESS PATH	STAIRS RAILING	Retrofit of stair/landing configurations/structure, railing heights/geometries, etc.
FS5F	EGRESS PATH	FIRE DOORS/HARDWARE	Installation/replacement/repair of fire doors and hardware including labeled fire doors, fire shutters, closers, magnetic holders, panic hardware, etc.
FS5G	EGRESS PATH	FINISH/FURNITURE RATINGS	Remediation of improper fire/smoke ratings of finishes and furniture along egress routes.
FS6A	GENERAL	OTHER	Life/fire safety items not specifically categorized elsewhere.
<b>SYSTEM DESCRIPTION: HEALTH</b>			
HE1A	ENVIRONMENTAL CONTROL	EQUIPMENT AND ENCLOSURES	Temperature control chambers (both hot and cold) for non-food storage. Includes both chamber and all associated mechanical equipment.
HE1B	ENVIRONMENTAL CONTROL	OTHER	General environmental control problems not catalogued elsewhere.
HE2A	PEST CONTROL	GENERAL	Includes all measures necessary to control and destroy insects, rodents and other pests.
HE3A	REFUSE	GENERAL	Issues related to the collection, handling and disposal of refuse.
HE4A	SANITATION EQUIPMENT	LABORATORY AND PROCESS	Includes autoclaves, cage washers, steam cleaners, etc.
HE5A	FOOD SERVICE	KITCHEN EQUIPMENT	Includes ranges, grilles, cookers, sculleries, etc.
HE5B	FOOD SERVICE	COLD STORAGE	Includes the cold storage room and all associated refrigeration equipment.



CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
HE6A	HAZARDOUS MATERIAL	STRUCTURAL ASBESTOS	Testing, abatement and disposal of structural and building finish materials containing asbestos.
HE6B	HAZARDOUS MATERIAL	MECHANICAL ASBESTOS	Testing, abatement and disposal of mechanical insulation materials containing asbestos.
HE6C	HAZARDOUS MATERIAL	PCBs	Includes testing, demolition, disposal and cleanup of PCB contaminated substances.
HE6D	HAZARDOUS MATERIAL	FUEL STORAGE	Includes monitoring, removal and replacement of above and below ground fuel storage and distribution systems. Also includes testing and disposal of contaminated soils.
HE6E	HAZARDOUS MATERIAL	LEAD PAINT	Testing, removal and disposal of lead-based paint systems.
HE6F	HAZARDOUS MATERIAL	OTHER	Handling, storage, and disposal of other hazardous materials.
HE7A	GENERAL	OTHER	Health related issues not catalogued elsewhere.
<b>SYSTEM DESCRIPTION: HVAC</b>			
HV1A	HEATING	BOILERS/STACKS/ CONTROLS	Boilers for heating purposes including their related stacks, flues, and controls.
HV1B	HEATING	RADIATORS/ CONVECTORS	Including cast iron radiators, fin tube radiators, baseboard radiators, etc.
HV1C	HEATING	FURNACE	Furnaces and their related controls, flues, etc.
HV1D	HEATING	FUEL SUPPLY/STORAGE	Storage and/or distribution of fuel for heating purposes, including tanks and piping networks and related leak detection/monitoring.
HV2A	COOLING	CHILLERS/ CONTROLS	Chiller units for production of chilled water for cooling purposes, related controls (not including mods for CFC compliance).
HV2B	COOLING	HEAT REJECTION	Repair/replacement of cooling towers, dry coolers, air-cooling and heat rejection. (Includes connection of once-through system to cooling tower.)
HV3A	HEATING/COOLING	SYSTEM RETROFIT/ REPLACE	Replacement or major retrofit of HVAC systems.
HV3B	HEATING/COOLING	WATER TREATMENT	Treatment of hot water, chilled water, steam, condenser water, etc.
HV3C	HEATING/COOLING	PACKAGE/SELF-CONTAINED UNITS	Repair/replacement of self-contained/package type units including stand up units, rooftop units, window units, etc; both air conditioners and heat pumps.
HV3D	HEATING/COOLING	CONVENTIONAL SPLIT SYSTEMS	Repair, installation, or replacement of conventional split systems; both air conditioners and heat pumps including independent component replacements of compressors and condensers.
HV4A	AIR MOVING/ VENTILATION	AIR HANDLERS/ FAN UNITS	Includes air handlers & coils, fan coil units, unit ventilators, filtration upgrades, etc., not including package/self-contained units, split systems or other specifically categorized systems.
HV4B	AIR MOVING/ VENTILATION	EXHAUST FANS	Exhaust fan systems including fans, range and fume hoods, controls, and related ductwork.
HV4C	AIR MOVING/ VENTILATION	OTHER FANS	Supply, return, or any other fans not incorporated into a component categorized elsewhere.
HV4D	AIR MOVING/ VENTILATION	AIR DISTRIBUTION NETWORK	Repair, replacement, or cleaning of air distribution network including ductwork, terminal reheat/cool, VAV units, induction units, power induction units, insulation, dampers, linkages, etc.
HV5A	STEAM/HYDRONIC DISTRIBUTION	PIPING NETWORK	Repair/replacement of piping networks for heating and cooling systems including pipe, fittings, insulation, related components, etc.
HV5B	STEAM/HYDRONIC DISTRIBUTION	PUMPS	Repair or replacement of pumps used in heating and cooling systems, related control components, etc.
HV5C	STEAM/HYDRONIC DISTRIBUTION	HEAT EXCHANGERS	Including shell and tube heat exchangers and plate heat exchangers for heating and cooling.
HV6A	CONTROLS	COMPLETE SYSTEM	Replacement of HVAC control systems.

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
		UPGRADE	
HV6B	CONTROLS	MODIFICATIONS/ REPAIRS	Repair or modification of HVAC control system.
HV6C	CONTROLS	AIR COMPRESSORS/ DRYERS	Repair or modification of control air compressors and dryers.
HV7A	INFRASTRUCTURE	STEAM/HOT WATER GENERATION	Generation of central steam and/or hot water including boilers and related components.
HV7B	INFRASTRUCTURE	STEAM/HOT WATER DISTRIBUTION	Distribution system for central hot water and/or steam.
HV7C	INFRASTRUCTURE	CHILLED WATER GENERATION	Generation of central chilled water including chillers and related components.
HV7D	INFRASTRUCTURE	CHILLED WATER DISTRIBUTION	Distribution system for central chilled water.
HV7E	INFRASTRUCTURE	TUNNELS/ MANHOLES/ TRENCHES	Repairs, installation, replacement of utility system access chambers.
HV7F	INFRASTRUCTURE	OTHER	HVAC infrastructure issues not specifically categorized elsewhere.
HV8A	GENERAL	CFC COMPLIANCE	Chiller conversions/replacements for CFC regulatory compliance, monitoring, etc.
HV8B	GENERAL	OTHER	HVAC issues not catalogued elsewhere.
<b>SYSTEM DESCRIPTION: INTERIOR FINISHES / SYSTEMS</b>			
IS1A	FLOOR	FINISHES-DRY	R & R of carpet, hardwood strip flooring, concrete coating, vinyl linoleum & tile, marble, terrazzo, rubber flooring, underlayment in predominantly dry areas ("dry" includes non-commercial kitchens)
IS1B	FLOOR	FINISHES-WET	Flooring finish/underlayment work in predominantly "wet" areas including work with linoleum, rubber, terrazzo, concrete coating, quarry tile, ceramic tile, epoxy aggregate, etc.
IS2A	PARTITIONS	STRUCTURE	Structural work on full height permanent interior partitions including wood/metal stud & drywall systems, CMU systems, structural brick, tile, glass block, etc.
IS2B	PARTITIONS	FINISHES	Work on full height permanent interior partitions including R & R to gypsum board, plaster, lath, wood paneling, acoustical panels, wall coverings, column coverings, tile, paint, etc.
IS3A	CEILINGS	REPAIR	Repair of interior ceilings (<40% of total) including tiles, gypsum board, plaster, paint, etc.
IS3B	CEILINGS	REPLACEMENT	Major refurbishments (>40% of total) to interior ceiling systems including grid system replacements, structural framing, new suspended systems, paint, plastering, etc.
IS4A	DOORS	GENERAL	Any work on interior non-fire rated doors, roll-up counter doors, mechanical/plumbing access doors, and all door hardware (except for reasons of access improvement).
IS5A	STAIRS	FINISH	Any finish restorative work to stair tower walking surfaces including replacement of rubber treads, safety grips, nosings, etc. (except as required to accommodate disabled persons).
IS6A	GENERAL	MOLDING	R & R to interior trim/molding systems including rubber/vinyl/wood base, crown/chair/ornamental moldings, cased openings, etc.
IS6B	GENERAL	CABINETY	R & R work to interior casework systems including cabinets, countertops, wardrobes, lockers, mail boxes, built-in bookcases, lab/work benches, reagent shelving, etc. (except as required for access by the disabled).
IS6C	GENERAL	SCREENING	Work on temporary or partial height partitioning systems including toilet partitions, urinal/vanity screens, etc.
IS6D	GENERAL	OTHER	Any work on interior elements not logically or specifically categorized elsewhere including light coves, phone booths, interior light wells, etc.
<b>SYSTEM DESCRIPTION: PLUMBING</b>			

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
PL1A	DOMESTIC WATER	PIPING NETWORK	Repair or replacement of domestic water supply piping network, insulation, hangers, etc.
PL1B	DOMESTIC WATER	PUMPS	Domestic water booster pumps, circulating pumps, related controls, etc.
PL1C	DOMESTIC WATER	STORAGE/ TREATMENT	Equipment or vessels for storage or treatment of domestic water.
PL1D	DOMESTIC WATER	METERING	Installation, repair, or replacement of water meters.
PL1E	DOMESTIC WATER	HEATING	Domestic water heaters including gas, oil, and electric water heaters, shell and tube heat exchangers, tank type and instantaneous.
PL1F	DOMESTIC WATER	COOLING	Central systems for cooling and distributing drinking water.
PL1G	DOMESTIC WATER	FIXTURES	Plumbing fixtures including sinks, drinking fountains, water closets, urinals, etc.
PL1H	DOMESTIC WATER	CONSERVATION	Alternations made to the water distribution system to conserve water.
PL1I	DOMESTIC WATER	BACKFLOW PROTECTION	Backflow protection devices including backflow preventers, vacuum breakers, etc.
PL2A	WASTEWATER	PIPING NETWORK	Repair or replacement of building wastewater piping network.
PL2B	WASTEWATER	PUMPS	Pump systems used to lift wastewater including sewage ejectors and other sump systems.
PL3A	SPECIAL SYSTEMS	PROCESS GAS/FLUIDS	Generation and/or distribution of process steam, compressed air, natural and LP gas, process water, vacuum, etc.
PL4A	INFRASTRUCTURE	POTABLE WATER STORAGE/ TREATMENT	Storage and treatment of potable water for distribution.
PL4B	INFRASTRUCTURE	INDUSTRIAL WATER DISTRIBUTION/ TREATMENT	Storage and treatment of industrial water for distribution.
PL4C	INFRASTRUCTURE	SANITARY WATER COLLECTION	Sanitary water collection systems, sanitary sewer systems; including combined systems.
PL4D	INFRASTRUCTURE	STORM WATER COLLECTION	Storm water collection systems, storm sewer systems; storm water only.
PL4E	INFRASTRUCTURE	POTABLE WATER DISTRIBUTION	Potable water distribution network.
PL4F	INFRASTRUCTURE	WASTEWATER TREATMENT	Wastewater treatment plants, associated equipment, etc.
PL5A	GENERAL	OTHER	Plumbing issues not categorized elsewhere.
<b>SYSTEM DESCRIPTION: SITE</b>			
SI1A	ACCESS	PEDESTRIAN	Paved pedestrian surfaces including walks, site stairs, step ramps, paths, pedestrian signage, sidewalk bridges/canopies, pedestrian plaza/mall areas, etc.
SI1B	ACCESS	VEHICULAR	Paved vehicular surfaces including roads, paths, curbs, guards, bollards, bridges, skyways, joints, shoulder work, culverts, ditches, vehicular signage, etc.
SI2A	LANDSCAPE	GRADE/FLORA	Landscape related work including new grass/turf refurbishment, grade improvements, catch basins, swales, berms, pruning, new ornamental flora, etc.
SI3A	HARDSCAPE	STRUCTURE	Permanent hard site features, predominantly ornamental, including terraces, fences, statues, freestanding signage, fountains, benches, etc.
SI4A	GENERAL	OTHER	Other site work not specifically categorized elsewhere.
<b>SYSTEM DESCRIPTION: SECURITY SYSTEMS</b>			
SS1A	LIGHTING	EXTERIOR	Fixtures, stanchions, foliage interference, cleanliness, locations, etc.

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
SS2A	SITE	FENCING	Perimeter campus fencing, individual building fencing, includes both pedestrian and vehicular control fences.
SS2B	SITE	GENERAL	Hidden areas due to foliage, fencing, parking, walls, etc.
SS3A	COMMUNICATIONS	EMERGENCY PHONES	Access, locations, visibility, function, reliability, etc.
SS4A	ACCESS CONTROL	DOORS	Access, locks, keys, two way speakers, reliability, redundancy, etc.
SS4B	ACCESS CONTROL	WINDOWS	Locks, screens, access, reliability, etc.
SS4C	ACCESS CONTROL	SYSTEMS	Card key, proximity devices, data control, data use, reliability, system design, etc.
SS5A	MONITORING	SYSTEMS	Cameras, audio communication, monitoring stations, locations, system design, etc.
SS6A	CIRCULATION	PEDESTRIAN	On campus as well as to and from off campus housing and class locations, etc.
SS6B	CIRCULATION	VEHICULAR	Guard gates, access, systems, data control and use, identification, etc.
SS7A	GENERAL	OTHER	General information/projects pertaining to security issues.
<b>SYSTEM DESCRIPTION: VERTICAL TRANSPORTATION</b>			
VT1A	MACHINE ROOM	GENERAL	Machine, worm gear, thrust bearing, brake, motors, sheaves, generator, controller, selector, governor, pump(s), valves, oil, access, lighting, ventilation, floor.
VT2A	CAR	GENERAL	Position indicator, lighting, floor, gate-doors, operation devices, safeties, safety shoe, light ray/detection, emergency light, fire fighter service, car top, door operator, stop switch, car frame, car guides, sheaves, phone, ventilation.
VT3A	HOISTWAY	GENERAL	Enclosure, fascia, interlock, doors, hangers, closers, sheaves, rails, hoistway switches, ropes, traveling cables, selector tape, weights, compensation.
VT4A	HALL FIXTURES	GENERAL	Operating panel, position indicator, hall buttons, lobby panel, hall lanterns, fire fighter service, audible signals, card/key access.
VT5A	PIT	GENERAL	Buffer(s), guards, sheaves, hydro packing, floor, lighting, safety controls.
VT6A	OPERATING CONDITIONS	GENERAL	Door open time, door close time, door thrust, acceleration, deceleration, leveling, dwell time, speed, OFR time, nudging.
VT7A	GENERAL	OTHER	General information/projects relating to vertical transportation system components.

FACILITY CONDITION ANALYSIS

**SECTION 2**

**DETAILED PROJECT SUMMARIES  
AND TOTALS**

**Detailed Project Totals  
 Facility Condition Analysis  
 System Code by Priority Class  
 MSCB : MENDENHALL STUDENT CENTER**

System Code	System Description	Priority Classes				Subtotal
		1	2	3	4	
AC	ACCESSIBILITY	0	0	0	208,964	208,964
EL	ELECTRICAL	0	0	1,364,274	1,174,891	2,539,165
ES	EXTERIOR	0	621,482	221,983	1,145,676	1,989,141
FS	FIRE/LIFE SAFETY	6,881	1,121,634	0	0	1,128,515
HE	HEALTH	0	0	31,966	0	31,966
HV	HVAC	0	0	3,681,091	0	3,681,091
IS	INTERIOR/FINISH SYS.	0	0	3,215,578	0	3,215,578
PL	PLUMBING	0	0	34,553	464,568	499,121
SI	SITE	0	0	27,762	0	27,762
	<b>TOTALS</b>	6,881	1,743,116	8,577,207	2,994,099	13,321,303

<b>Facility Replacement Cost</b>	<b>\$37,108,237</b>
<b>Facility Condition Needs Index</b>	<b>0.36</b>


<b>Gross Square Feet</b>	<b>116,900</b>
--------------------------	----------------

<b>Total Cost Per Square Foot</b>	<b>\$113.95</b>
-----------------------------------	-----------------

# FACILITY CONDITION ANALYSIS

## System Code by Priority Class

MSCB : MENDENHALL STUDENT CENTER



**Detailed Project Totals  
Facility Condition Analysis  
System Code by Project Class  
MSCB : MENDENHALL STUDENT CENTER**

System Code	System Description	Project Classes			Subtotal
		Capital Renewal	Deferred Maintenance	Plant Adaption	
AC	ACCESSIBILITY	0	0	208,964	208,964
EL	ELECTRICAL	1,237,369	1,301,796	0	2,539,165
ES	EXTERIOR	1,870,261	118,880	0	1,989,141
FS	FIRE/LIFE SAFETY	0	0	1,128,515	1,128,515
HE	HEALTH	0	31,966	0	31,966
HV	HVAC	201,859	3,479,232	0	3,681,091
IS	INTERIOR/FINISH SYS.	856,984	2,358,593	0	3,215,578
PL	PLUMBING	499,121	0	0	499,121
SI	SITE	0	27,762	0	27,762
	<b>TOTALS</b>	4,665,595	7,318,229	1,337,479	13,321,303

<b>Facility Replacement Cost</b>	<b>\$37,108,237</b>
<b>Facility Condition Needs Index</b>	<b>0.36</b>

<b>Gross Square Feet</b>	<b>116,900</b>
--------------------------	----------------


<b>Total Cost Per Square Foot</b>	<b>\$113.95</b>
-----------------------------------	-----------------



# FACILITY CONDITION ANALYSIS

## System Code by Project Class

MSCB : MENDENHALL STUDENT CENTER



**Detailed Project Summary  
 Facility Condition Analysis  
 Project Class by Priority Class  
 MSCB : MENDENHALL STUDENT CENTER**

Project Class	Priority Classes				Subtotal
	1	2	3	4	
Capital Renewal	0	600,358	1,280,102	2,785,135	4,665,595
Deferred Maintenance	0	21,125	7,297,105	0	7,318,229
Plant Adaption	6,881	1,121,634	0	208,964	1,337,479
<b>TOTALS</b>	6,881	1,743,116	8,577,207	2,994,099	13,321,303

Facility Replacement Cost	\$37,108,237
Facility Condition Needs Index	0.36


Gross Square Feet	116,900
-------------------	---------

Total Cost Per Square Foot	\$113.95
----------------------------	----------

# FACILITY CONDITION ANALYSIS

## Project Class by Priority Class

MSCB : MENDENHALL STUDENT CENTER



**Detailed Project Summary**  
**Facility Condition Analysis**  
**Priority Class - Priority Sequence**  
MSCB : MENDENHALL STUDENT CENTER

<b>Cat. Code</b>	<b>Project Number</b>	<b>Pri Cls</b>	<b>Pri Seq</b>	<b>Project Title</b>	<b>Construction Cost</b>	<b>Professional Fee</b>	<b>Total Cost</b>
FS5C	MSCBFS01	1	1	ELIMINATE FIRE RATING COMPROMISES AND EGRESS OBSTRUCTIONS	5,932	949	6,881
<b>Totals for Priority Class 1</b>					<b>5,932</b>	<b>949</b>	<b>6,881</b>
FS2A	MSCBFS02	2	2	FIRE ALARM SYSTEM REPLACEMENT	267,041	42,726	309,767
FS3A	MSCBFS03	2	3	FIRE SPRINKLER SYSTEM INSTALLATION	699,885	111,982	811,867
ES1B	MSCBES04	2	4	WATERPROOFING OF EXTERIOR FOUNDATION WALL	18,211	2,914	21,125
ES4B	MSCBES07	2	5	BUILT-UP ROOF REPLACEMENT	517,550	82,808	600,358
<b>Totals for Priority Class 2</b>					<b>1,502,687</b>	<b>240,430</b>	<b>1,743,116</b>
HE1A	MSCBHE01	3	6	FOOD SERVICE COLD BOX REFRIGERATION SYSTEM REPLACEMENT	27,557	4,409	31,966
ES2B	MSCBES01	3	7	RESTORE BRICK MASONRY VENEER	43,924	7,028	50,951
ES2B	MSCBES03	3	8	STUCCO SOFFIT AND WALL FINISH UPGRADES	6,691	1,071	7,761
ES2B	MSCBES02	3	9	RESTORE ARCHITECTURAL CONCRETE FINISHES	33,658	5,385	39,043
ES5A	MSCBES05	3	10	EXTERIOR DOOR REPLACEMENT	107,092	17,135	124,227
HV3A	MSCBHV01	3	11	HVAC SYSTEM REPLACEMENT	2,935,989	469,758	3,405,747
HV4B	MSCBHV03	3	12	KITCHEN VENTILATION SYSTEM REPLACEMENT	63,349	10,136	73,485
HV2A	MSCBHV02	3	13	REPLACE AIR-COOLED CHILLER	174,017	27,843	201,859
EL2A	MSCBEL02	3	14	REPLACE ELECTRICAL DISTRIBUTION EQUIPMENT	441,429	70,629	512,057
EL4B	MSCBEL03	3	15	INTERIOR LIGHTING UPGRADE	680,809	108,929	789,738
EL5A	MSCBEL01	3	16	REPLACE EMERGENCY GENERATOR	53,861	8,618	62,479
IS1A	MSCBIS01	3	17	REFINISH FLOORING	658,329	105,333	763,662
IS2B	MSCBIS02	3	18	REFINISH WALLS	299,579	47,933	347,512
IS3B	MSCBIS03	3	19	REFINISH CEILINGS	276,667	44,267	320,934
IS4A	MSCBIS04	3	20	REPLACE INTERIOR DOORS	798,695	127,791	926,486
IS6B	MSCBIS05	3	21	REPLACE STANDARD CASEWORK	59,351	9,496	68,847
IS6D	MSCBIS06	3	22	FIXED SEATING UPGRADE	192,240	30,758	222,998
IS6D	MSCBIS07	3	23	PUBLIC RESTROOM RENOVATION	437,407	69,985	507,392
IS6D	MSCBIS08	3	24	EMPLOYEE LOCKER ROOM RENOVATION	49,782	7,965	57,748
PL1E	MSCBPL01	3	25	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT	29,787	4,766	34,553

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Priority Class - Priority Sequence**  
 MSCB : MENDENHALL STUDENT CENTER

Cat. Code	Project Number	Pri Cls	Pri Seq	Project Title	Construction Cost	Professional Fee	Total Cost
SI4A	MSCBSI01	3	26	SITE PAVING UPGRADES	23,933	3,829	27,762
<b>Totals for Priority Class 3</b>					<b>7,394,144</b>	<b>1,183,063</b>	<b>8,577,207</b>
AC2A	MSCBAC01	4	27	BUILDING ENTRY ACCESSIBILITY UPGRADES	40,199	6,432	46,630
AC4B	MSCBAC02	4	28	AUDITORIUM ACCESSIBILITY UPGRADES	16,432	2,629	19,062
AC3B	MSCBAC03	4	29	STAIR SAFETY UPGRADES	123,511	19,762	143,272
ES5B	MSCBES06	4	30	WINDOW WALL REPLACEMENT AND UPGRADES	987,652	158,024	1,145,676
EL3B	MSCBEL04	4	31	UPGRADE ELECTRICAL DISTRIBUTION NETWORK	1,012,837	162,054	1,174,891
PL1A	MSCBPL02	4	32	WATER SUPPLY PIPING REPLACEMENT	400,490	64,078	464,568
<b>Totals for Priority Class 4</b>					<b>2,581,120</b>	<b>412,979</b>	<b>2,994,099</b>
<b>Grand Total:</b>					<b>11,483,882</b>	<b>1,837,421</b>	<b>13,321,303</b>

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Cost Range**  
MSCB : MENDENHALL STUDENT CENTER

<b>Cat. Code</b>	<b>Project Number</b>	<b>Pri Cls</b>	<b>Pri Seq</b>	<b>Project Title</b>	<b>Construction Cost</b>	<b>Professional Fee</b>	<b>Total Cost</b>
FS5C	MSCBFS01	1	1	ELIMINATE FIRE RATING COMPROMISES AND EGRESS OBSTRUCTIONS	5,932	949	6,881
<b>Totals for Priority Class 1</b>					<b>5,932</b>	<b>949</b>	<b>6,881</b>
ES1B	MSCBES04	2	4	WATERPROOFING OF EXTERIOR FOUNDATION WALL	18,211	2,914	21,125
<b>Totals for Priority Class 2</b>					<b>18,211</b>	<b>2,914</b>	<b>21,125</b>
ES2B	MSCBES01	3	7	RESTORE BRICK MASONRY VENEER	43,924	7,028	50,951
ES2B	MSCBES02	3	9	RESTORE ARCHITECTURAL CONCRETE FINISHES	33,658	5,385	39,043
ES2B	MSCBES03	3	8	STUCCO SOFFIT AND WALL FINISH UPGRADES	6,691	1,071	7,761
IS6B	MSCBIS05	3	21	REPLACE STANDARD CASEWORK	59,351	9,496	68,847
IS6D	MSCBIS08	3	24	EMPLOYEE LOCKER ROOM RENOVATION	49,782	7,965	57,748
SI4A	MSCBSI01	3	26	SITE PAVING UPGRADES	23,933	3,829	27,762
HE1A	MSCBHE01	3	6	FOOD SERVICE COLD BOX REFRIGERATION SYSTEM REPLACEMENT	27,557	4,409	31,966
HV4B	MSCBHV03	3	12	KITCHEN VENTILATION SYSTEM REPLACEMENT	63,349	10,136	73,485
EL5A	MSCBEL01	3	16	REPLACE EMERGENCY GENERATOR	53,861	8,618	62,479
PL1E	MSCBPL01	3	25	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT	29,787	4,766	34,553
<b>Totals for Priority Class 3</b>					<b>391,892</b>	<b>62,703</b>	<b>454,595</b>
AC2A	MSCBAC01	4	27	BUILDING ENTRY ACCESSIBILITY UPGRADES	40,199	6,432	46,630
AC4B	MSCBAC02	4	28	AUDITORIUM ACCESSIBILITY UPGRADES	16,432	2,629	19,062
<b>Totals for Priority Class 4</b>					<b>56,631</b>	<b>9,061</b>	<b>65,692</b>
<b>Grand Totals for Projects &lt; 100,000</b>					<b>472,666</b>	<b>75,627</b>	<b>548,292</b>

Detailed Project Summary  
Facility Condition Analysis  
Project Cost Range  
MSCB : MENDENHALL STUDENT CENTER

Cat. Code	Project Number	Pri Cls	Pri Seq	Project Title	Construction Cost	Professional Fee	Total Cost
FS2A	MSCBFS02	2	2	FIRE ALARM SYSTEM REPLACEMENT	267,041	42,726	309,767
<b>Totals for Priority Class 2</b>					<b>267,041</b>	<b>42,726</b>	<b>309,767</b>
ES5A	MSCBES05	3	10	EXTERIOR DOOR REPLACEMENT	107,092	17,135	124,227
IS2B	MSCBIS02	3	18	REFINISH WALLS	299,579	47,933	347,512
IS3B	MSCBIS03	3	19	REFINISH CEILINGS	276,667	44,267	320,934
IS6D	MSCBIS06	3	22	FIXED SEATING UPGRADE	192,240	30,758	222,998
HV2A	MSCBHV02	3	13	REPLACE AIR-COOLED CHILLER	174,017	27,843	201,859
<b>Totals for Priority Class 3</b>					<b>1,049,595</b>	<b>167,935</b>	<b>1,217,530</b>
AC3B	MSCBAC03	4	29	STAIR SAFETY UPGRADES	123,511	19,762	143,272
PL1A	MSCBPL02	4	32	WATER SUPPLY PIPING REPLACEMENT	400,490	64,078	464,568
<b>Totals for Priority Class 4</b>					<b>524,000</b>	<b>83,840</b>	<b>607,840</b>
<b>Grand Totals for Projects &gt;= 100,000 and &lt; 500,000</b>					<b>1,840,635</b>	<b>294,502</b>	<b>2,135,137</b>

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Cost Range**  
MSCB : MENDENHALL STUDENT CENTER

<b>Cat. Code</b>	<b>Project Number</b>	<b>Pri Cls</b>	<b>Pri Seq</b>	<b>Project Title</b>	<b>Construction Cost</b>	<b>Professional Fee</b>	<b>Total Cost</b>
ES4B	MSCBES07	2	5	BUILT-UP ROOF REPLACEMENT	517,550	82,808	600,358
FS3A	MSCBFS03	2	3	FIRE SPRINKLER SYSTEM INSTALLATION	699,885	111,982	811,867
<b>Totals for Priority Class 2</b>					<b>1,217,435</b>	<b>194,790</b>	<b>1,412,225</b>
IS1A	MSCBIS01	3	17	REFINISH FLOORING	658,329	105,333	763,662
IS4A	MSCBIS04	3	20	REPLACE INTERIOR DOORS	798,695	127,791	926,486
IS6D	MSCBIS07	3	23	PUBLIC RESTROOM RENOVATION	437,407	69,985	507,392
HV3A	MSCBHV01	3	11	HVAC SYSTEM REPLACEMENT	2,935,989	469,758	3,405,747
EL2A	MSCBEL02	3	14	REPLACE ELECTRICAL DISTRIBUTION EQUIPMENT	441,429	70,629	512,057
EL4B	MSCBEL03	3	15	INTERIOR LIGHTING UPGRADE	680,809	108,929	789,738
<b>Totals for Priority Class 3</b>					<b>5,952,657</b>	<b>952,425</b>	<b>6,905,082</b>
ES5B	MSCBES06	4	30	WINDOW WALL REPLACEMENT AND UPGRADES	987,652	158,024	1,145,676
EL3B	MSCBEL04	4	31	UPGRADE ELECTRICAL DISTRIBUTION NETWORK	1,012,837	162,054	1,174,891
<b>Totals for Priority Class 4</b>					<b>2,000,489</b>	<b>320,078</b>	<b>2,320,567</b>
<b>Grand Totals for Projects &gt;= 500,000</b>					<b>9,170,581</b>	<b>1,467,293</b>	<b>10,637,874</b>
<b>Grand Totals For All Projects:</b>					<b>11,483,882</b>	<b>1,837,421</b>	<b>13,321,303</b>



**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Classification**  
MSCB : MENDENHALL STUDENT CENTER

<b>Cat Code</b>	<b>Project Number</b>	<b>Pri. Seq.</b>	<b>Project Classification</b>	<b>Pri. Cls</b>	<b>Project Title</b>	<b>Total Cost</b>
ES4B	MSCBES07	5	Capital Renewal	2	BUILT-UP ROOF REPLACEMENT	600,358
ES5A	MSCBES05	10	Capital Renewal	3	EXTERIOR DOOR REPLACEMENT	124,227
HV2A	MSCBHV02	13	Capital Renewal	3	REPLACE AIR-COOLED CHILLER	201,859
EL5A	MSCBEL01	16	Capital Renewal	3	REPLACE EMERGENCY GENERATOR	62,479
IS6B	MSCBIS05	21	Capital Renewal	3	REPLACE STANDARD CASEWORK	68,847
IS6D	MSCBIS06	22	Capital Renewal	3	FIXED SEATING UPGRADE	222,998
IS6D	MSCBIS07	23	Capital Renewal	3	PUBLIC RESTROOM RENOVATION	507,392
IS6D	MSCBIS08	24	Capital Renewal	3	EMPLOYEE LOCKER ROOM RENOVATION	57,748
PL1E	MSCBPL01	25	Capital Renewal	3	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT	34,553
ES5B	MSCBES06	30	Capital Renewal	4	WINDOW WALL REPLACEMENT AND UPGRADES	1,145,676
EL3B	MSCBEL04	31	Capital Renewal	4	UPGRADE ELECTRICAL DISTRIBUTION NETWORK	1,174,891
PL1A	MSCBPL02	32	Capital Renewal	4	WATER SUPPLY PIPING REPLACEMENT	464,568
<b>Totals for Capital Renewal</b>						<b>4,665,595</b>
ES1B	MSCBES04	4	Deferred Maintenance	2	WATERPROOFING OF EXTERIOR FOUNDATION WALL	21,125
HE1A	MSCBHE01	6	Deferred Maintenance	3	FOOD SERVICE COLD BOX REFRIGERATION SYSTEM REPLACEMENT	31,966
ES2B	MSCBES01	7	Deferred Maintenance	3	RESTORE BRICK MASONRY VENEER	50,951
ES2B	MSCBES03	8	Deferred Maintenance	3	STUCCO SOFFIT AND WALL FINISH UPGRADES	7,761
ES2B	MSCBES02	9	Deferred Maintenance	3	RESTORE ARCHITECTURAL CONCRETE FINISHES	39,043
HV3A	MSCBHV01	11	Deferred Maintenance	3	HVAC SYSTEM REPLACEMENT	3,405,747
HV4B	MSCBHV03	12	Deferred Maintenance	3	KITCHEN VENTILATION SYSTEM REPLACEMENT	73,485
EL2A	MSCBEL02	14	Deferred Maintenance	3	REPLACE ELECTRICAL DISTRIBUTION EQUIPMENT	512,057
EL4B	MSCBEL03	15	Deferred Maintenance	3	INTERIOR LIGHTING UPGRADE	789,738
IS1A	MSCBIS01	17	Deferred Maintenance	3	REFINISH FLOORING	763,662
IS2B	MSCBIS02	18	Deferred Maintenance	3	REFINISH WALLS	347,512
IS3B	MSCBIS03	19	Deferred Maintenance	3	REFINISH CEILINGS	320,934
IS4A	MSCBIS04	20	Deferred Maintenance	3	REPLACE INTERIOR DOORS	926,486
SI4A	MSCBSI01	26	Deferred Maintenance	3	SITE PAVING UPGRADES	27,762
<b>Totals for Deferred Maintenance</b>						<b>7,318,229</b>

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Classification**  
 MSCB : MENDENHALL STUDENT CENTER

Cat Code	Project Number	Pri. Seq.	Project Classification	Pri. Cls	Project Title	Total Cost
FS5C	MSCBFS01	1	Plant Adaption	1	ELIMINATE FIRE RATING COMPROMISES AND EGRESS OBSTRUCTIONS	6,881
FS2A	MSCBFS02	2	Plant Adaption	2	FIRE ALARM SYSTEM REPLACEMENT	309,767
FS3A	MSCBFS03	3	Plant Adaption	2	FIRE SPRINKLER SYSTEM INSTALLATION	811,867
AC2A	MSCBAC01	27	Plant Adaption	4	BUILDING ENTRY ACCESSIBILITY UPGRADES	46,630
AC4B	MSCBAC02	28	Plant Adaption	4	AUDITORIUM ACCESSIBILITY UPGRADES	19,062
AC3B	MSCBAC03	29	Plant Adaption	4	STAIR SAFETY UPGRADES	143,272
<b>Totals for Plant Adaption</b>						<b>1,337,479</b>
<b>Grand Total:</b>						<b>13,321,303</b>

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Energy Conservation**  
 MSCB : MENDENHALL STUDENT CENTER

<b>Cat Code</b>	<b>Project Number</b>	<b>Pri Cls</b>	<b>Pri Seq</b>	<b>Project Title</b>	<b>Total Cost</b>	<b>Annual Savings</b>	<b>Simple Payback</b>
ES4B	MSCBES07	2	5	BUILT-UP ROOF REPLACEMENT	600,358	9,100	65.97
<b>Totals for Priority Class 2</b>					<b>600,358</b>	<b>9,100</b>	<b>65.97</b>
HV3A	MSCBHV01	3	11	HVAC SYSTEM REPLACEMENT	3,405,747	74,630	45.64
EL4B	MSCBEL03	3	15	INTERIOR LIGHTING UPGRADE	789,738	23,850	33.11
<b>Totals for Priority Class 3</b>					<b>4,195,486</b>	<b>98,480</b>	<b>42.6</b>
ES5B	MSCBES06	4	30	WINDOW WALL REPLACEMENT AND UPGRADES	1,145,676	2,200	520.76
<b>Totals for Priority Class 4</b>					<b>1,145,676</b>	<b>2,200</b>	<b>520.76</b>
<b>Grand Total:</b>					<b>5,941,520</b>	<b>109,780</b>	<b>54.12</b>

Detailed Project Summary  
Facility Condition Analysis  
Category/System Code  
MSCB : MENDENHALL STUDENT CENTER

Cat. Code	Project Number	Pri Cls	Pri Seq	Project Title	Construction Cost	Professional Fee	Total Cost
AC2A	MSCBAC01	4	27	BUILDING ENTRY ACCESSIBILITY UPGRADES	40,199	6,432	46,630
AC4B	MSCBAC02	4	28	AUDITORIUM ACCESSIBILITY UPGRADES	16,432	2,629	19,062
AC3B	MSCBAC03	4	29	STAIR SAFETY UPGRADES	123,511	19,762	143,272
<b>Totals for System Code: ACCESSIBILITY</b>					<b>180,142</b>	<b>28,823</b>	<b>208,964</b>
EL2A	MSCBEL02	3	14	REPLACE ELECTRICAL DISTRIBUTION EQUIPMENT	441,429	70,629	512,057
EL4B	MSCBEL03	3	15	INTERIOR LIGHTING UPGRADE	680,809	108,929	789,738
EL5A	MSCBEL01	3	16	REPLACE EMERGENCY GENERATOR	53,861	8,618	62,479
EL3B	MSCBEL04	4	31	UPGRADE ELECTRICAL DISTRIBUTION NETWORK	1,012,837	162,054	1,174,891
<b>Totals for System Code: ELECTRICAL</b>					<b>2,188,935</b>	<b>350,230</b>	<b>2,539,165</b>
ES1B	MSCBES04	2	4	WATERPROOFING OF EXTERIOR FOUNDATION WALL	18,211	2,914	21,125
ES4B	MSCBES07	2	5	BUILT-UP ROOF REPLACEMENT	517,550	82,808	600,358
ES2B	MSCBES01	3	7	RESTORE BRICK MASONRY VENEER	43,924	7,028	50,951
ES2B	MSCBES03	3	8	STUCCO SOFFIT AND WALL FINISH UPGRADES	6,691	1,071	7,761
ES2B	MSCBES02	3	9	RESTORE ARCHITECTURAL CONCRETE FINISHES	33,658	5,385	39,043
ES5A	MSCBES05	3	10	EXTERIOR DOOR REPLACEMENT	107,092	17,135	124,227
ES5B	MSCBES06	4	30	WINDOW WALL REPLACEMENT AND UPGRADES	987,652	158,024	1,145,676
<b>Totals for System Code: EXTERIOR</b>					<b>1,714,777</b>	<b>274,364</b>	<b>1,989,141</b>
FS5C	MSCBFS01	1	1	ELIMINATE FIRE RATING COMPROMISES AND EGRESS OBSTRUCTIONS	5,932	949	6,881
FS2A	MSCBFS02	2	2	FIRE ALARM SYSTEM REPLACEMENT	267,041	42,726	309,767
FS3A	MSCBFS03	2	3	FIRE SPRINKLER SYSTEM INSTALLATION	699,885	111,982	811,867
<b>Totals for System Code: FIRE/LIFE SAFETY</b>					<b>972,857</b>	<b>155,657</b>	<b>1,128,515</b>
HE1A	MSCBHE01	3	6	FOOD SERVICE COLD BOX REFRIGERATION SYSTEM REPLACEMENT	27,557	4,409	31,966
<b>Totals for System Code: HEALTH</b>					<b>27,557</b>	<b>4,409</b>	<b>31,966</b>
HV3A	MSCBHV01	3	11	HVAC SYSTEM REPLACEMENT	2,935,989	469,758	3,405,747
HV4B	MSCBHV03	3	12	KITCHEN VENTILATION SYSTEM REPLACEMENT	63,349	10,136	73,485
HV2A	MSCBHV02	3	13	REPLACE AIR-COOLED CHILLER	174,017	27,843	201,859
<b>Totals for System Code: HVAC</b>					<b>3,173,355</b>	<b>507,737</b>	<b>3,681,091</b>
IS1A	MSCBIS01	3	17	REFINISH FLOORING	658,329	105,333	763,662
IS2B	MSCBIS02	3	18	REFINISH WALLS	299,579	47,933	347,512
IS3B	MSCBIS03	3	19	REFINISH CEILINGS	276,667	44,267	320,934
IS4A	MSCBIS04	3	20	REPLACE INTERIOR DOORS	798,695	127,791	926,486

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Category/System Code**  
 MSCB : MENDENHALL STUDENT CENTER

Cat. Code	Project Number	Pri Cls	Pri Seq	Project Title	Construction Cost	Professional Fee	Total Cost
IS6B	MSCBIS05	3	21	REPLACE STANDARD CASEWORK	59,351	9,496	68,847
IS6D	MSCBIS06	3	22	FIXED SEATING UPGRADE	192,240	30,758	222,998
IS6D	MSCBIS07	3	23	PUBLIC RESTROOM RENOVATION	437,407	69,985	507,392
IS6D	MSCBIS08	3	24	EMPLOYEE LOCKER ROOM RENOVATION	49,782	7,965	57,748
<b>Totals for System Code: INTERIOR/FINISH SYS.</b>					<b>2,772,050</b>	<b>443,528</b>	<b>3,215,578</b>
PL1E	MSCBPL01	3	25	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT	29,787	4,766	34,553
PL1A	MSCBPL02	4	32	WATER SUPPLY PIPING REPLACEMENT	400,490	64,078	464,568
<b>Totals for System Code: PLUMBING</b>					<b>430,277</b>	<b>68,844</b>	<b>499,121</b>
SI4A	MSCBSI01	3	26	SITE PAVING UPGRADES	23,933	3,829	27,762
<b>Totals for System Code: SITE</b>					<b>23,933</b>	<b>3,829</b>	<b>27,762</b>
<b>Grand Total:</b>					<b>11,483,882</b>	<b>1,837,421</b>	<b>13,321,303</b>



FACILITY CONDITION ANALYSIS

**SECTION 3**

SPECIFIC PROJECT DETAILS  
ILLUSTRATING DESCRIPTION / COST

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBFS01	<b>Title:</b>	ELIMINATE FIRE RATING COMPROMISES AND EGRESS OBSTRUCTIONS
<b>Priority Sequence:</b>	1		
<b>Priority Class:</b>	1		
<b>Category Code:</b>	FS5C	<b>System:</b>	FIRE/LIFE SAFETY
		<b>Component:</b>	EGRESS PATH
		<b>Element:</b>	SEPARATION RATING
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	IBC	711.3	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

Structural fire separations are not maintained according to code requirements for new construction in some areas of this facility. Little or no regard has been given to the passive and active firestopping systems in the building. Moderate structural separation repairs and intumescent passive firestopping should be accomplished promptly. A few of the egress corridor are obstructed by inappropriately stored materials. All obstructive items should be removed and an ongoing monitoring program implemented.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBFS01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Moderate passive firestopping and structural separation repairs	SF	18,000	\$0.06	\$1,080	\$0.17	\$3,060	\$4,140
Remove egress route corridor obstructions	LOT	1	\$1,000	\$1,000	\$2,200	\$2,200	\$3,200
<b>Project Totals:</b>				<b>\$2,080</b>		<b>\$5,260</b>	<b>\$7,340</b>

<b>Material/Labor Cost</b>		\$7,340
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		\$4,793
<b>General Contractor Mark Up at 20.0%</b>	+	\$959
<b>Inflation</b>	+	\$180
<b>Construction Cost</b>		\$5,932
<b>Professional Fees at 16.0%</b>	+	\$949
<b>Total Project Cost</b>		<b>\$6,881</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBFS02	<b>Title:</b>	FIRE ALARM SYSTEM REPLACEMENT
<b>Priority Sequence:</b>	2		
<b>Priority Class:</b>	2		
<b>Category Code:</b>	FS2A	<b>System:</b>	FIRE/LIFE SAFETY
		<b>Component:</b>	DETECTION ALARM
		<b>Element:</b>	GENERAL
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	702.1	
	NFPA	1, 101	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

Update the existing fire alarm system using new, late model components. Specify a point addressable supervised main fire alarm panel with an annunciator and additional remote annunciator panels as appropriate. Include pull stations, audible and visible strobe alarms, smoke and heat detectors, and a wiring network. Install all devices in accordance with current NFPA and ADA requirements. The system should be monitored to report activation or trouble to an applicable receiving station.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBFS02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Fire alarm control panel(s), annunciator, smoke and heat detectors, manual pull stations, audible and visual alarms, wiring, raceways, and cut and patching materials	SF	116,900	\$1.40	\$163,660	\$0.85	\$99,365	\$263,025
<b>Project Totals:</b>				<b>\$163,660</b>		<b>\$99,365</b>	<b>\$263,025</b>

<b>Material/Labor Cost</b>		\$263,025
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		\$215,780
<b>General Contractor Mark Up at 20.0%</b>	+	\$43,156
<b>Inflation</b>	+	\$8,105
<b>Construction Cost</b>		\$267,041
<b>Professional Fees at 16.0%</b>	+	\$42,726
<b>Total Project Cost</b>		<b>\$309,767</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBFS03	<b>Title:</b>	FIRE SPRINKLER SYSTEM INSTALLATION
<b>Priority Sequence:</b>	3		
<b>Priority Class:</b>	2		
<b>Category Code:</b>	FS3A	<b>System:</b>	FIRE/LIFE SAFETY
		<b>Component:</b>	SUPPRESSION
		<b>Element:</b>	SPRINKLERS
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	NFPA	1, 13, 13R, 101	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

Install a building-wide automatic fire sprinkler system. Include piping, valves, sprinkler heads, and piping supports. Install flow switches and sensors to interface with the fire alarm system.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBFS03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Install wet-pipe sprinkler system, including valves, piping, sprinkler heads, piping supports, etc.	SF	116,900	\$2.96	\$346,024	\$3.62	\$423,178	\$769,202
<b>Project Totals:</b>				<b>\$346,024</b>		<b>\$423,178</b>	<b>\$769,202</b>

<b>Material/Labor Cost</b>		<b>\$769,202</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$565,536</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$113,107</b>
<b>Inflation</b>	+	<b>\$21,242</b>
<b>Construction Cost</b>		<b>\$699,885</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$111,982</b>
<b>Total Project Cost</b>		<b>\$811,867</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBES04	<b>Title:</b>	WATERPROOFING OF EXTERIOR FOUNDATION WALL
<b>Priority Sequence:</b>	4		
<b>Priority Class:</b>	2		
<b>Category Code:</b>	ES1B	<b>System:</b>	EXTERIOR
		<b>Component:</b>	FOUNDATION/FOOTING
		<b>Element:</b>	DAMPPROOFING/DEWATERING
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Area Wide: Floor(s) 1		

**Project Description**

There is evidence of water infiltration through portions of the ground floor foundation wall in mechanical room G026. Excavation and waterproofing system upgrades are recommended. Improve the slope of grade away from the foundation prior to restoring the landscaping.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBES04

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Excavation and backfill to a depth of 10 feet	LF	48	\$121	\$5,808	\$257	\$12,336	\$18,144
Landscape restoration 20 feet from building	LF	48	\$11.49	\$552	\$8.62	\$414	\$965
Dampproofing application to a height of 10 feet	LF	48	\$21.35	\$1,025	\$29.99	\$1,440	\$2,464
<b>Project Totals:</b>				<b>\$7,384</b>		<b>\$14,189</b>	<b>\$21,574</b>

<b>Material/Labor Cost</b>		<b>\$21,574</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$14,715</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$2,943</b>
<b>Inflation</b>	+	<b>\$553</b>
<b>Construction Cost</b>		<b>\$18,211</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$2,914</b>
<b>Total Project Cost</b>		<b>\$21,125</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBES07	<b>Title:</b>	BUILT-UP ROOF REPLACEMENT
<b>Priority Sequence:</b>	5		
<b>Priority Class:</b>	2		
<b>Category Code:</b>	ES4B	<b>System:</b>	EXTERIOR
		<b>Component:</b>	ROOF
		<b>Element:</b>	REPLACEMENT
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Energy Conservation	\$9,100	
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) R		

**Project Description**

While the west roof section over Hendrix Theatre is only ten years old, the east section built-up roofing system has failed and places the building interior at risk. Future budget modeling should include a provision for the replacement of all failing roofing systems. Replace this roof with a similar application. The associated roof drainage inlets are showing signs of ineffective channeling of rainwater from the flat membrane roof to interior piping systems. Repairs or replacement of these drainage systems is recommended to prevent water damage to the building interior.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBES07

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Built-up roof	SF	83,736	\$3.06	\$256,232	\$3.58	\$299,775	\$556,007
Roof drainage system inlet upgrades	LOT	1	\$3,800	\$3,800	\$5,000	\$5,000	\$8,800
<b>Project Totals:</b>				<b>\$260,032</b>		<b>\$304,775</b>	<b>\$564,807</b>

<b>Material/Labor Cost</b>		<b>\$564,807</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$418,202</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$83,640</b>
<b>Inflation</b>	+	<b>\$15,708</b>
<b>Construction Cost</b>		<b>\$517,550</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$82,808</b>
<b>Total Project Cost</b>		<b>\$600,358</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBHE01	<b>Title:</b>	FOOD SERVICE COLD BOX REFRIGERATION SYSTEM REPLACEMENT
<b>Priority Sequence:</b>	6		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	HE1A	<b>System:</b>	HEALTH
		<b>Component:</b>	ENVIRONMENTAL CONTROL
		<b>Element:</b>	EQUIPMENT AND ENCLOSURES
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ASHRAE	15-2004	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Item Only: Floor(s) 1		

**Project Description**

Replacement of the food service walk-in cooler / freezer refrigeration systems is recommended. Remove the existing systems. Install new non-CFC / HCFC refrigerant based systems of the latest energy-efficient design.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBHE01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Refrigeration system, including compressor, evaporator unit, controls, refrigerant, and demolition of existing equipment	SYS	5	\$3,210	\$16,050	\$2,380	\$11,900	\$27,950
<b>Project Totals:</b>				<b>\$16,050</b>		<b>\$11,900</b>	<b>\$27,950</b>

<b>Material/Labor Cost</b>		\$27,950
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$22,267</u>
<b>General Contractor Mark Up at 20.0%</b>	+	\$4,453
<b>Inflation</b>	+	<u>\$836</u>
<b>Construction Cost</b>		\$27,557
<b>Professional Fees at 16.0%</b>	+	<u>\$4,409</u>
<b>Total Project Cost</b>		<u><b>\$31,966</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBES01	<b>Title:</b>	RESTORE BRICK MASONRY VENEER
<b>Priority Sequence:</b>	7		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	ES2B	<b>System:</b>	EXTERIOR
		<b>Component:</b>	COLUMNS/BEAMS/WALLS
		<b>Element:</b>	FINISH
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Building-wide: Floor(s) 1		

**Project Description**

Brick masonry veneer is one of the primary exterior facade finishes. While the brick is fundamentally sound, exposure to the elements has caused some deterioration of the mortar joints and expansion joints. Cleaning, surface preparation, selective repairs, and applied finish or penetrating sealant upgrades are recommended to restore the aesthetics and integrity of the building envelope. Selective area work includes masonry wall repairs at the vertical crack located at the auditorium loading dock.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBES01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Cleaning and surface preparation	SF	24,050	\$0.11	\$2,646	\$0.22	\$5,291	\$7,937
Selective mortar and / or sealant repairs (assumes 10 linear feet for every 100 square feet of envelope)	LF	2,405	\$2.45	\$5,892	\$4.99	\$12,001	\$17,893
Applied finish or sealant	SF	24,050	\$0.22	\$5,291	\$0.82	\$19,721	\$25,012
Masonry wall repairs at vertical crack at auditorium loading dock	LF	20	\$64.88	\$1,298	\$124	\$2,480	\$3,778
<b>Project Totals:</b>				<b>\$15,126</b>		<b>\$39,493</b>	<b>\$54,619</b>

<b>Material/Labor Cost</b>		<b>\$54,619</b>
<b>Material Index</b>		<b>100.7%</b>
<b>Labor Index</b>		<b>51.3%</b>
<b>Material/Labor Indexed Cost</b>		<b>\$35,492</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$7,098</b>
<b>Inflation</b>	+	<b>\$1,333</b>
<b>Construction Cost</b>		<b>\$43,924</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$7,028</b>
<b>Total Project Cost</b>		<b>\$50,951</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBES03	<b>Title:</b>	STUCCO SOFFIT AND WALL FINISH UPGRADES
<b>Priority Sequence:</b>	8		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	ES2B	<b>System:</b>	EXTERIOR
		<b>Component:</b>	COLUMNS/BEAMS/WALLS
		<b>Element:</b>	FINISH
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	IBC	IRC- Part III, Ch. R7, 703.9	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Building-wide: Floor(s) 1		

**Project Description**

Portions of the exterior soffits have a painted stucco finish system. The substrate is sound, but exposure to the elements has deteriorated the trowelled stucco finish. There are numerous cracks and substantial color variation. Selective substrate repairs, surface preparation, trowelled finish application, and painting are recommended to restore the aesthetics and integrity of the building envelope.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBES03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Natural masonry base, aggregate, surface stucco finish	SF	800	\$1.56	\$1,248	\$3.36	\$2,688	\$3,936
Surface preparation	SF	3,200	\$0.11	\$352	\$0.22	\$704	\$1,056
Paint	SF	3,200	\$0.22	\$704	\$0.82	\$2,624	\$3,328
<b>Project Totals:</b>				<b>\$2,304</b>		<b>\$6,016</b>	<b>\$8,320</b>

<b>Material/Labor Cost</b>		<b>\$8,320</b>
<b>Material Index</b>		<b>100.7%</b>
<b>Labor Index</b>		<b>51.3%</b>
<b>Material/Labor Indexed Cost</b>		<b>\$5,406</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$1,081</b>
<b>Inflation</b>	+	<b>\$203</b>
<b>Construction Cost</b>		<b>\$6,691</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$1,071</b>
<b>Total Project Cost</b>		<b>\$7,761</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBES02	<b>Title:</b>	RESTORE ARCHITECTURAL CONCRETE FINISHES
<b>Priority Sequence:</b>	9		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	ES2B	<b>System:</b>	EXTERIOR
		<b>Component:</b>	COLUMNS/BEAMS/WALLS
		<b>Element:</b>	FINISH
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Building-wide: Floor(s) 1		

**Project Description**

The secondary facade finish includes exposed natural concrete and architectural concrete panels. This exterior concrete has become visibly soiled, and the construction joints are failing. Cleaning, surface preparation, selective repairs, and applied finish upgrades are recommended to restore the aesthetics and integrity of the building envelope. Elastomeric coatings should be applied to all horizontal concrete and panel surfaces to improve water shed and reduce infiltration into the wall assembly.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBES02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Cleaning and surface preparation	SF	17,490	\$0.11	\$1,924	\$0.22	\$3,848	\$5,772
Selective mortar and / or sealant repairs (assumes 10 linear feet for every 100 square feet of envelope)	LF	1,749	\$2.45	\$4,285	\$4.99	\$8,728	\$13,013
Applied finish or sealant	SF	17,490	\$0.22	\$3,848	\$0.82	\$14,342	\$18,190
Elastomeric coating applications	SF	3,200	\$0.36	\$1,152	\$1.28	\$4,096	\$5,248
<b>Project Totals:</b>				<b>\$11,209</b>		<b>\$31,013</b>	<b>\$42,222</b>

<b>Material/Labor Cost</b>		<b>\$42,222</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$27,197</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$5,439</b>
<b>Inflation</b>	+	<b>\$1,022</b>
<b>Construction Cost</b>		<b>\$33,658</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$5,385</b>
<b>Total Project Cost</b>		<b>\$39,043</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBES05	<b>Title:</b>	EXTERIOR DOOR REPLACEMENT
<b>Priority Sequence:</b>	10		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	ES5A	<b>System:</b>	EXTERIOR
		<b>Component:</b>	FENESTRATIONS
		<b>Element:</b>	DOORS
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Building-wide: Floor(s) 1		

**Project Description**

Replacements are recommended for the aging exterior door systems. This project includes the primary and secondary entrance and service doors. The replacement units should maintain the architectural design aspects of this facility and be modern, energy-efficient applications.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBES05

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
High traffic door system	LEAF	22	\$1,978	\$43,516	\$1,999	\$43,978	\$87,494
Low traffic door system	LEAF	12	\$1,031	\$12,372	\$1,250	\$15,000	\$27,372
<b>Project Totals:</b>				<b>\$55,888</b>		<b>\$58,978</b>	<b>\$114,866</b>

<b>Material/Labor Cost</b>		<b>\$114,866</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$86,535</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$17,307</b>
<b>Inflation</b>	+	<b>\$3,250</b>
<b>Construction Cost</b>		<b>\$107,092</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$17,135</b>
<b>Total Project Cost</b>		<b>\$124,227</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBHV01	<b>Title:</b>	HVAC SYSTEM REPLACEMENT
<b>Priority Sequence:</b>	11		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	HV3A	<b>System:</b>	HVAC
		<b>Component:</b>	HEATING/COOLING
		<b>Element:</b>	SYSTEM RETROFIT/REPLACE
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Energy Conservation	\$74,630	
<b>Code Application:</b>	ASHRAE	62-2004	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G, R		

**Project Description**

A complete redesign and replacement of the HVAC system is recommended. Demolish and dispose of existing equipment. Install a new modern HVAC system with variable air volume (VAV) and constant volume air distribution as needed. This includes new air handlers, exhaust fans, ductwork, terminal units, heat exchangers, pumps, piping, controls, and related electrical components. Specify direct digital controls (DDCs) for the new equipment. Incorporate variable frequency drives (VFDs) into the new HVAC design as applicable.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBHV01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Air handlers, exhaust fans, ductwork, VAVs, VFDs, DDCs, heat exchangers, pumps, piping, electrical connections, and demolition of existing equipment	SF	116,900	\$12.42	\$1,451,898	\$15.18	\$1,774,542	\$3,226,440
<b>Project Totals:</b>				<b>\$1,451,898</b>		<b>\$1,774,542</b>	<b>\$3,226,440</b>

<b>Material/Labor Cost</b>		<b>\$3,226,440</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$2,372,401</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$474,480</b>
<b>Inflation</b>	+	<b>\$89,107</b>
<b>Construction Cost</b>		<b>\$2,935,989</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$469,758</b>
<b>Total Project Cost</b>		<b>\$3,405,747</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBHV03	<b>Title:</b>	KITCHEN VENTILATION SYSTEM REPLACEMENT
<b>Priority Sequence:</b>	12		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	HV4B	<b>System:</b>	HVAC
		<b>Component:</b>	AIR MOVING/VENTILATION
		<b>Element:</b>	EXHAUST FANS
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ASHRAE	62-2004	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Room Only: Floor(s) 1		

**Project Description**

Replacement of the aging kitchen exhaust systems is recommended. Remove the existing equipment, and install new kitchen exhaust and makeup air systems. This work includes the exhaust fans, makeup air units, controls, ductwork, connections, and demolition of the existing equipment.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBHV03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Commercial kitchen exhaust / makeup air system and demolition of existing equipment	SYS	2	\$19,170	\$38,341	\$12,261	\$24,521	\$62,862
<b>Project Totals:</b>				<b>\$38,341</b>		<b>\$24,521</b>	<b>\$62,862</b>

<b>Material/Labor Cost</b>		<b>\$62,862</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$51,189</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$10,238</b>
<b>Inflation</b>	+	<b>\$1,923</b>
<b>Construction Cost</b>		<b>\$63,349</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$10,136</b>
<b>Total Project Cost</b>		<b>\$73,485</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBHV02	<b>Title:</b>	REPLACE AIR-COOLED CHILLER
<b>Priority Sequence:</b>	13		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	HV2A	<b>System:</b>	HVAC
		<b>Component:</b>	COOLING
		<b>Element:</b>	CHILLERS/CONTROLS
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ASHRAE	15-2004	
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Item Only: Floor(s) 1		

**Project Description**

The existing Carrier air-cooled chiller is recommended for replacement. Remove the existing chiller. Install a new chiller, along with electrical connections and related controls and programming. Specify an energy-efficient replacement system that utilizes a non-CFC refrigerant.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBHV02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Air-cooled chiller replacement and removal of existing unit	TON	170	\$731	\$124,272	\$177	\$30,158	\$154,430
<b>Project Totals:</b>				<b>\$124,272</b>		<b>\$30,158</b>	<b>\$154,430</b>

<b>Material/Labor Cost</b>		<b>\$154,430</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$140,613</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$28,123</b>
<b>Inflation</b>	+	<b>\$5,281</b>
<b>Construction Cost</b>		<b>\$174,017</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$27,843</b>
<b>Total Project Cost</b>		<b>\$201,859</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBEL02	<b>Title:</b>	REPLACE ELECTRICAL DISTRIBUTION EQUIPMENT
<b>Priority Sequence:</b>	14		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	EL2A	<b>System:</b>	ELECTRICAL
		<b>Component:</b>	MAIN DISTRIBUTION PANELS
		<b>Element:</b>	CONDITION UPGRADE
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	NEC	Article 230	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Room Only: Floor(s) 1, 2, G		

**Project Description**

The main electrical distribution equipment components are recommended for replacement. This includes 277/480 volt switchgear and main distribution panels, step-down transformers, and 120/208 volt main distribution panels. With increasing age, the risk increases that circuit breaker and transformer failures could become fire hazards or cause other damage.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBEL02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
277/480 V switchgear, rated 2500, 1600, and 1200 amps, in rooms G030, G117, and G030, respectively, includes switchboards, circuit breakers, feeders, digital metering, transient surge protectors	LOT	1	\$168,856	\$168,856	\$106,400	\$106,400	\$275,256
120/208 V switchgear, rated 1600, 800, and 800 amps in rooms G117, 126, and 113, respectively, including switchboards, circuit breakers, feeders, digital metering, transient surge protectors	LOT	1	\$47,680	\$47,680	\$39,968	\$39,968	\$87,648
277/480 V to 120/208 V dry type transformers: 2 at 30 kVA, rooms G030 and G119; 3 at 75 kVA, rooms G026, G119, and 225; 1 at 112.5 kVA, room 113; 1 at 225 kVA, room G030; 1 at 500 kVA, room G117	LOT	1	\$43,270	\$43,270	\$38,950	\$38,950	\$82,220
<b>Project Totals:</b>				<b>\$259,806</b>		<b>\$185,318</b>	<b>\$445,124</b>

<b>Material/Labor Cost</b>		<b>\$445,124</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$356,693</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$71,339</b>
<b>Inflation</b>	+	<b>\$13,397</b>
<b>Construction Cost</b>		<b>\$441,429</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$70,629</b>
<b>Total Project Cost</b>		<b>\$512,057</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBEL03	<b>Title:</b>	INTERIOR LIGHTING UPGRADE
<b>Priority Sequence:</b>	15		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	EL4B	<b>System:</b>	ELECTRICAL
		<b>Component:</b>	DEVICES AND FIXTURES
		<b>Element:</b>	INTERIOR LIGHTING
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Energy Conservation	\$23,850	
<b>Code Application:</b>	NEC	Articles 210, 410	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

An interior lighting upgrade is recommended. Replace existing aged and / or inefficient light fixtures with modern fixtures of the latest energy-efficient design. Select lamps with the same color temperature and rendering index for lighting uniformity. Install occupancy sensors in select areas for additional energy conservation.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBEL03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
High efficiency fluorescent fixtures, occupancy sensors, and demolition of existing lighting	SF	116,900	\$2.88	\$336,672	\$3.52	\$411,488	\$748,160
<b>Project Totals:</b>				<b>\$336,672</b>		<b>\$411,488</b>	<b>\$748,160</b>

<b>Material/Labor Cost</b>		<b>\$748,160</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$550,122</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$110,024</b>
<b>Inflation</b>	+	<b>\$20,663</b>
<b>Construction Cost</b>		<b>\$680,809</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$108,929</b>
<b>Total Project Cost</b>		<b>\$789,738</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBEL01	<b>Title:</b>	REPLACE EMERGENCY GENERATOR
<b>Priority Sequence:</b>	16		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	EL5A	<b>System:</b>	ELECTRICAL
		<b>Component:</b>	EMERGENCY POWER SYSTEM
		<b>Element:</b>	GENERATION/DISTRIBUTION
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	NEC	Article 700	
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Item Only: Floor(s) G		

**Project Description**

Replace the existing emergency generator set with an appropriately sized unit based on current facility requirements. Replacement costs include the demolition of existing equipment and installation a new generator, automatic transfer switches (ATS), diesel fuel tank, battery and charger, exhaust system, and necessary electrical connections. Specify a diesel-fired unit unless otherwise directed by local standards.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBEL01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Diesel generator set, including fuel tank, battery, charger, exhaust, and automatic transfer switches	KW	125	\$305	\$38,125	\$80.00	\$10,000	\$48,125
<b>Project Totals:</b>				<b>\$38,125</b>		<b>\$10,000</b>	<b>\$48,125</b>

<b>Material/Labor Cost</b>		\$48,125
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		\$43,522
<b>General Contractor Mark Up at 20.0%</b>	+	\$8,704
<b>Inflation</b>	+	\$1,635
<b>Construction Cost</b>		\$53,861
<b>Professional Fees at 16.0%</b>	+	\$8,618
<b>Total Project Cost</b>		<b>\$62,479</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBIS01	<b>Title:</b>	REFINISH FLOORING
<b>Priority Sequence:</b>	17		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS1A	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	FLOOR
		<b>Element:</b>	FINISHES-DRY

<b>Building Code:</b>	MSCB
<b>Building Name:</b>	MENDENHALL STUDENT CENTER
<b>Subclass/Savings:</b>	Not Applicable

**Code Application:** Not Applicable

<b>Project Class:</b>	Deferred Maintenance
<b>Project Date:</b>	10/9/2009

<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G
--------------------------	------------------------------

**Project Description**

Interior floor finish applications vary in age, type, and condition. Floor finish upgrades should be considered as part of any future cosmetic improvements or major comprehensive renovation efforts.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBIS01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Carpet	SF	38,200	\$5.36	\$204,752	\$2.00	\$76,400	\$281,152
Vinyl floor tile	SF	3,550	\$3.53	\$12,532	\$2.50	\$8,875	\$21,407
Ceramic tile	SF	15,100	\$7.24	\$109,324	\$10.63	\$160,513	\$269,837
Sand and finish hardwood flooring	SF	11,376	\$0.36	\$4,095	\$3.92	\$44,594	\$48,689
Hardwood replacement	SF	2,844	\$9.11	\$25,909	\$16.37	\$46,556	\$72,465
<b>Project Totals:</b>				<b>\$356,612</b>		<b>\$336,938</b>	<b>\$693,550</b>

<b>Material/Labor Cost</b>		<b>\$693,550</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$531,957</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$106,391</b>
<b>Inflation</b>	+	<b>\$19,980</b>
<b>Construction Cost</b>		<b>\$658,329</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$105,333</b>
<b>Total Project Cost</b>		<b>\$763,662</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBIS02	<b>Title:</b>	REFINISH WALLS
<b>Priority Sequence:</b>	18		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS2B	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	PARTITIONS
		<b>Element:</b>	FINISHES

<b>Building Code:</b>	MSCB
<b>Building Name:</b>	MENDENHALL STUDENT CENTER
<b>Subclass/Savings:</b>	Not Applicable

**Code Application:** Not Applicable

<b>Project Class:</b>	Deferred Maintenance
<b>Project Date:</b>	10/9/2009

<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G
--------------------------	------------------------------

**Project Description**

Interior wall finish applications vary in age, type, and condition. Wall finish upgrades should be considered as part of any future cosmetic improvements or major comprehensive renovation efforts.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBIS02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Standard wall finish (paint, wall covering, etc.)	SF	179,740	\$0.17	\$30,556	\$0.81	\$145,589	\$176,145
Premium wall finish (epoxy, tile, wood panel, etc.)	SF	31,720	\$2.28	\$72,322	\$3.92	\$124,342	\$196,664
<b>Project Totals:</b>				<b>\$102,877</b>		<b>\$269,932</b>	<b>\$372,809</b>

<b>Material/Labor Cost</b>		<b>\$372,809</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$242,073</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$48,415</b>
<b>Inflation</b>	+	<b>\$9,092</b>
<b>Construction Cost</b>		<b>\$299,579</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$47,933</b>
<b>Total Project Cost</b>		<b>\$347,512</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBIS03	<b>Title:</b>	REFINISH CEILINGS
<b>Priority Sequence:</b>	19		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS3B	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	CEILINGS
		<b>Element:</b>	REPLACEMENT

<b>Building Code:</b>	MSCB
<b>Building Name:</b>	MENDENHALL STUDENT CENTER
<b>Subclass/Savings:</b>	Not Applicable

**Code Application:** Not Applicable

<b>Project Class:</b>	Deferred Maintenance
<b>Project Date:</b>	10/9/2009

<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G
--------------------------	------------------------------

**Project Description**

Ceiling finish applications vary in age, type, and condition. Ceiling finish upgrades should be considered as part of any future cosmetic improvements or major comprehensive renovation efforts.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBIS03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Acoustical tile ceiling system	SF	57,750	\$2.12	\$122,430	\$2.98	\$172,095	\$294,525
Painted ceiling finish application	SF	20,430	\$0.17	\$3,473	\$0.81	\$16,548	\$20,021
<b>Project Totals:</b>				<b>\$125,903</b>		<b>\$188,643</b>	<b>\$314,546</b>

<b>Material/Labor Cost</b>		<b>\$314,546</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$223,558</u>
<b>General Contractor Mark Up at 20.0%</b>	+	<u>\$44,712</u>
<b>Inflation</b>	+	<u>\$8,397</u>
<b>Construction Cost</b>		<u>\$276,667</u>
<b>Professional Fees at 16.0%</b>	+	<u>\$44,267</u>
<b>Total Project Cost</b>		<u><b>\$320,934</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBIS04	<b>Title:</b>	REPLACE INTERIOR DOORS
<b>Priority Sequence:</b>	20		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS4A	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	DOORS
		<b>Element:</b>	GENERAL
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

The condition of the interior door systems is such that door system replacements are recommended as part of a comprehensive renovation effort. Complete demolition of existing door systems and replacement according to a code compliant plan to protect egress passages properly is recommended.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBIS04

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Interior door and frame installation with all hardware and accessible signage	EA	200	\$370	\$74,000	\$396	\$79,200	\$153,200
Rated door and rated metal frame, including all hardware and accessible signage	EA	485	\$672	\$325,920	\$812	\$393,820	\$719,740
<b>Project Totals:</b>				<b>\$399,920</b>		<b>\$473,020</b>	<b>\$872,940</b>

<b>Material/Labor Cost</b>		<b>\$872,940</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$645,379</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$129,076</b>
<b>Inflation</b>	+	<b>\$24,240</b>
<b>Construction Cost</b>		<b>\$798,695</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$127,791</b>
<b>Total Project Cost</b>		<b>\$926,486</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBIS05	<b>Title:</b>	REPLACE STANDARD CASEWORK
<b>Priority Sequence:</b>	21		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS6B	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	GENERAL
		<b>Element:</b>	CABINETRY
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

Portions of the kitchen pantry areas, equipment, and storage cabinetry are in overall poor condition. New fully ADA compliant cabinetry should be installed as part of any future renovation efforts.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBIS05

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Base or wall cabinetry	LF	240	\$156	\$37,440	\$83.30	\$19,992	\$57,432
<b>Project Totals:</b>				<b>\$37,440</b>		<b>\$19,992</b>	<b>\$57,432</b>

<b>Material/Labor Cost</b>		<b>\$57,432</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$47,958</u>
<b>General Contractor Mark Up at 20.0%</b>	+	<u>\$9,592</u>
<b>Inflation</b>	+	<u>\$1,801</u>
<b>Construction Cost</b>		<u>\$59,351</u>
<b>Professional Fees at 16.0%</b>	+	<u>\$9,496</u>
<b>Total Project Cost</b>		<u><b>\$68,847</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBIS06	<b>Title:</b>	FIXED SEATING UPGRADE
<b>Priority Sequence:</b>	22		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS6D	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	GENERAL
		<b>Element:</b>	OTHER
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Undefined: Floor(s) 1		

**Project Description**

The fixed seating in the assembly area is worn and should be upgraded. Replace the existing seating with new folding fixed seats in a similar row configuration. Ensure that ADA requirements are followed with the new seating layout.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBIS06

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Basic, upholstered, folding, and fixed seating	EA	760	\$160	\$121,600	\$84.35	\$64,106	\$185,706
<b>Project Totals:</b>				<b>\$121,600</b>		<b>\$64,106</b>	<b>\$185,706</b>

<b>Material/Labor Cost</b>		<b>\$185,706</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$155,338</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$31,068</b>
<b>Inflation</b>	+	<b>\$5,834</b>
<b>Construction Cost</b>		<b>\$192,240</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$30,758</b>
<b>Total Project Cost</b>		<b>\$222,998</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBIS07	<b>Title:</b>	PUBLIC RESTROOM RENOVATION
<b>Priority Sequence:</b>	23		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS6D	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	GENERAL
		<b>Element:</b>	OTHER
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

The majority of the public area restroom fixtures and finishes are mostly original to the year of construction or latest renovation and do not meet modern accessibility standards. The fixtures are sound but aged and inefficient. The finishes are outdated. A comprehensive restroom renovation, including new fixtures, finishes, partitions, accessories, and dual level drinking fountains, is recommended.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBIS07

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Major restroom renovation, including fixtures, finishes, partitions, accessories, and expansion if necessary (assumes 55 square feet of restroom area per fixture)	FIXT	112	\$1,969	\$220,528	\$1,699	\$190,288	\$410,816
Dual level drinking fountain	EA	8	\$1,216	\$9,728	\$374	\$2,992	\$12,720
Alcove construction	EA	8	\$877	\$7,016	\$3,742	\$29,936	\$36,952
<b>Project Totals:</b>				<b>\$237,272</b>		<b>\$223,216</b>	<b>\$460,488</b>

<b>Material/Labor Cost</b>		<b>\$460,488</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$353,443</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$70,689</b>
<b>Inflation</b>	+	<b>\$13,275</b>
<b>Construction Cost</b>		<b>\$437,407</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$69,985</b>
<b>Total Project Cost</b>		<b>\$507,392</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBIS08	<b>Title:</b>	EMPLOYEE LOCKER ROOM RENOVATION
<b>Priority Sequence:</b>	24		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS6D	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	GENERAL
		<b>Element:</b>	OTHER
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) G		

**Project Description**

The ground floor employee locker room fixtures and finishes are mostly original to the year of construction or latest major renovation. The fixtures are sound but dated and are spaced such that clearances are not ADA compliant. A comprehensive locker room renovation, including new fixtures, finishes, partitions, and accessories, is recommended. Locker room expansion may be necessary in order to meet modern minimum fixture counts and accessibility legislation.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBIS08

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Major restroom renovation, including fixtures, finishes, partitions, accessories, and expansion if necessary	FIXT	8	\$1,969	\$15,752	\$1,699	\$13,592	\$29,344
Shower, 125 square feet of locker room renovation, partitions, accessories, and expansion if necessary	FIXT	2	\$5,141	\$10,282	\$6,859	\$13,718	\$24,000
<b>Project Totals:</b>				<b>\$26,034</b>		<b>\$27,310</b>	<b>\$53,344</b>

<b>Material/Labor Cost</b>		<b>\$53,344</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$40,226</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$8,045</b>
<b>Inflation</b>	+	<b>\$1,511</b>
<b>Construction Cost</b>		<b>\$49,782</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$7,965</b>
<b>Total Project Cost</b>		<b>\$57,748</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBPL01	<b>Title:</b>	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT
<b>Priority Sequence:</b>	25		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	PL1E	<b>System:</b>	PLUMBING
		<b>Component:</b>	DOMESTIC WATER
		<b>Element:</b>	HEATING
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Item Only: Floor(s) G		

**Project Description**

Replacement of the domestic hot water converter is recommended. With age, heat exchanger efficiency is reduced by internal tube scaling. Internal wear will eventually lead to failure, allowing contaminants to enter the water system. Remove the existing system. Install a new heat exchanger, pumps, piping, and controls as needed.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBPL01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Heat exchanger, pumps, piping, valves, controls, insulation, and demolition	GPM	96	\$176	\$16,880	\$144	\$13,785	\$30,664
<b>Project Totals:</b>				<b>\$16,880</b>		<b>\$13,785</b>	<b>\$30,664</b>

<b>Material/Labor Cost</b>		<b>\$30,664</b>
<b>Material Index</b>		<b>100.7%</b>
<b>Labor Index</b>		<b>51.3%</b>
<b>Material/Labor Indexed Cost</b>		<b>\$24,069</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$4,814</b>
<b>Inflation</b>	+	<b>\$904</b>
<b>Construction Cost</b>		<b>\$29,787</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$4,766</b>
<b>Total Project Cost</b>		<b>\$34,553</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBSI01	<b>Title:</b>	SITE PAVING UPGRADES
<b>Priority Sequence:</b>	26		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	SI4A	<b>System:</b>	SITE
		<b>Component:</b>	GENERAL
		<b>Element:</b>	OTHER
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	502	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Undefined: Floor(s) 1		

**Project Description**

The pedestrian paving systems are in overall fair to good condition, with isolated areas of settlement and uneven pavements that may potentially represent a liability to the owner. In-place grinding, selective area replacements, and brick paver resets are recommended.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBSI01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Concrete pedestrian paving	SF	800	\$2.97	\$2,376	\$3.64	\$2,912	\$5,288
Brick pedestrian paving	SF	1,200	\$6.98	\$8,376	\$6.77	\$8,124	\$16,500
Brick paver resets and concrete grinding	LOT	1	\$1,200	\$1,200	\$3,200	\$3,200	\$4,400
<b>Project Totals:</b>				<b>\$11,952</b>		<b>\$14,236</b>	<b>\$26,188</b>

<b>Material/Labor Cost</b>		<b>\$26,188</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$19,339</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$3,868</b>
<b>Inflation</b>	+	<b>\$726</b>
<b>Construction Cost</b>		<b>\$23,933</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$3,829</b>
<b>Total Project Cost</b>		<b>\$27,762</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBAC01	<b>Title:</b>	BUILDING ENTRY ACCESSIBILITY UPGRADES
<b>Priority Sequence:</b>	27		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	AC2A	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	BUILDING ENTRY
		<b>Element:</b>	GENERAL
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	403.6, 505	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Undefined: Floor(s) 1		

**Project Description**

Current legislation related to accessibility requires that building entrances be wheelchair accessible. To comply with the intent of this legislation, it is recommended that compliant, painted metal handrails be installed at all entrances as required.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBAC01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Freestanding handrail system, painted (15 foot minimum)	LF	132	\$91.11	\$12,027	\$150	\$19,800	\$31,827
Wall-mounted handrail system, painted (15 foot minimum)	LF	148	\$50.50	\$7,474	\$35.40	\$5,239	\$12,713
<b>Project Totals:</b>				<b>\$19,501</b>		<b>\$25,039</b>	<b>\$44,540</b>

<b>Material/Labor Cost</b>		<b>\$44,540</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$32,482</u>
<b>General Contractor Mark Up at 20.0%</b>	+	<u>\$6,496</u>
<b>Inflation</b>	+	<u>\$1,220</u>
<b>Construction Cost</b>		<u>\$40,199</u>
<b>Professional Fees at 16.0%</b>	+	<u>\$6,432</u>
<b>Total Project Cost</b>		<u><b>\$46,630</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBAC02	<b>Title:</b>	AUDITORIUM ACCESSIBILITY UPGRADES
<b>Priority Sequence:</b>	28		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	AC4B	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	GENERAL
		<b>Element:</b>	OTHER
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	219.3, 706.1, 806, 505	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Undefined: Floor(s) 1		

**Project Description**

Current accessibility legislation requires that places of assembly be accessible to the handicapped. The auditorium has multiple barriers to accessibility. There are no seating spaces designated for wheelchair use. It is recommended that approximately eight seating areas be modified to accommodate persons in wheelchairs. Install transmitter and headphone receiver sets to accommodate those individuals that require audible assistance. The access steps at the auditorium stage lack supportive handrails. It is recommended that wall-mounted, compliant, painted metal handrails be installed.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBAC02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Accessible seating modifications	LOT	8	\$885	\$7,080	\$555	\$4,440	\$11,520
Infrared transmitter and headphone receiver sets	SYS	1	\$1,520	\$1,520	\$1,333	\$1,333	\$2,853
Wall-mounted handrail system (15 foot minimum)	LF	24	\$50.50	\$1,212	\$35.40	\$850	\$2,062
<b>Project Totals:</b>				<b>\$9,812</b>		<b>\$6,623</b>	<b>\$16,435</b>

<b>Material/Labor Cost</b>		\$16,435
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		\$13,278
<b>General Contractor Mark Up at 20.0%</b>	+	\$2,656
<b>Inflation</b>	+	\$499
<b>Construction Cost</b>		\$16,432
<b>Professional Fees at 16.0%</b>	+	\$2,629
<b>Total Project Cost</b>		<b>\$19,062</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBAC03	<b>Title:</b>	STAIR SAFETY UPGRADES
<b>Priority Sequence:</b>	29		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	AC3B	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	INTERIOR PATH OF TRAVEL
		<b>Element:</b>	STAIRS AND RAILINGS
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	IBC	1003.3	
	ADAAG	505	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

Current legislation regarding building accessibility by the handicapped requires that stairs have graspable handrails on both sides, that the rails have a specific end geometry, and that the handrails continue horizontally at the landings. In addition, guardrails must prevent the passage of a 4 inch diameter sphere (6 inches in the triangle formed by the lower rail and tread / riser angle). Although the stairs are compliant with the code enforced at the time of construction until a major renovation occurs, they are deficient in handrail and guardrail design relative to current standards. The finishes on the stairs have also deteriorated or are otherwise unsafe. Future renovation efforts should include comprehensive stair railing and finish upgrades. The installation of contrasting visual stair / step nosings should also be installed at all locations to improve stair safety.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBAC03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Wall-mounted handrail system per floor	FLR	20	\$573	\$11,460	\$521	\$10,420	\$21,880
Center handrail / guardrail system per floor	FLR	20	\$1,297	\$25,940	\$833	\$16,660	\$42,600
Stair tread and landing finish upgrades per floor	FLR	26	\$1,449	\$37,674	\$773	\$20,098	\$57,772
<b>Project Totals:</b>				<b>\$75,074</b>		<b>\$47,178</b>	<b>\$122,252</b>

<b>Material/Labor Cost</b>		\$122,252
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		\$99,802
<b>General Contractor Mark Up at 20.0%</b>	+	\$19,960
<b>Inflation</b>	+	\$3,749
<b>Construction Cost</b>		\$123,511
<b>Professional Fees at 16.0%</b>	+	\$19,762
<b>Total Project Cost</b>		<b>\$143,272</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBES06	<b>Title:</b>	WINDOW WALL REPLACEMENT AND UPGRADES
<b>Priority Sequence:</b>	30		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	ES5B	<b>System:</b>	EXTERIOR
		<b>Component:</b>	FENESTRATIONS
		<b>Element:</b>	WINDOWS
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Energy Conservation	\$2,200	
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/9/2009		
<b>Project Location:</b>	Building-wide: Floor(s) 1		

**Project Description**

Approximately 20 percent of the exterior window wall systems have been replaced since the original construction. The newer systems include insulated glazing units. It is recommended that the remaining older single pane, aluminum-framed window wall applications be upgraded to thermal pane systems. Such double pane systems will reduce the energy required to operate the building. Repair or replacement of the windowsills and trim may also be necessary.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBES06

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Typical standard glazing applications	SF	10,450	\$57.27	\$598,472	\$36.45	\$380,903	\$979,374
<b>Project Totals:</b>				<b>\$598,472</b>		<b>\$380,903</b>	<b>\$979,374</b>

<b>Material/Labor Cost</b>		<b>\$979,374</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$798,064</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$159,613</b>
<b>Inflation</b>	+	<b>\$29,975</b>
<b>Construction Cost</b>		<b>\$987,652</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$158,024</b>
<b>Total Project Cost</b>		<b>\$1,145,676</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBEL04	<b>Title:</b>	UPGRADE ELECTRICAL DISTRIBUTION NETWORK
<b>Priority Sequence:</b>	31		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	EL3B	<b>System:</b>	ELECTRICAL
		<b>Component:</b>	SECONDARY DISTRIBUTION
		<b>Element:</b>	DISTRIBUTION NETWORK
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	NEC	Articles 110, 210, 220, 230	
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 2, G		

**Project Description**

An upgrade of the building electrical system is recommended. Aging components, such as the circuit breakers, could serve as fire hazards if they fail to open a circuit in an overload or short circuit condition. Remove existing 1970s vintage electrical components and branch circuitry. Install new power panels, switches, raceways, conductors, and devices. Provide molded case thermal magnetic circuit breakers and HACR circuit breakers for HVAC equipment. Redistribute the electrical loads to the appropriate areas to ensure safe and reliable power to building occupants. In original building areas and subsequent additions, provide ground fault circuit interrupter (GFCI) protection where required, and clearly label all panels for circuit identification. In 1988 addition areas, update switches, receptacles, cover plates, and miscellaneous items as indicated in the task descriptions.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBEL04

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Power panels, conductors, raceways, devices, demolition, and cut and patching materials in the original 1974 areas of the building	SF	88,129	\$5.07	\$446,814	\$7.60	\$669,780	\$1,116,594
Switches, receptacles, cover plates, breakers, and miscellaneous materials in 1988 addition areas of the building	SF	35,771	\$0.39	\$13,951	\$0.59	\$21,105	\$35,056
<b>Project Totals:</b>				<b>\$460,765</b>		<b>\$690,885</b>	<b>\$1,151,650</b>

<b>Material/Labor Cost</b>		<b>\$1,151,650</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$818,414</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$163,683</b>
<b>Inflation</b>	+	<b>\$30,740</b>
<b>Construction Cost</b>		<b>\$1,012,837</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$162,054</b>
<b>Total Project Cost</b>		<b>\$1,174,891</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Description**

<b>Project Number:</b>	MSCBPL02	<b>Title:</b>	WATER SUPPLY PIPING REPLACEMENT
<b>Priority Sequence:</b>	32		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	PL1A	<b>System:</b>	PLUMBING
		<b>Component:</b>	DOMESTIC WATER
		<b>Element:</b>	PIPING NETWORK
<b>Building Code:</b>	MSCB		
<b>Building Name:</b>	MENDENHALL STUDENT CENTER		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	IPC	Chapter 6	
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	11/2/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1,2,G		

**Project Description**

Replacement of the aging water piping network in the original 1974 portion of the facility is recommended. Failure to replace the water piping will result in frequent leaks and escalating maintenance costs. Remove the existing water supply network. Install new copper water supply piping with fiberglass insulation. Install isolation valves, pressure regulators, shock absorbers, backflow preventers, and vacuum breakers as needed.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
MSCB : MENDENHALL STUDENT CENTER

**Project Cost**

**Project Number:** MSCBPL02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Copper pipe and fittings, valves, backflow prevention devices, insulation, hangers, demolition, and cut and patching materials	SF	81,129	\$1.74	\$141,164	\$4.36	\$353,722	\$494,887
<b>Project Totals:</b>				<b>\$141,164</b>		<b>\$353,722</b>	<b>\$494,887</b>

<b>Material/Labor Cost</b>		<b>\$494,887</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$323,612</b>
<b>General Contractor Mark Up at 20.0%</b>	+	\$64,722
<b>Inflation</b>	+	\$12,155
<b>Construction Cost</b>		<b>\$400,490</b>
<b>Professional Fees at 16.0%</b>	+	\$64,078
<b>Total Project Cost</b>		<b>\$464,568</b>





FACILITY CONDITION ANALYSIS

**SECTION 4**


**DRAWINGS  
AND PROJECT LOCATIONS**





FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



- AC03
- EL03
- EL04
- FS01
- FS02
- FS03
- HV01
- IS01
- IS02
- IS03
- IS04
- IS05
- IS07
- IS08
- PL02

- PROJECT NUMBER APPLIES TO ONE ROOM ONLY
- PROJECT NUMBER APPLIES TO ONE ITEM ONLY
- PROJECT NUMBER APPLIES TO ENTIRE BUILDING
- PROJECT NUMBER APPLIES TO ENTIRE FLOOR
- PROJECT NUMBER APPLIES TO A SITUATION OF UNDEFINED EXTENTS
- PROJECT NUMBER APPLIES TO AREA AS NOTED


Date: 12/16/09  
 Drawn by: J.T.V.  
 Project No. 09-041

GROUND  
FLOOR  
PLAN



FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376




- AC01 AC02 IS06 SI01
- ES01 ES02 ES03 ES05 ES06
- AC03 EL03 EL04 FS01 FS02 FS03
- HV01 IS01 IS02 IS03 IS04 IS05
- IS07 PL02

- PROJECT NUMBER APPLIES TO ONE ROOM ONLY
- PROJECT NUMBER APPLIES TO ONE ITEM ONLY
- PROJECT NUMBER APPLIES TO ENTIRE BUILDING
- PROJECT NUMBER APPLIES TO ENTIRE FLOOR
- PROJECT NUMBER APPLIES TO A SITUATION OF UNDEFINED EXTENTS
- PROJECT NUMBER APPLIES TO AREA AS NOTED



Date: 12/16/09  
 Drawn by: J.T.V.  
 Project No. 09-041

FIRST  
FLOOR  
PLAN

Sheet No.  
2 of 3



ROOF









MENDENHALL  
STUDENT CENTER

BLDG NO. MSCB




FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376

-  PROJECT NUMBER APPLIES TO ONE ROOM ONLY
-  PROJECT NUMBER APPLIES TO ONE ITEM ONLY
-  PROJECT NUMBER APPLIES TO ENTIRE BUILDING
-  PROJECT NUMBER APPLIES TO ENTIRE FLOOR
-  PROJECT NUMBER APPLIES TO A SITUATION OF UNDEFINED EXTENTS
-  PROJECT NUMBER APPLIES TO AREA AS NOTED

Date: 12/16/09  
 Drawn by: J.T.V.  
 Project No. 09-041



SECOND  
FLOOR  
PLAN

Sheet No.  
3 of 3



FACILITY CONDITION ANALYSIS

**SECTION 5**

LIFE CYCLE MODEL SUMMARY  
AND PROJECTIONS





**Life Cycle Model**  
**Building Component Summary**  
**MSCB : MENDENHALL STUDENT CENTER**

<b>Unifomat Code</b>	<b>Component Description</b>	<b>Qty</b>	<b>Units</b>	<b>Unit Cost</b>	<b>Complex Adj</b>	<b>Total Cost</b>	<b>Install Date</b>	<b>Life Exp</b>
B2010	EXTERIOR FINISH RENEWAL	17,490	SF	\$1.30		\$22,800	1974	10
B2010	EXTERIOR FINISH RENEWAL	24,050	SF	\$1.30	.31	\$9,719	1974	10
B2010	STUCCO FINISH RENEWAL	2,190	SF	\$3.33		\$7,293	1974	30
B2020	STANDARD GLAZING AND CURTAIN WALL	10,450	SF	\$104.04		\$1,087,182	1974	55
B2020	STANDARD GLAZING AND CURTAIN WALL	2,610	SF	\$104.04		\$271,535	1990	55
B2030	HIGH TRAFFIC EXTERIOR DOOR SYSTEM	10	LEAF	\$4,311.24		\$43,112	1974	20
B2030	HIGH TRAFFIC EXTERIOR DOOR SYSTEM	12	LEAF	\$4,311.24		\$51,735	1990	20
B2030	LOW TRAFFIC EXTERIOR DOOR SYSTEM	12	LEAF	\$2,863.29		\$34,359	1974	40
B3010	BUILT-UP ROOF	83,736	SF	\$6.70		\$561,251	1989	20
B3010	BUILT-UP ROOF	20,934	SF	\$6.70		\$140,313	2000	20
C1020	STANDARD DOOR AND FRAME INCLUDING HARDWARE	200	LEAF	\$783.68		\$156,736	1974	35
C1020	RATED DOOR AND FRAME INCLUDING HARDWARE	485	LEAF	\$1,489.06		\$722,194	1974	35
C1020	INTERIOR DOOR HARDWARE	485	EA	\$423.04		\$205,176	1974	15
C1020	INTERIOR DOOR HARDWARE	200	EA	\$423.04		\$84,608	1974	15
C3010	STANDARD WALL FINISH (PAINT, WALL COVERING, ETC.)	179,740	SF	\$0.80		\$143,979	1974	10
C3010	PREMIUM WALL FINISH (EPOXY, TILE, WOOD PANEL, ETC.)	31,720	SF	\$5.87		\$186,071	1974	20
C3020	CARPET	38,200	SF	\$8.75		\$334,115	1974	10
C3020	VINYL FLOOR TILE	3,550	SF	\$6.59		\$23,387	1974	15
C3020	CERAMIC FLOOR TILE	15,100	SF	\$17.36		\$262,172	1974	20
C3020	RESURFACE AND SEAL CONCRETE OR TERRAZZO	17,770	SF	\$5.85		\$103,896	1974	50
C3020	HARDWOOD REPLACEMENT	14,220	SF	\$23.94		\$340,381	1974	50
C3020	SAND AND FINISH HARDWOOD FLOORING	14,220	SF	\$3.24		\$46,041	1974	15
C3030	ACOUSTICAL TILE CEILING SYSTEM	57,750	SF	\$4.99		\$288,346	1974	15
C3030	PAINTED CEILING FINISH APPLICATION	20,430	SF	\$0.80		\$16,365	1974	15
D1010	ELEVATOR MODERNIZATION - HYDRAULIC	1	EA	\$158,628.64		\$158,629	2004	25
D1010	ELEVATOR MODERNIZATION - HYDRAULIC	1	EA	\$158,628.64		\$158,629	1988	25
D1010	ELEVATOR CAB RENOVATION - PASSENGER	1	EA	\$26,616.80		\$26,617	2004	12
D1010	ELEVATOR CAB RENOVATION - PASSENGER	1	EA	\$26,616.80		\$26,617	1988	12
D2010	PLUMBING FIXTURES - STUDENT UNION	81,129	SF	\$7.96		\$645,575	1974	35

**Life Cycle Model**  
**Building Component Summary**  
**MSCB : MENDENHALL STUDENT CENTER**


<b>Unifomat Code</b>	<b>Component Description</b>	<b>Qty</b>	<b>Units</b>	<b>Unit Cost</b>	<b>Complex Adj</b>	<b>Total Cost</b>	<b>Install Date</b>	<b>Life Exp</b>
D2010	PLUMBING FIXTURES - STUDENT UNION	35,771	SF	\$7.96		\$284,644	1988	35
D2020	WATER PIPING - STUDENT UNION	81,129	SF	\$5.66		\$459,414	1974	35
D2020	WATER PIPING - STUDENT UNION	35,771	SF	\$5.66		\$202,563	1988	35
D2020	WATER HEATER, SHELL AND TUBE HEAT EXCHANGER	96	GPM	\$355.69		\$34,146	1988	24
D2030	DRAIN PIPING - STUDENT UNION	81,129	SF	\$8.60		\$697,306	1974	40
D2030	DRAIN PIPING - STUDENT UNION	35,771	SF	\$8.60		\$307,453	1988	40
D2030	SUMP PUMP SYS (2 PUMPS, CONTROLS)	2	SYS	\$8,276.49		\$16,553	2005	20
D2030	SUMP PUMP SYS (2 PUMPS, CONTROLS)	2	SYS	\$8,276.49		\$16,553	1974	20
D2050	AIR COMPRESSOR PACKAGE (AVERAGE SIZE)	1	SYS	\$6,456.49		\$6,456	1974	25
D2050	AIR COMPRESSOR PACKAGE (AVERAGE SIZE)	1	SYS	\$6,456.49		\$6,456	1988	25
D3030	COLD BOX REFRIGERATION SYSTEM	5	SYS	\$6,324.50		\$31,622	1988	15
D3030	CHILLER - WATER COOLED (200-1000 TONS)	380	TON	\$686.38		\$260,825	2004	25
D3030	CHILLER - AIR COOLED (OVER 100 TONS)	170	TON	\$1,173.39		\$199,476	1988	20
D3030	COOLING TOWER (OVER 300 TONS)	500	TON	\$184.81		\$92,407	2004	20
D3040	CONDENSATE RECEIVER	1	SYS	\$9,504.01		\$9,504	2004	15
D3040	CONDENSATE RECEIVER	1	SYS	\$9,504.01		\$9,504	1988	15
D3040	EXHAUST FAN - CENTRIFUGAL ROOF EXHAUSTER OR SIMILAR	13	EA	\$2,768.62		\$35,992	1974	20
D3040	EXHAUST FAN - UTILITY SET OR SIMILAR	11	EA	\$3,660.81		\$40,269	1974	20
D3040	EXHAUST FAN - PROPELLER TYPE OR SIMILAR	1	EA	\$1,357.34		\$1,357	1974	20
D3040	KITCHEN EXHAUST SYSTEM WITH MAKE-UP UNIT	1	SYS	\$54,113.61		\$54,114	1974	20
D3040	ELECTRIC UNIT HEATER (10 KW)	2	EA	\$1,255.64		\$2,511	1974	22
D3040	HVAC SYSTEM - STUDENT UNION	81,129	SF	\$28.79		\$2,335,560	1974	25
D3040	HVAC SYSTEM - STUDENT UNION	35,771	SF	\$28.79		\$1,029,784	1988	25
D3040	BASE MTD. PUMP - UP TO 15 HP	50	HP	\$3,175.77		\$158,788	2004	20
D3040	BASE MTD. PUMP - 15 HP TO 50 HP	35	HP	\$1,142.19		\$39,977	2004	20
D3040	BASE MTD. PUMP - 50 HP TO 150 HP	40	HP	\$782.99		\$31,319	2004	25
D5010	ELECTRICAL SYSTEM - STUDENT UNION	81,129	SF	\$12.78		\$1,036,472	1974	50
D5010	ELECTRICAL SYSTEM - STUDENT UNION	35,771	SF	\$12.78		\$456,996	1988	50
D5010	ELECTRICAL SWITCHGEAR 120/208V	1,600	AMP	\$32.96		\$52,742	1988	20

**Life Cycle Model  
Building Component Summary  
MSCB : MENDENHALL STUDENT CENTER**

<b>Unifomat Code</b>	<b>Component Description</b>	<b>Qty</b>	<b>Units</b>	<b>Unit Cost</b>	<b>Complex Adj</b>	<b>Total Cost</b>	<b>Install Date</b>	<b>Life Exp</b>
D5010	ELECTRICAL SWITCHGEAR 120/208V	800	AMP	\$32.96		\$26,371	1974	20
D5010	ELECTRICAL SWITCHGEAR 277/480V	1,200	AMP	\$39.56		\$47,476	1974	20
D5010	ELECTRICAL SWITCHGEAR 277/480V	2,500	AMP	\$39.56		\$98,909	1988	20
D5010	ELECTRICAL SWITCHGEAR 277/480V	1,600	AMP	\$39.56		\$63,302	1988	20
D5020	EXIT SIGNS (CENTRAL POWER)	118	EA	\$163.78		\$19,326	1974	20
D5020	EXTERIOR LIGHT (HID)	1	EA	\$689.58		\$690	1974	20
D5020	LIGHTING - STUDENT UNION	81,129	SF	\$6.68		\$542,236	1974	20
D5020	LIGHTING - STUDENT UNION	35,771	SF	\$6.68		\$239,080	1988	20
D5030	FIRE ALARM SYSTEM, POINT ADDRESSABLE	116,900	SF	\$2.61		\$305,646	1988	15
D5040	GENERATOR, DIESEL (50-100KW)	50	KW	\$717.93		\$35,897	1988	25
E2010	STANDARD BASE OR WALL CABINetry	240	LF	\$272.50		\$65,400	1994	20
E2010	BASIC FOLDING FIXED SEATING	760	EA	\$278.95		\$212,001	1994	20
F1020	ENVIRONMENTAL CHAMBER	400	SF	\$139.02		<u>\$55,606</u>	1988	35
						<b>\$15,781,537</b>		

# Life Cycle Model Expenditure Projections

MSCB : MENDENHALL STUDENT CENTER



Average Annual Renewal Cost Per SqFt \$5.17

FACILITY CONDITION ANALYSIS

**SECTION 6**

PHOTOGRAPHIC LOG



**Photo Log - Facility Condition  
Analysis  
MSCB : MENDENHALL STUDENT CENTER**

<b>Photo ID No</b>	<b>Description</b>	<b>Location</b>	<b>Date</b>
MSCB001a	Building facade	East elevation	9/14/2009
MSCB001e	Air-cooled liquid chiller in foreground and Marley cooling tower in background	From roof, looking south	9/14/2008
MSCB002a	Loading dock	South elevation	9/14/2009
MSCB002e	Out-of-service Ansul dry extinguishing system	Serving pantry 240	9/14/2008
MSCB003a	Loading dock	South elevation	9/14/2009
MSCB003e	AHU9 with outside air disconnected and closed off	Mechanical room 249	9/14/2008
MSCB004a	Building facade	East elevation	9/14/2009
MSCB004e	Floor drain	Mechanical room 249	9/14/2008
MSCB005a	Building facade	East elevation	9/14/2009
MSCB005e	Floor drain and piping penetrations	Mechanical room 249	9/14/2008
MSCB006a	Building facade	West elevation	9/14/2009
MSCB006e	Negative air pressure at drain inlet	Mechanical room 249	9/14/2008
MSCB007a	Outdoor terrace	Southwest building corner	9/14/2009
MSCB007e	Mineral deposits at valve and fittings	Mechanical room 249	9/14/2008
MSCB008a	Building facade	South elevation	9/14/2009
MSCB008e	Pendant type ceiling diffuser	Auditorium 102, balcony	9/14/2008
MSCB009a	Outdoor terrace	Southwest building corner	9/14/2009
MSCB009e	Trane Climate Changer air handling unit	Mechanical room 113	9/14/2008
MSCB010a	Building facade	South elevation	9/14/2009
MSCB010e	Fluorescent vanity lighting fixtures	Women's restroom 103	9/14/2008
MSCB011a	Building facade	West elevation	9/14/2009
MSCB011e	Chilled water pump for addition, Carrier liquid chiller system	Mechanical room G105	9/14/2008
MSCB012a	Building facade	West elevation	9/14/2009
MSCB012e	Duplex control air compressor	Mechanical room G105	9/14/2008
MSCB013a	Primary entrance and facade	North elevation	9/14/2009
MSCB013e	Carrier air handling unit	Mechanical room G105	9/14/2008
MSCB014a	Primary entrance and facade	North elevation	9/14/2009
MSCB014e	Two shell-and-tube heat exchangers	Mechanical room G105	9/14/2008
MSCB015a	Primary entrance and facade	Northeast building corner elevation	9/14/2009
MSCB015e	Duplex condensate receiver	Mechanical room G105	9/14/2008
MSCB016a	Building facade	East elevation	9/14/2009

**Photo Log - Facility Condition  
Analysis  
MSCB : MENDENHALL STUDENT CENTER**

<b>Photo ID No</b>	<b>Description</b>	<b>Location</b>	<b>Date</b>
MSCB016e	Missing insulation and dripping unions at domestic hot water heat exchanger	Mechanical room G105	9/14/2008
MSCB017a	Mechanical equipment screenwall	Southeast building corner	9/14/2009
MSCB017e	Vertical-mount sump pumps	Mechanical room G105	9/14/2008
MSCB018a	Architectural precast concrete panels	Building facade	9/14/2009
MSCB018e	Typical lavatory	Men's restroom G012	9/14/2008
MSCB019a	Failing sealant joints in precast panels	Building facade	9/14/2009
MSCB019e	Simplex 4002 fire alarm control panel	Mechanical room G030	9/14/2008
MSCB020a	Failing sealant joints in precast panels	Building facade	9/14/2009
MSCB020e	Main 2,500 amp switchboard added in 1988 and original switchboard BD	Mechanical room G030	9/14/2008
MSCB021a	Water damaged brick wall at exterior stairway	Northeast building corner	9/14/2009
MSCB021e	Cummins diesel emergency generator	Mechanical room G030	9/14/2008
MSCB022a	Failing sealant joints in precast panels	Building facade	9/14/2009
MSCB022e	Heat exchanger for heating hot water	Mechanical room G030	9/14/2008
MSCB023a	Failing sealant joints in precast panels	Building facade	9/14/2009
MSCB023e	Heat exchanger for domestic hot water	Mechanical room G030	9/14/2008
MSCB024a	Impact damage at loading dock wall	Loading dock	9/14/2009
MSCB024e	Automatic transfer switch, emergency panels, panel EE, and transformer	Mechanical room G030	9/14/2008
MSCB025a	Structural masonry wall crack at dock	Auditorium dock, west	9/14/2009
MSCB025e	Carrier liquid chiller, three of six compressors	South of building	9/14/2008
MSCB026a	Structural masonry wall crack at dock	Auditorium dock, west	9/14/2009
MSCB026e	Carrier liquid chiller, three of six compressors	South of building	9/14/2008
MSCB027a	Water infiltration at basement wall	Mechanical room G028	9/14/2009
MSCB028a	Typical original exterior window wall	Building facade	9/14/2009
MSCB029a	Stucco soffit over window wall	Building facade	9/14/2009
MSCB030a	Typical original exterior window wall	Building facade	9/14/2009
MSCB031a	Stucco soffit over window wall	Building facade	9/14/2009
MSCB032a	Deteriorating exterior service door	Southeast ground floor egress	9/14/2009
MSCB033a	Light monitor penthouse	Main roof	9/14/2009
MSCB034a	Overview of membrane roofing system	Main roof	9/14/2009
MSCB035a	Failed roof membrane with blisters	Main roof	9/14/2009
MSCB036a	Failed roof membrane with blisters	Main roof	9/14/2009



**Photo Log - Facility Condition  
Analysis  
MSCB : MENDENHALL STUDENT CENTER**

<b>Photo ID No</b>	<b>Description</b>	<b>Location</b>	<b>Date</b>
MSCB037a	Failed roof membrane base flashing	Main roof	9/14/2009
MSCB038a	Overview of membrane roofing system	Main roof, east	9/14/2009
MSCB039a	Failed roof membrane and exposed felt fibers	Main roof, east	9/14/2009
MSCB040a	Unprotected top surface on precast panel	Main roof, perimeter curb	9/14/2009
MSCB041a	Failed roof membrane with blisters	Main roof	9/14/2009
MSCB042a	Failed roof membrane seams	Main roof	9/14/2009
MSCB043a	Failed roof membrane with blisters	Main roof	9/14/2009
MSCB044a	Failed roof membrane seams	Main roof	9/14/2009
MSCB045a	Failed roof membrane seams	Main roof	9/14/2009
MSCB046a	Failed roof membrane seams	Main roof	9/14/2009
MSCB047a	Failed roof membrane seams	Main roof	9/14/2009
MSCB048a	Obstructed roof drain inlet	Main roof	9/14/2009
MSCB049a	Obstructed roof drain inlet	Main roof	9/14/2009
MSCB050a	Obstructed roof drain inlet	Main roof	9/14/2009
MSCB051a	Failing sealant joints in precast panels	Roof parapet wall	9/14/2009
MSCB052a	Meeting room interior	Second floor	9/14/2009
MSCB053a	Clerestory lighting windows	Second floor	9/14/2009
MSCB054a	Non-compliant fire separation door	First floor	9/14/2009
MSCB055a	Non-compliant fire separation door	First floor	9/14/2009
MSCB056a	Overview of dining area, Grille	First floor	9/14/2009
MSCB057a	Overview of dining area, Grille	First floor	9/14/2009
MSCB058a	Main kitchen area, Grille	First floor	9/14/2009
MSCB059a	Non-compliant fire separation door	Typical stairwell	9/14/2009
MSCB060a	Bowling alley lanes	Ground floor	9/14/2009
MSCB061a	Billiard room	Ground floor	9/14/2009
MSCB062a	Typical corridor	Ground floor	9/14/2009
MSCB063a	Missing fire safing	Electrical / mechanical room	9/14/2009
MSCB064a	Improperly blocked egress corridor	Outside mechanical room 130	9/14/2009
MSCB065a	Overhead storage room door	Main kitchen	9/14/2009
MSCB066a	Mold growth at leaking piping	Main electrical room G17	9/14/2009
MSCB067a	Mold growth at leaking piping	Main electrical room G17	9/14/2009
MSCB068a	Non-compliant thumb latch door hardware	Typical stairwell	9/14/2009
MSCB069a	Non-compliant handrail	Typical stairwell	9/14/2009

**Photo Log - Facility Condition  
Analysis  
MSCB : MENDENHALL STUDENT CENTER**

<b>Photo ID No</b>	<b>Description</b>	<b>Location</b>	<b>Date</b>
MSCB070a	Non-compliant knob type door hardware	Typical stairwell	9/14/2009
MSCB071a	Missing handrailing	Stage steps, meeting room 214	9/14/2009
MSCB072a	Non-compliant railing systems	Central stair	9/14/2009
MSCB073a	Non-compliant railing systems	Central stair	9/14/2009
MSCB074a	Non-compliant handrailing	Typical stairwell	9/14/2009
MSCB075a	Missing handrailing	Ground floor, service elevator	9/14/2009
MSCB076a	Missing handrailing	Exterior egress steps	9/14/2009
MSCB077a	Missing handrailing	Exterior access ramp	9/14/2009
MSCB078a	Non-compliant handrailing	Exterior egress steps	9/14/2009
MSCB079a	Missing handrailing	Exterior access ramp	9/14/2009
MSCB080a	Missing handrailing	Exterior egress steps	9/14/2009
MSCB081a	Non-contrast stair nosings	Exterior egress steps	9/14/2009
MSCB082a	Non-contrast stair nosings	Exterior egress steps	9/14/2009
MSCB083a	Undersized accessible stall	Public restroom	9/14/2009
MSCB084a	Partially compliant, aging lavatory	Public restroom	9/14/2009
MSCB085a	Trip hazard at elevator doorsill	Second floor, service elevator	9/14/2009
MSCB086a	Aging fixtures and partitions	Public restroom	9/14/2009
MSCB087a	Aging fixtures and finishes	Public restroom	9/14/2009
MSCB088a	Aging fixtures and partitions	Public restroom	9/14/2009
MSCB089a	Aging and non-compliant drinking fountain	Public corridor	9/14/2009
MSCB090a	Typical folding theater seat	Second floor, auditorium	9/14/2009
MSCB091a	Non-contrast stair nosings	Exterior egress steps	9/14/2009
MSCB092a	Trip hazard at settled brick pavers	Exterior terrace	9/14/2009
MSCB093a	Overview of cooling tower enclosure	Building exterior, southeast	9/14/2009

Facility Condition Analysis - Photo Log



MSCB001A.jpg



MSCB001E.jpg



MSCB002A.jpg



MSCB002E.jpg



MSCB003A.jpg



MSCB003E.jpg



MSCB004A.jpg



MSCB004E.jpg



MSCB005A.jpg



MSCB005E.jpg



MSCB006A.jpg



MSCB006E.jpg



MSCB007A.jpg



MSCB007E.jpg



MSCB008A.jpg



MSCB008E.jpg



MSCB009A.jpg



MSCB009E.jpg



MSCB010A.jpg



MSCB010E.jpg

Facility Condition Analysis - Photo Log



MSCB011A.jpg



MSCB011E.jpg



MSCB012A.jpg



MSCB012E.jpg



MSCB013A.jpg



MSCB013E.jpg



MSCB014A.jpg



MSCB014E.jpg



MSCB015A.jpg



MSCB015E.jpg



MSCB016A.jpg



MSCB016E.jpg



MSCB017A.jpg



MSCB017E.jpg



MSCB018A.jpg




MSCB018E.jpg



MSCB019A.jpg



MSCB019E.jpg



MSCB020A.jpg



MSCB020E.jpg

Facility Condition Analysis - Photo Log



MSCB021A.jpg



MSCB021E.jpg



MSCB022A.jpg



MSCB022E.jpg



MSCB023A.jpg



MSCB023E.jpg



MSCB024A.jpg



MSCB024E.jpg



MSCB025A.jpg



MSCB025E.jpg



MSCB026A.jpg



MSCB026E.jpg



MSCB027A.jpg



MSCB028A.jpg



MSCB029A.jpg



MSCB030A.jpg



MSCB031A.jpg



MSCB032A.jpg



MSCB033A.jpg



MSCB034A.jpg

Facility Condition Analysis - Photo Log



MSCB035A.jpg



MSCB036A.jpg



MSCB037A.jpg



MSCB038A.jpg



MSCB039A.jpg



MSCB040A.jpg




MSCB041A.jpg



MSCB042A.jpg



MSCB043A.jpg



MSCB044A.jpg



MSCB045A.jpg



MSCB046A.jpg




MSCB047A.jpg



MSCB048A.jpg



MSCB049A.jpg



MSCB050A.jpg



MSCB051A.jpg



MSCB052A.jpg



MSCB053A.jpg



MSCB054A.jpg

Facility Condition Analysis - Photo Log



MSCB055A.jpg




MSCB056A.jpg



MSCB057A.jpg



MSCB058A.jpg



MSCB059A.jpg



MSCB060A.jpg




MSCB061A.jpg



MSCB062A.jpg



MSCB063A.jpg



MSCB064A.jpg



MSCB065A.jpg



MSCB066A.jpg



MSCB067A.jpg



MSCB068A.jpg



MSCB069A.jpg



MSCB070A.jpg



MSCB071A.jpg



MSCB072A.jpg



MSCB073A.jpg



MSCB074A.jpg

Facility Condition Analysis - Photo Log




MSCB075A.jpg



MSCB076A.jpg



MSCB077A.jpg



MSCB078A.jpg



MSCB079A.jpg



MSCB080A.jpg



MSCB081A.jpg




MSCB082A.jpg



MSCB083A.jpg



MSCB084A.jpg



MSCB085A.jpg



MSCB086A.jpg



MSCB087A.jpg



MSCB088A.jpg



MSCB089A.jpg



MSCB090A.jpg



MSCB091A.jpg



MSCB092A.jpg



MSCB093A.jpg