

EAST CAROLINA UNIVERSITY

Facility Condition Assessment

Allied Health Sciences Building
Asset AHSB

Inspected April 20, 2016



TABLE OF CONTENTS

SECTION 1 ASSET OVERVIEW

| | |
|---------------------------------|-------|
| Asset Executive Summary..... | 1.1.1 |
| Asset Summary | 1.2.1 |
| Inspection Team Data..... | 1.3.1 |
| Definitions | 1.4.1 |
| Overview | 1.4.1 |
| Recurring Costs | 1.4.2 |
| Nonrecurring Costs | 1.4.3 |
| Drawings/Project Locations..... | 1.4.6 |
| Photographs | 1.4.6 |
| Category Code Report | 1.5.1 |

SECTION 2 COST SUMMARIES AND TOTALS

| | |
|--------------------------------------|-------|
| Renewal Costs Matrix | 2.1.1 |
| Renewal Costs by System | 2.2.1 |
| Facilities Renewal Plan | 2.3.1 |
| Project List by Classification | 2.4.1 |
| Project List by Category Code..... | 2.5.1 |

SECTION 3 NONRECURRING PROJECT DETAILS..... 3.1.1

SECTION 4 LIFECYCLE COMPONENT SUMMARY

| | |
|--|-------|
| Asset Component Inventory..... | 4.1.1 |
| Component Renewal Cost by Year..... | 4.2.1 |
| Recurring Component Expenditure Projections..... | 4.3.1 |

SECTION 5 DRAWINGS/PROJECT LOCATIONS

SECTION 6 PHOTOGRAPHS 6.1.1

FACILITY CONDITION ASSESSMENT

SECTION 1

ASSET OVERVIEW

ASSET EXECUTIVE SUMMARY

All costs shown as Present Value

| | |
|---|---|
| ASSET CODE AHSB | CURRENT REPLACEMENT VALUE \$95,636,000 |
| ASSET NAME ALLIED HEALTH SCIENCES BUILDING | FACILITY CONDITION NEEDS INDEX 0.11 |
| ASSET USE Classroom / Academic | FACILITY CONDITION INDEX 0.00 |
| YEAR BUILT 2006 | 10-YEAR \$/SF 34.65 |
| GSF 303,406 | |
| INSPECTION DATE 04/20/2016 | |


FCNI Scale

The FCNI for this asset is **0.11**

- Excellent Condition (typically new construction)
- Below Average Condition (major renovation required)
- Good Condition (maintained within lifecycle)
- Poor Condition (total renovation required)
- Fair Condition (normal renovations required)
- Replacement Indicated (unless historic)




Total Facility Renewal Costs




Non-Recurring Costs

Project Cost by Priority

| PLANT ADAPTION | |
|------------------|----------|
| 1 - Immediate | \$0 |
| 2 - Critical | \$77,227 |
| 3 - Non-Critical | \$23,483 |




| CORRECTIVE ACTION | |
|-------------------|-------------|
| 1 - Immediate | \$0 |
| 2 - Critical | \$0 |
| 3 - Non-Critical | \$5,930,909 |




Recurring Costs

Component Replacement Cost by Year



Facilities Renewal Cost by System



ASSET SUMMARY

The Allied Health Sciences Building is a four-story, irregular “Z” shaped, 303,406 gross square foot, reinforced concrete and steel framed structure built in 2006. The building is located in the northern section of the East Carolina University Health Sciences campus just west of the north end of Health Sciences Drive. The brick masonry veneer building has a combination of both flat membrane and pitched metal roof areas. The building foundation appears to be a slab on grade. There is no basement or subterranean level associated with this facility.

This medical school facility contains numerous administration and departmental office spaces, a medical library, a number of lecture halls, classrooms, hands-on teaching laboratories, and typical support areas such as a conference rooms, staff and student lounges, public restrooms, a first floor snack bar, mechanical/electrical spaces, and a northern rear shipping and receiving area. There is also a one-bedroom staff apartment located on the third floor of the D Wing with a full bathroom and kitchen.

Information for this report was gathered during a site inspection that concluded on April 20, 2016.

Site

Overall the site is well maintained and visually appealing. The site landscaping is adequate and appropriate for the existing building conditions. Generally the site hardscape, which includes the concrete sidewalks, curbs, and gutter, are in good condition. Several large asphalt parking lots lies adjacent to the north and east sides of the facility with ample parking and sufficient accessible spaces. This asphalt parking lot has surface cracks where if left unattended, will lead to premature failure of the pavement structure. Since these parking areas serve both university-owned and privately-owned medical facilities, they were not included within this facility condition assessment.

Exterior Structure

The existing brick masonry veneer exterior walls from the original 2006 construction exhibit significant moisture penetration around the windows and through the masonry. Numerous areas of the exterior were uncovered and found to have systematic deficiencies throughout. This appears to be a result of improper flashing installation and/or faulty design and construction of the internal wall drainage cavity. A major rehabilitation is recommended of the exterior envelope’s vertical masonry walls, including any window resealing and re-gasketing as necessary to ensure a waterproof exterior envelope. This should include the removal and replacement of the existing deficient flashing within the wall structure at the existing openings and creation of an improved end-damn condition.

The building has a central pitched, blue/grey colored, standing seam metal roof system. There are also some flat perimeter roofs that hare covered with a white, TPO, single-ply membrane application. These flat areas house rooftop mechanical equipment and act as a large gutter to collect rainwater from the pitched roofs and divert it through internal drains. Both are original to 2006 in good condition. The

metal roof shouldn't require upgrades within the next ten years. The TPO single-ply membrane roof is expected to be near the end of its expected service life right around the end of the ten-year window of this assessment. The existing skylights need the flashing to be reworked. Leaks were apparent at numerous locations. Reflash and recaulk/reseal skylights as required, and water-test prior to completion.

The windows located in this facility are either large inoperable, tempered units or dual-pane windows. The windows are typically in good condition and not expected to need any replacements. However, some are exhibiting loose gasket seals and the seals should be repaired or replaced. This issue is addressed in the exterior masonry recommendation.

The building has several main entrances, with the library entrance to the south, and the main medical school entrance to the north, and numerous additional entrances located throughout the first floor for accessing the various wings of the facility. The exterior entrance doors are either aluminum and glass or hollow metal service type door applications. They appear to be original to the building construction and are in good condition. There is one overhead commercial garage door at the southern loading dock. It is also original and in good condition.

Interior Finishes/Systems

The interior finishes within this facility are typically original and generally in good condition. The office suites, lecture halls, conference rooms, and general classrooms within this facility are primarily finished with wall-to-wall carpeted floors, most of which are in good condition. It is anticipated that the carpeted floor areas will need renewal within the next ten years. Areas of higher traffic circulation will always need earlier and more frequent renewal. The laboratory areas have twelve-inch vinyl floor tile, and the training classrooms typically have sheet vinyl flooring. There is a premium slate floor application on the first floor and the second floor southern lobby to the library. There is also premium hardwood flooring in the Historic Collections Reading Room. These floor finishes should remain satisfactory through the next ten years. Painted and sealed concrete floors should be refinished during the next ten years.

The restroom facilities in this building are constructed of ceramic tiled floors and walls with fully accessible fixtures. All of the restrooms are in good condition requiring no upgrades.

Most of the interior walls are painted sheetrock partitions with some papered walls. All should outlast this assessment. There are some lobby areas within the first floor of this facility with premium slate tile wall applications that are also in good condition.

Most ceilings are finished with suspended grid acoustical tile drop ceiling finishes that are also original and in good. Some areas have painted sheetrock applications. All the ceilings should last beyond the timeframe covered by this report. The Historic Collections Reading Room on the fourth floor of the southern E Wing contains a premium ceiling finish with an inset of ceiling tiles molded to suggest a 19th century tin ceiling.

The interior doors are all properly rated and in good condition with accessible lever actuated hardware throughout. The interior glazing is all properly fire and safety rated. No upgrades are necessary for the doors.

The laboratory casework, including the metal casement, are in good condition and not expected to warrant significant improvements. The non-lab casework should also outlast the purview of this assessment. The classroom seating is in acceptable condition and should outlast this report.

Accessibility

The facility was constructed in 2006, years after the ADA legislation was approved into law. Being a public university and this facility being a hands-on classroom and laboratory teaching facility, accessibility was incorporated into the original design with significant access provided throughout the entire facility.

However, one issue was observed that can be improved upon to provide better access. Present legislation pertaining to access within buildings requires that goods and services be generally accessible to all persons. Even though wheelchair access has been provided at the front of the six terraced classrooms on the first floor, the existing stepped aisles along the outer walls do not have the wall rail required for stepped egresses. It is recommended that wall-mounted compliant railings be installed along the side aisles to improve the access to these classrooms.

Health

This facility is equipped with a cold room that supports the research and laboratory programs. The physical structure is in proper working condition, and no recommendations have been developed for this equipment. The refrigeration serving this area is also in proper working condition and has been well maintained. It will be necessary to remove and replace the mechanical equipment at or near the end of this ten-year planning scope.

Fire/Life Safety

Structural fire separations are maintained according to code requirements for new construction in all areas of this facility. The paths of egress in this building are adequate in regard to fire rating. There are no compromises involving doors, partitions, or stairs. No fire or life safety issues related to architectural features were observed during the inspection of this facility.

This facility is equipped with a fire alarm/detection system that utilize a relatively modern point-addressable control panel, manual pull stations, horn strobe signals, smoke/fire detection, and auto communication dialer. This system was in proper working condition at the time of inspection but will require an upgrade near the end of this ten-year planning horizon. At such time, it will be necessary to upgrade the main control panel and annunciator display.

The majority facility is protected with a complete, wet-pipe fire suppression system with a pre-action system serving area E. The stairwells, mechanical penthouses, and main mechanical rooms are equipped with the main fire risers and each landing is equipped with the proper safety valves with tamper switches. This majority of the system including the pre-action compressor, sprinkler heads, valves and tamper switches are in good condition and will require only routine maintenance to remain reliable well beyond the planning horizon of this assessment.

Suite 1512 is the primary data center for this facility. It is currently protected by the wet pipe fire suppression system. It is recommended that this area be equipped with an FM-200 or Inergen based fire suppression system.

The exit signage and egress lighting are a modern, efficient design that is currently in proper working condition. This equipment is connected to the emergency power network that is installed throughout this facility. The egress lighting is a combination of emergency lighting ballasts and twin-sealed fixtures with battery back-up. Statistically, the exit signage and egress lighting should outlast the purview of this report.

HVAC

This facility utilizes chilled water and steam that is provided from the HSC Central Utility Plant. The central steam pressure is reduced through the use of six pressure reducing stations installed in room 1510B. The steam is then converted into heating hot water for distribution throughout the facility via the use of a shell-and-tube heat exchanger. These pressure reducing valves and heat exchanger are well maintained and in proper working condition. With continued maintenance, this equipment will continue to operate reliably beyond the ten year planning phase of this report.

Seventeen air handlers of varying capacity that are equipped with heating and chilled water coils furnish conditioned air through a ducted forced air system that utilizes a variable air volume design. The air handlers are equipped with supply fans and inline/ axial return fan systems. The physical inspection revealed no major deficiencies to this equipment as the air handler and fans have been well maintained. There are no recommendations for the replacement or repair of this equipment at this time.

Four energy recovery units (ERU) with internal enthalpy wheels have been installed that recapture waste exhaust from the restroom facilities located throughout the building. These ERUs reduce energy consumption by acting as an air-to-air heat exchanger through the use of the heat wheel that combines restroom waste exhaust with equipment return air. Additional exhaust air fans are installed for use within the ERUs. This equipment is in good condition, and no recommendations have been developed at this time. Additional facility exhaust is achieved through the use of utility set exhaust fans that are all in proper working condition. There are no recommendations for the exhaust fans at this time.

Supplemental cooling is provided to this facility through the use of four computer room air conditioning units that were manufactured by Data-Air, Inc. and have a maximum supply capacity of 18 tons each. These units provide the conditioned air to the rare books area and main data center. They will reach the end of their statistical lifecycles within the next ten years and are recommended for replacement.

Electric pumps distribute heating and chilled water to the terminal units, air handlers, hydronic units, and computer room air conditioning units installed through the facility. The two heating water and three chilled water pumps identified as HWP-1, HWP-2, CHWP-1, CHWP-2 and PCHW-1 have been very well maintained and are in good working condition. Condensate is captured and redistributed to the central system through the use of a duplex, electric condensate return system and one vacuum condensate system with flash tank that are in good working condition. The vacuum system air compressor is also in proper working condition. With the continued attention to maintenance, these pump systems will remain reliable and serviceable beyond the planning horizon of this assessment.

The HVAC distribution system consisting of ductwork, heating water pipe, chilled water pipe and condensate return pipe is all in good working condition. The ductwork had no visible damage or leaks and the piping systems insulation was all primarily intact. Additionally, the expansion tanks installed to serve the HVAC distribution system are also in good working condition. There are no recommendations for this equipment.

The controls for the HVAC equipment are primarily a direct digital (DDC) design that was manufactured by Siemens. Some pneumatic actuators are in service that are provided control air from an air compressor and associated air dryers located in mechanical space 1510B. The control system and associated mechanical equipment are in proper working condition and should remain reliable and efficient beyond the planning scope of this assessment.

Nine fume hood systems are installed to support the research and laboratory programs within this facility. These fume hoods are in proper working condition and have been well maintained. With continued, diligent maintenance, these units will continue to work reliably beyond the planning horizon of this assessment.

Electrical

Primary electrical service is provided to this facility through the use of two exterior oil-filled transformers and associated pad-mounted selector switch. This equipment has been detailed as part of the High Voltage Utility Report.

Secondary electric power within this building consists of 480/277 and 208Y/120 distribution volt services. Thirty-four dry-type branch transformers of varying capacity reduce the 480 volt service to 120/208 volts. Located in room 1514 is a section of low-voltage switchgear that is installed in a main-tie-main configuration and has a maximum capacity of 3,200 amps. Low-voltage circuit breaker panelboards are installed throughout the building top service occupied spaces and for lighting and system controls. The majority of the HVAC equipment is connected to the 480/227 volt service. The secondary electrical system and main switchgear are all in good working condition and will require only routine operation and maintenance to remain reliable beyond the planning scope of this report. It may be necessary to replace some panelboard circuit breakers, light switches, and electrical outlets over the next ten years, but these small upgrades are more indicative of routine maintenance as opposed to budgeted formal recommendations.

Emergency power is provided to this facility from the central campus emergency power network. Installed within room 1514A are two automatic transfer switches that were manufactured by Cummins and transfer emergency power to the facility in the event of a loss of normal power. These units identified as ATS-EQ and ATS-LS, provide electrical service to life safety and critical equipment installed throughout the facility. These switches are currently in proper working condition and will require only routine maintenance and operation to remain reliable beyond the ten-year planning scope of this assessment.

The mechanical devices serving the HVAC system, including the supply, return, and exhaust fans, are equipped with variable frequency drives (VFDs). There are approximately fifty VFDs that are currently in service within this building. These drives are all currently in proper working condition but will reach the ends of their statistical lifecycles within the ten-year planning scope of this report. At such time, it is recommended that new VFDs be installed. It is also recommended that a staggered or phased replacement program be instituted to mitigate initial costs associated with the replacement of such a large amount of electrical and control equipment.

The interior lighting within this facility consists of a combination of surface-mounted, recessed, and pendant light fixtures that are equipped with T-8 fluorescent lamps, as well as some recessed and sconce fixtures that are equipped with compact fluorescent lamps. As a whole, the lighting system is in good condition and relatively energy efficient. It should outlast the purview of this assessment.

Exterior lighting is provided through the use of a combination of surface-mounted, pole-mounted, recessed, and sconce fixtures. The majority of the surface-mounted, recessed, and sconce fixtures are equipped with CFL lamps, but there are some lamps that utilize HID lamps. These light sources will reach the end of their statistical service lives within the scope of this assessment and are recommended for replacement. The stanchion light fixtures are all in good working condition and should remain reliable beyond the ten-year planning scope of this assessment.

Plumbing

The domestic water supply system within this facility is a soldered copper design and in proper working condition. The wastewater piping system is constructed of cast iron or black steel and is also in proper working condition. No evidence of leaks were identified at the time of inspection, and these systems will require continued maintenance and inspection to remain serviceable beyond the scope of this assessment.

Six backflow preventers (BF) installed within this facility prevent cross-contamination of the domestic, chilled, and heating water systems within this facility and the municipal water service. The two main BF devices are sized at 4 inches and have developed minor calcification on the valve stems. All these devices are original to facility construction and have reached the end of their statistical lifecycles. It is recommended that this equipment be replaced within the planning horizon of this assessment.

Domestic hot water is generated through the use of an unfired heat exchanger and three electric-fired units. All of these water heaters are currently in proper working condition, and no visual damage was identified. The three electric units will require replacement within the scope of this assessment. The

domestic hot water is circulated throughout the building via the use of four circulating pumps. These pumps are in proper working condition, and no recommendations for their replacement have been developed at this time.

The unitary plumbing fixtures installed within men's and women's restrooms throughout this facility include porcelain counter-mounted lavatories with manual hardware, wall-mounted urinals with automatic hardware, and wall-mounted, tankless water closets with automatic hardware. Additionally, the facility is equipped with base-mounted service sinks, a bathtub, and a stainless steel kitchen sink. These plumbing fixtures are all in good working condition and will require only minimal maintenance and repair to remain serviceable beyond the planning scope of this report.

Emergency service equipment installed throughout the building includes eyewash stations, showers, drench hoses, and combination eyewash/shower fixtures. These fixtures are all equipped with dedicated mixing valves and are operated and tested regularly. With this continued dedication and aggressive maintenance practice, these fixtures will remain reliable and serviceable for the next ten years and beyond.

Additional plumbing systems utilized within the laboratory areas of this building include dedicated vacuum and compressed air systems. The duplex, vacuum pump system and air compressor are in good working condition. No recommendation for replacement of this equipment was developed at this time.

Vertical Transportation

This facility is served by four hydraulic elevator systems that were installed in 2006 and are in proper working condition. Passenger elevators C and D are rated for 3,500 pounds each and travel four stops. Passenger elevator B and freight elevator E have a rated capacity of 4,500 pounds each and travel five stops. The hydraulic machines and control systems will require only routine maintenance to remain reliable beyond the planning scope of this report. The passenger elevator cars will require an upgrade within the next ten-years.

Note: The renewal needs outlined in this report were identified from the visual inspection and staff interviews. Our professional architectural and engineering inspectors thoroughly examined the accessible equipment and various building components to determine what repairs or modifications may be necessary to restore the systems and asset to an acceptable condition, or to a level defined by the Client. The estimated costs represent correction of existing deficiencies and anticipated lifecycle failures within a ten-year period. These recommendations are to bring the facility to modern standards without any anticipation of change to facility space layout or function. The total costs include variable project delivery costs as determined by the Owner. The costs developed do not represent the cost of a complete facility renovation. Soft costs not represented in this report include telecommunications, security, furniture, window treatment, space change, program issues, relocation, swing space, contingency, or costs that could not be identified or determined from the visual inspection and available building information.

INSPECTION TEAM DATA

Report Development

ISES Corporation
3100 Breckinridge Boulevard, Suite 400
Duluth, GA 30096

Project Manager

Carl Mason, PE, BSCP, M.ASCE
770.674.3141
carlm@isescorp.com

Date of Inspection

April 15, 2016

Inspection Team Personnel

| NAME | POSITION | SPECIALTY |
|------------------------------|-------------------------|---|
| Rob Camperlino | Facility Assessor | Mechanical, Electrical, Plumbing, Energy, Fire/Life Safety, Health |
| Carl Mason, PE, BSCP, M.ASCE | Senior Project Engineer | Interior Finishes, Exterior Structure, ADA Compliance, Site, Fire/Life Safety, Health |

Client Contact

| NAME | POSITION |
|-----------------|---|
| Griffin L. Avin | Director of Facilities Services, Health Sciences Campus |

DEFINITIONS

The following information is a clarification of the Facility Condition Assessment report using example definitions.

Overview

Recurring and Nonrecurring Facility Renewal Costs

Facility renewal costs are divided into two main categories – recurring and nonrecurring. Recurring costs are cyclical and consist primarily of major repairs to or replacement/rebuilding of facility systems and components (e.g., roof or HVAC system replacement at or past the end of its normal useful life). The tool for projecting the recurring renewal costs is the Asset Component Inventory, which is explained in detail below. Nonrecurring costs typically consist of modifications or repairs necessary to comply with fire/life safety or accessibility code requirements or to address isolated, nonrecurring deficiencies that could negatively affect the structure of the facility or the systems and components within. For these nonrecurring costs, projects have been developed and include estimated material and labor costs.

Facility Condition Needs Index (FCNI)

The FCNI provides a lifecycle cost comparison. It is a ratio of the sum of the recurring and nonrecurring renewal costs over ten years to the current replacement value of the asset. The current replacement value is based on replacement with current construction standards for the facility use type, and not original design parameters. This index gives the university a comparison within all buildings for identifying worst case/best case building conditions.

$$\text{FCNI} = \frac{\text{Nonrecurring Projects} + \text{10-Year Recurring Component Renewal}}{\text{Current Replacement Value}}$$

Facility Condition Index (FCI)

The FCI is a ratio of the Deferred Renewal facilities renewal costs to the current replacement value.

$$\text{FCI} = \frac{\text{Deferred Renewal}}{\text{Current Replacement Value}}$$

Material and Labor Cost Factors and Additional Markups

The project costs are adjusted from the national averages to reflect conditions in Greenville, NC using the R. S. Means City Cost Index for material and labor cost factors. The percentage adjustment of the national average is shown in the table below. Typical general contractor fees (which could include profit, overhead, bonds, and insurance) and professional fees (architect or engineer design fees and in-house design costs) are also included in the renewal costs.

| GLOBAL MARKUP | % |
|---------------------------|-------|
| Local Labor Index | 71.3 |
| Local Materials Index | 100.7 |
| General Contractor Markup | 20.0 |
| Professional Fees | 16.0 |

Recurring Costs

Asset Component Inventory and Cost Projections

The Asset Component Inventory (starting on page 4.1.1) is based on industry standard lifecycle expectancies applied to an inventory of major building systems and major components within a facility. This is a list of all major systems and components within the facility. Each indicated component has the following associated information:

| CATEGORY | DEFINITION |
|----------------------------|---|
| Uniformat Code | The standard Uniformat Code that applies to the component |
| Component Description | This line item describes the individual component |
| Identifier | Unique identifying information entered for a component as necessary |
| Quantity | The quantity of the listed component |
| Units | The unit of measure associated with the quantity |
| Unit Cost | The cost to replace each individual component unit (this cost is in today's dollars) |
| Complexity Adjustment | A factor utilize to adjust component replacement costs accordingly when it is anticipated that the actual cost will deviate from the average for that component |
| Total Cost | Unit cost multiplied by quantity, in today's dollars. Note that this is a one-time renewal/replacement cost |
| Install Date | Year that the component was or is estimated to have been installed. When this data is not available, it defaults to the year the asset was constructed |
| Life Expectancy | Average life expectancy for each individual component |
| Life Expectancy Adjustment | Utilized to adjust the first lifecycle of the component and to express when the next replacement should occur |

The component listing forms the basis of the Recurring Component Renewal Schedule, which provides a year-by-year list of projected recurring renewal costs over the next ten years. Each individual component is assigned a replacement year based on lifecycles, and the costs for each item are in future year dollars. For items that are already past the end of their lifecycle, the replacement year is shown as Deferred Renewal.

For a longer term perspective, the Recurring Component Expenditure Projections Graph presents recurring renewal cost projections over a 50-year period (starting from the date the report is run) based on each individual item's renewal cost and life span. Some components might require renewal several times within the 50-year model, while others might not occur at all. The vertical bars on the graph represent the accumulated total costs for each individual year. The average annual cost per gross square foot (\$/GSF) is shown at the bottom of the graph. In this calculation, costs are not escalated. This figure can be utilized to assess the adequacy of existing capital renewal and repair budgets.

Recurring Cost Classifications

- **Deferred Renewal**
Recurring repairs, generated by the Asset Component Inventory, that are past due for completion but have not yet been accomplished as part of normal maintenance or capital repair efforts. Further deferral of such renewal could impair the proper functioning of the facility. Costs estimated for Deferred Renewal projects should include compliance with applicable codes, even if such compliance requires expenditures beyond those essential to effect the needed repairs.
- **Projected Renewal**
Recurring renewal efforts, generated by the Asset Component Inventory, that will be due within the scope of the assessment. These are regular or normal facility maintenance, repair, or renovation efforts that should be planned in the near future.

Nonrecurring Costs

As previously mentioned, modifications or repairs necessary to comply with fire/life safety or accessibility code requirements and those that address isolated, nonrecurring deficiencies that could negatively affect the structure of the facility or the systems and components within are not included in the Asset Component Inventory. For each such deficiency identified during the facility inspection, a project with an estimated cost to rectify said deficiency is recommended. These projects each have a unique identifier and are categorized by system type, priority, and classification, which are defined below. The costs in these projects are also indexed to local conditions and markups applied as the situation dictates.

Project Number

Each project has a unique number consisting of three elements, the asset identification number, system code, and a sequential number assigned by the FCA software. For example, the third fire/life safety project identified for asset 0001 would have a project number of 0001FS03 (0001 for the asset number, FS for fire/life safety, and 03 being the next sequential number for a fire/life safety project).

Project Classifications

- **Plant/Program Adaption**
Nonrecurring expenditures, stored in the Projects module, required to adapt the physical plant to the evolving needs of the institution and to changing codes or standards. These are expenditures beyond normal maintenance. Examples include compliance with changing codes (e.g., accessibility), facility alterations required by changed teaching or research methods, and improvements occasioned by the adoption of modern technology (e.g., the use of personal computer networks).
- **Corrective Action**
Nonrecurring expenditures, stored in the Projects module, for repairs needed to correct random and unpredictable deficiencies. Such projects are not related to aligning a building with codes or standards. Deficiencies classified as Corrective Action could have an effect on building aesthetics, safety, or usability.

Priority Classes

Recurring renewal needs do not receive individual prioritization, as the entire data set of needs in this category is year-based. Each separate component has a distinct need year, rendering further prioritization unnecessary. Each nonrecurring renewal project, however, has a priority assigned to indicate the criticality of the recommended work. The prioritization utilized for this subset of the data is as follows.

- **Immediate**
Projects in this category require immediate action to:
 - a. correct a cited safety hazard
 - b. stop accelerated deterioration
 - c. and/or return a facility to normal operation

- **Critical**

Projects in this category include actions that must be addressed in the short-term:

- a. repairs to prevent further deterioration
- b. improvements to facilities associated with critical accessibility needs
- c. potential safety hazards

- **Noncritical**

Projects in this category include:

- a. improvements to facilities associated with noncritical accessibility needs
- b. actions to bring a facility into compliance with current building codes as grandfather clauses expire
- c. actions to improve the usability of a facility following an occupancy or use change

Category Codes

| CATEGORY CODE* | SYSTEM DESCRIPTION |
|----------------|---------------------------|
| AC1A – AC4B | ACCESSIBILITY |
| EL1A – EL8A | ELECTRICAL |
| ES1A – ES6E | EXTERIOR STRUCTURE |
| FS1A – FS6A | FIRE/LIFE SAFETY |
| HE1A – HE7A | HEALTH |
| HV1A – HV8B | HVAC |
| IS1A – IS6D | INTERIOR FINISHES/SYSTEMS |
| PL1A – PL5A | PLUMBING |
| SI1A – SI4A | SITE |
| SS1A – SS7A | SECURITY SYSTEMS |
| VT1A – VT7A | VERTICAL TRANSPORTATION |

| <i>Example:</i> Category Code = EL5A | |
|---|-----------------------|
| EL | System Description |
| 5 | Component Description |
| A | Element Description |

*Refer to the Category Code Report starting on page 1.5.1.

Priority Sequence

A Priority Sequence number is automatically assigned to each project to rank the projects in order of relative criticality and show the recommended execution order. This number is calculated based on the Priority Class and identified system of each project.

Example:

| Priority Class | Category Code | Project Number | Priority Sequence |
|----------------|---------------|----------------|-------------------|
| 1 | HV2C | 0001HV04 | 01 |
| 1 | PL1D | 0001PL02 | 02 |
| 2 | IS1E | 0001IS06 | 03 |
| 2 | EL4C | 0001EL03 | 04 |

Project Subclass Type

- **Energy Conservation**
Projects with energy conservation opportunities, based on simple payback analysis.

Drawings/Project Locations

The drawings for this facility are marked with icons (see legend on plans) denoting the specific location(s) for each project. Within each icon are the last four characters of the respective project number (e.g., 0001IS01 is marked on the plan as IS01).

Photographs

A code shown on the Photo Log identifies the asset number, photo sequence, and a letter designation for architect (a) or engineer (e).

| <i>Example:</i> Photo Number: 0001006e | |
|---|-------------------|
| 0001 | Asset Number |
| 006 | Photo Sequence |
| e | Engineering Photo |

CATEGORY CODE REPORT

ACCESSIBILITY

| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
|------|-------------------------|--------------------------------|---|
| AC1A | Site | Stair and Railings | Includes exterior stairs and railings which are not part of the building entrance points. |
| AC1B | Site | Ramps and Walks | Includes sidewalks, grade change ramps (except for a building entrance), curb ramps, etc. |
| AC1C | Site | Parking | Designated parking spaces, including striping, signage, access aisles and ramps, etc. |
| AC1D | Site | Tactile Warnings | Raised tactile warnings located at traffic crossing and elevation changes. |
| AC2A | Building Entry | General | Covers all aspects of entry into the building itself, including ramps, lifts, doors and hardware, power operators, etc. |
| AC3A | Interior Path of Travel | Lifts/Ramps/Elevators | Interior lifts, ramps and elevators designed to accommodate level changes inside a building. Includes both installation and retrofitting. |
| AC3B | Interior Path of Travel | Stairs and Railings | Upgrades to interior stairs and handrails for accessibility reasons. |
| AC3C | Interior Path of Travel | Doors and Hardware | Accessibility upgrades to the interior doors including widening, replacing hardware power, assisted operators, etc. |
| AC3D | Interior Path of Travel | Signage | Interior building signage upgrades for compliance with the ADA. |
| AC3E | Interior Path of Travel | Restrooms/Bathrooms | Modifications to and installation of accessible public restrooms and bathrooms. Bathrooms that are an integral part of residential suites are catalogued under HC4A. |
| AC3F | Interior Path of Travel | Drinking Fountains | Upgrading/replacing drinking fountains for reasons of accessibility. |
| AC3G | Interior Path of Travel | Phones | Replacement/modification of public access telephones. |
| AC4A | General | Functional Space Modifications | This category covers all necessary interior modifications necessary to make the services and functions of a building accessible. It includes installation of assistive listening systems, modification of living quarters, modifications to laboratory workstations, etc. Bathrooms that are integral to efficiency suites are catalogued here. |
| AC4B | General | Other | All accessibility issues not catalogued elsewhere. |

ELECTRICAL

| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
|------|--------------------------|------------------------|--|
| EL1A | Incoming Service | Transformer | Main building service transformer. |
| EL1B | Incoming Service | Disconnects | Main building disconnect and switchgear. |
| EL1C | Incoming Service | Feeders | Incoming service feeders. Complete incoming service upgrades, including transformers, feeders, and main distribution panels are catalogued here. |
| EL1D | Incoming Service | Metering | Installation of meters to record consumption and/or demand. |
| EL2A | Main Distribution Panels | Condition Upgrade | Main distribution upgrade due to deficiencies in condition. |
| EL2B | Main Distribution Panels | Capacity Upgrade | Main distribution upgrades due to inadequate capacity. |
| EL3A | Secondary Distribution | Step-Down Transformers | Secondary distribution step-down and isolation transformers. |
| EL3B | Secondary Distribution | Distribution Network | Includes conduit, conductors, sub-distribution panels, switches, outlets, etc. Complete interior rewiring of a facility is catalogued here. |

| | | | |
|------|------------------------|---------------------------|---|
| EL3C | Secondary Distribution | Motor Controllers | Mechanical equipment motor starters and control centers. |
| EL4A | Devices and Fixtures | Exterior Lighting | Exterior building lighting fixtures, including supply conductors and conduit. |
| EL4B | Devices and Fixtures | Interior Lighting | Interior lighting fixtures (also system wide emergency lighting), including supply conductors and conduits. |
| EL4C | Devices and Fixtures | Lighting Controllers | Motion sensors, photocell controllers, lighting contactors, etc. |
| EL4D | Devices and Fixtures | GFCI Protection | Ground fault protection, including GFCI receptacles and breakers. |
| EL4E | Devices and Fixtures | Lightning Protection | Lightning arrestation systems including air terminals and grounding conductors. |
| EL5A | Emergency Power System | Generation/ Distribution | Includes generators, central battery banks, transfer switches, emergency power grid, etc. |
| EL6A | Systems | UPS/DC Power Supply | Uninterruptible power supply systems and DC motor-generator sets and distribution systems. |
| EL7A | Infrastructure | Above Ground Transmission | Includes poles, towers, conductors, insulators, fuses, disconnects, etc. |
| EL7B | Infrastructure | Underground Transmission | Includes direct buried feeders, duct banks, conduit, manholes, feeders, switches, disconnects, etc. |
| EL7C | Infrastructure | Substations | Includes incoming feeders, breakers, buses, switchgear, meters, CTs, PTs, battery systems, capacitor banks, and all associated auxiliary equipment. |
| EL7D | Infrastructure | Distribution Switchgear | Stand-alone sectionalizing switches, distribution switchboards, etc. |
| EL7F | Infrastructure | Area and Street Lighting | Area and street lighting systems, including stanchions, fixtures, feeders, etc. |
| EL8A | General | Other | Electrical system components not catalogued elsewhere. |

EXTERIOR STRUCTURE

| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
|------|-------------------------|-----------------------------|--|
| ES1A | Foundation/ Footing | Structure | Structural foundation improvements involving structural work on foundation wall/footing, piers, caissons, and piles, including crack repairs, shoring, and pointing |
| ES1B | Foundation/ Footing | Dampproofing/ Dewatering | Foundation/footing waterproofing work, including, damp-proofing, dewatering, insulation, etc. |
| ES2A | Columns/Beams/ Walls | Structure | Structural work to primary load-bearing structural components aside from floors, including columns, beams, bearing walls, lintels, arches, etc. |
| ES2B | Columns/Beams/ Walls | Finish | Work involving restoration of the appearance and weatherproof integrity of exterior wall/structural envelope components, including masonry/pointing, expansion joints, efflorescence and stain removal, grouting, surfacing, chimney repairs, etc. |
| ES3A | Floor | Structure | Work concerning the structural integrity of the load supporting floors, both exposed and unexposed, including deformation, delamination, spalling, shoring, crack repair, etc. |
| ES4A | Roof | Repair | Work on waterproof horizontal finish (roof) involving repair and/or limited replacement (<40% total), including membrane patching, flashing repair, coping caulk/resetting, PPT wall parging/coating, walk pad installation, skylight and roof hatch R&R, etc. |
| ES4B | Roof | Replacement | Work involving total refurbishment of roofing system, including related component rehab. |
| ES5A | Fenestrations | Doors | Work on exterior exit/access door, including storefronts, airlocks, air curtains, vinyl slat doors, all power/manual operating hardware (except handicapped), etc. |
| ES5B | Fenestrations | Windows | Work on exterior fenestration closure and related components, including glass/metal/wood curtain walls, fixed or operable window sashes, glazing, frames, sills, casings, stools, seats, coatings, treatments, screens, storm windows, etc. |

| | | | |
|------|---------|--------------------|--|
| ES6A | General | Attached Structure | Work on attached exterior structure components not normally considered in above categories, including porches, stoops, decks, monumental entrance stairs, cupolas, tower, etc. |
| ES6B | General | Areaways | Work on attached grade level or below structural features, including subterranean lightwells, areaways, basement access stairs, etc. |
| ES6C | General | Trim | Work on ornamental exterior (generally nonstructural) elements, including beltlines, quoins, porticos, soffits, cornices, moldings, trim, etc. |
| ES6D | General | Superstructure | Finish and structural work on nonstandard structures with exposed load-bearing elements, such as stadiums, bag houses, bleachers, freestanding towers, etc. |
| ES6E | General | Other | Any exterior work not specifically categorized elsewhere, including finish and structural work on freestanding boiler stacks. |

| FIRE/LIFE SAFETY | | | |
|------------------|-----------------------|------------------------------|--|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| FS1A | Lighting | Egress Lighting/Exit Signage | R&R work on exit signage and packaged AC/DC emergency lighting. |
| FS2A | Detection/Alarm | General | Repair or replacement of fire alarm/detection system/components, including alarms, pull boxes, smoke/heat detectors, annunciator panels, central fire control stations, remote dialers, fire station communications, etc. |
| FS3A | Suppression | Sprinklers | Repair or installation of water sprinkler type automatic fire suppressions, including wet-pipe and dry-pipe systems, heads, piping, deflectors, valves, monitors, associated fire pump, etc. |
| FS3B | Suppression | Standpipe/Hose | Repair or installation of standpipe system or components, including hardware, hoses, cabinets, nozzles, necessary fire pumping system, etc. |
| FS3C | Suppression | Extinguishers | Repairs or upgrades to F.E. cabinets/wall fastenings and handheld extinguisher testing/replacement. |
| FS3D | Suppression | Other | Other fire suppression items not specifically categorized elsewhere, including fire blankets, carbon dioxide automatic systems, Halon systems, dry chemical systems, etc. |
| FS4A | Hazardous Materials | Storage Environment | Installation or repair of special storage environment for the safe holding of flammable or otherwise dangerous materials/supplies, including vented flammables storage cabinets, holding pens/rooms, cages, fire safe chemical storage rooms, etc. |
| FS4B | Hazardous Materials | User Safety | Improvements, repairs, installation, or testing of user safety equipment, including emergency eyewashes, safety showers, emergency panic/shut-down system, etc. |
| FS5A | Egress Path | Designation | Installation, relocation or repair of posted diagrammatic emergency evacuation routes. |
| FS5B | Egress Path | Distance/Geometry | Work involving remediation of egress routing problems, including elimination of dead end corridors, excessive egress distance modifications, and egress routing inadequacies. |
| FS5C | Egress Path | Separation Rating | Restoration of required fire protective barriers, including wall rating compromises, fire-rated construction, structural fire proofing, wind/safety glazing, transom retrofitting, etc. |
| FS5D | Egress Path | Obstruction | Clearance of items restricting the required egress routes. |
| FS5E | Egress Path | Stairs Railing | Retrofit of stair/landing configurations/structure, railing heights/geometries, etc. |
| FS5F | Egress Path | Fire Doors/Hardware | Installation/replacement/repair of fire doors and hardware, including labeled fire doors, fire shutters, closers, magnetic holders, panic hardware, etc. |
| FS5G | Egress Path | Finish/Furniture Ratings | Remediation of improper fire/smoke ratings of finishes and furniture along egress routes. |
| FS6A | General | Other | Life/fire safety items not specifically categorized elsewhere. |

| HEALTH | | | |
|--------|-----------------------|--------------------------|--|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| HE1A | Environmental Control | Equipment and Enclosures | Temperature control chambers (both hot and cold) for non-food storage. Includes both chamber and all associated mechanical equipment. |
| HE1B | Environmental Control | Other | General environmental control problems not catalogued elsewhere. |
| HE2A | Pest Control | General | Includes all measures necessary to control and destroy insects, rodents, and other pests. |
| HE3A | Refuse | General | Issues related to the collection, handling, and disposal of refuse. |
| HE4A | Sanitation Equipment | Laboratory and Process | Includes autoclaves, cage washers, steam cleaners, etc. |
| HE5A | Food Service | Kitchen Equipment | Includes ranges, grilles, cookers, sculleries, etc. |
| HE5B | Food Service | Cold Storage | Includes the cold storage room and all associated refrigeration equipment. |
| HE6A | Hazardous Material | Structural Asbestos | Testing, abatement, and disposal of structural and building finish materials containing asbestos. |
| HE6B | Hazardous Material | Mechanical Asbestos | Testing, abatement, and disposal of mechanical insulation materials containing asbestos. |
| HE6C | Hazardous Material | PCBs | Includes testing, demolition, disposal, and cleanup of PCB contaminated substances. |
| HE6D | Hazardous Material | Fuel Storage | Includes monitoring, removal, and replacement of above and below ground fuel storage and distribution systems. Also includes testing and disposal of contaminated soils. |
| HE6E | Hazardous Material | Lead Paint | Testing, removal, and disposal of lead-based paint systems. |
| HE6F | Hazardous Material | Other | Handling, storage, and disposal of other hazardous materials. |
| HE7A | General | Other | Health related issues not catalogued elsewhere. |

| HVAC | | | |
|------|-----------------------|------------------------------|---|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| HV1A | Heating | Boilers/Stacks/Controls | Boilers for heating purposes, including their related stacks, flues, and controls. |
| HV1B | Heating | Radiators/Convectors | Including cast-iron radiators, fin tube radiators, baseboard radiators, etc. |
| HV1C | Heating | Furnace | Furnaces and their related controls, flues, etc. |
| HV1D | Heating | Fuel Supply/Storage | Storage and/or distribution of fuel for heating purposes, including tanks and piping networks and related leak detection/monitoring. |
| HV2A | Cooling | Chillers/Controls | Chiller units for production of chilled water for cooling purposes, related controls (not including mods for CFC compliance). |
| HV2B | Cooling | Heat Rejection | Repair/replacement of cooling towers, dry coolers, air-cooling, and heat rejection. Includes connection of once-through system to cooling tower. |
| HV3A | Heating/Cooling | System Retrofit/Replace | Replacement or major retrofit of HVAC systems. |
| HV3B | Heating/Cooling | Water Treatment | Treatment of hot water, chilled water, steam, condenser water, etc. |
| HV3C | Heating/Cooling | Package/Self-Contained Units | Repair/replacement of self-contained/package type units, including stand-up units, rooftop units, window units, etc.; both air conditioners and heat pumps. |
| HV3D | Heating/Cooling | Conventional Split Systems | Repair, installation, or replacement of conventional split systems, both air conditioners and heat pumps, including independent component replacements of compressors and condensers. |

| | | | |
|------|--------------------------------|-----------------------------------|---|
| HV4A | Air Moving/ Ventilation | Air Handlers/ Fan Units | Includes air handlers and coils, fan coil units, unit ventilators, filtration upgrades, etc., not including package/self-contained units, split systems, or other specifically categorized systems. |
| HV4B | Air Moving/ Ventilation | Exhaust Fans | Exhaust fan systems, including fans, range and fume hoods, controls, and related ductwork. |
| HV4C | Air Moving/ Ventilation | Other Fans | Supply, return, or any other fans not incorporated into a component categorized elsewhere. |
| HV4D | Air Moving/ Ventilation | Air Distribution Network | Repair, replacement, or cleaning of air distribution network, including ductwork, terminal reheat/cool, VAV units, induction units, power induction units, insulation, dampers, linkages, etc. |
| HV5A | Steam/Hydronic Distribution | Piping Network | Repair/replacement of piping networks for heating and cooling systems, including pipe, fittings, insulation, related components, etc. |
| HV5B | Steam/Hydronic Distribution | Pumps | Repair or replacement of pumps used in heating and cooling systems, related control components, etc. |
| HV5C | Steam/Hydronic Distribution | Heat Exchangers | Including shell-and-tube heat exchangers and plate heat exchangers for heating and cooling. |
| HV6A | Controls | Complete System Upgrade | Replacement of HVAC control systems. |
| HV6B | Controls | Modifications/ Repairs | Repair or modification of HVAC control system. |
| HV6C | Controls | Air Compressors/ Dryers | Repair or modification of control air compressors and dryers. |
| HV7A | Infrastructure | Steam/Hot Water Generation | Generation of central steam and/or hot water, including boilers and related components. |
| HV7B | Infrastructure | Steam/Hot Water Distribution | Distribution system for central hot water and/or steam. |
| HV7C | Infrastructure | Chilled Water Generation | Generation of central chilled water, including chillers and related components. |
| HV7D | Infrastructure | Chilled Water Distribution | Distribution system for central chilled water. |
| HV7E | Infrastructure | Tunnels/ Manholes/ Trenches | Repairs, installation, or replacement of utility system access chambers. |
| HV7F | Infrastructure | Other | HVAC infrastructure issues not specifically categorized elsewhere. |
| HV8A | General | CFC Compliance | Chiller conversions/replacements for CFC regulatory compliance, monitoring, etc. |
| HV8B | General | Other | HVAC issues not catalogued elsewhere. |

INTERIOR FINISHES/SYSTEMS

| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
|------|--------------------------|------------------------|--|
| IS1A | Floor | Finishes-Dry | R&R of carpet, hardwood strip flooring, concrete coating, vinyl linoleum and tile, marble, terrazzo, rubber flooring, and underlayment in predominantly dry areas ("dry" includes non-commercial kitchens) |
| IS1B | Floor | Finishes-Wet | Flooring finish/underlayment work in predominantly "wet" areas, including work with linoleum, rubber, terrazzo, concrete coating, quarry tile, ceramic tile, epoxy aggregate, etc. |
| IS2A | Partitions | Structure | Structural work on full height permanent interior partitions, including wood/metal stud and drywall systems, CMU systems, structural brick, tile, glass block, etc. |
| IS2B | Partitions | Finishes | Work on full height permanent interior partitions, including R&R, to gypsum board, plaster, lath, wood paneling, acoustical panels, wall coverings, column coverings, tile, paint, etc. |
| IS3A | Ceilings | Repair | Repair of interior ceilings (<40% of total), including tiles, gypsum board, plaster, paint, etc. |
| IS3B | Ceilings | Replacement | Major refurbishments (>40% of total) to interior ceiling systems, including grid system replacements, structural framing, new suspended systems, paint, plastering, etc. |

| | | | |
|------|---------|-----------|---|
| IS4A | Doors | General | Any work on interior non-fire-rated doors, roll-up counter doors, mechanical/plumbing access doors, and all door hardware (except for reasons of access improvement). |
| IS5A | Stairs | Finish | Any finish restorative work to stair tower walking surfaces, including replacement of rubber treads, safety grips, nosings, etc. (except as required to accommodate disabled persons). |
| IS6A | General | Molding | R&R to interior trim/molding systems, including rubber/vinyl/wood base, crown/chair/ornamental moldings, cased openings, etc. |
| IS6B | General | Cabinetry | R&R work to interior casework systems, including cabinets, countertops, wardrobes, lockers, mail boxes, built-in bookcases, lab/work benches, reagent shelving, etc. (except as required for access by the disabled). |
| IS6C | General | Screening | Work on temporary or partial height partitioning systems, including toilet partitions, urinal/vanity screens, etc. |
| IS6D | General | Other | Any work on interior elements not logically or specifically categorized elsewhere, including light coves, phone booths, interior lightwells, etc. |

| PLUMBING | | | |
|----------|-----------------------|--|---|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| PL1A | Domestic Water | Piping Network | Repair or replacement of domestic water supply piping network, insulation, hangers, etc. |
| PL1B | Domestic Water | Pumps | Domestic water booster pumps, circulating pumps, related controls, etc. |
| PL1C | Domestic Water | Storage/ Treatment | Equipment or vessels for storage or treatment of domestic water. |
| PL1D | Domestic Water | Metering | Installation, repair, or replacement of water meters. |
| PL1E | Domestic Water | Heating | Domestic water heaters, including gas, oil, and electric water heaters, shell-and-tube heat exchangers, tank type, and instantaneous. |
| PL1F | Domestic Water | Cooling | Central systems for cooling and distributing drinking water. |
| PL1G | Domestic Water | Fixtures | Plumbing fixtures, including sinks, drinking fountains, water closets, urinals, etc. |
| PL1H | Domestic Water | Conservation | Alternations made to the water distribution system to conserve water. |
| PL1I | Domestic Water | Backflow Protection | Backflow protection devices, including backflow preventers, vacuum breakers, etc. |
| PL2A | Wastewater | Piping Network | Repair or replacement of building wastewater piping network. |
| PL2B | Wastewater | Pumps | Pump systems used to lift wastewater, including sewage ejectors and other sump systems. |
| PL3A | Special Systems | Process Gas/Fluids | Generation and/or distribution of process steam, compressed air, natural and LP gas, process water, vacuum, etc. |
| PL4A | Infrastructure | Potable Water Storage/ Treatment | Storage and treatment of potable water for distribution. |
| PL4B | Infrastructure | Industrial Water Distribution/ Treatment | Storage and treatment of industrial water for distribution. |
| PL4C | Infrastructure | Sanitary Water Collection | Sanitary water collection systems and sanitary sewer systems, including combined systems. |
| PL4D | Infrastructure | Stormwater Collection | Stormwater collection systems and storm sewer systems; storm water only. |
| PL4E | Infrastructure | Potable Water Distribution | Potable water distribution network. |
| PL4F | Infrastructure | Wastewater Treatment | Wastewater treatment plants, associated equipment, etc. |
| PL5A | General | Other | Plumbing issues not categorized elsewhere. |

| SITE | | | |
|------|-----------------------|---------------------|--|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| SI1A | Access | Pedestrian | Paved pedestrian surfaces, including walks, site stairs, step ramps, paths, pedestrian signage, sidewalk bridges/canopies, pedestrian plaza/mall areas, etc. |
| SI1B | Access | Vehicular | Paved vehicular surfaces, including roads, paths, curbs, guards, bollards, bridges, skyways, joints, shoulder work, culverts, ditches, vehicular signage, etc. |
| SI2A | Landscape | Grade/Flora | Landscape related work, including new grass/turf refurbishment, grade improvements, catch basins, swales, berms, pruning, new ornamental flora, etc. |
| SI3A | Hardscape | Structure | Permanent hard site features, predominantly ornamental, including terraces, fences, statues, freestanding signage, fountains, benches, etc. |
| SI4A | General | Other | Other site work not specifically categorized elsewhere. |

| SECURITY SYSTEMS | | | |
|------------------|-----------------------|---------------------|---|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| SS1A | Lighting | Exterior | Fixtures, stanchions, foliage interference, cleanliness, locations, etc. |
| SS2A | Site | Fencing | Perimeter campus fencing, individual building fencing, includes both pedestrian and vehicular control fences. |
| SS2B | Site | General | Hidden areas due to foliage, fencing, parking, walls, etc. |
| SS3A | Communications | Emergency Phones | Access, locations, visibility, function, reliability, etc. |
| SS4A | Access Control | Doors | Access, locks, keys, two-way speakers, reliability, redundancy, etc. |
| SS4B | Access Control | Windows | Locks, screens, access, reliability, etc. |
| SS4C | Access Control | Systems | Card key, proximity devices, data control, data use, reliability, system design, etc. |
| SS5A | Monitoring | Systems | Cameras, audio communication, monitoring stations, locations, system design, etc. |
| SS6A | Circulation | Pedestrian | On campus as well as to and from off-campus housing and class locations, etc. |
| SS6B | Circulation | Vehicular | Guard gates, access, systems, data control and use, identification, etc. |
| SS7A | General | Other | General information/projects pertaining to security issues. |

| VERTICAL TRANSPORTATION | | | |
|-------------------------|-----------------------|---------------------|---|
| CODE | Component Description | Element Description | DEFINITION |
| VT1A | Machine Room | General | Machine, worm gear, thrust bearing, brake, motors, sheaves, generator, controller, selector, governor, pump(s), valves, oil, access, lighting, ventilation, and floor. |
| VT2A | Car | General | Position indicator, lighting, floor, gate-doors, operation devices, safeties, safety shoe, light ray/detection, emergency light, fire fighter service, car top, door operator, stop switch, car frame, car guides, sheaves, phone, and ventilation. |
| VT3A | Hoistway | General | Enclosure, fascia, interlock, doors, hangers, closers, sheaves, rails, hoistway switches, ropes, traveling cables, selector tape, weights, and compensation. |
| VT4A | Hall Fixtures | General | Operating panel, position indicator, hall buttons, lobby panel, hall lanterns, fire fighter service, audible signals, and card/key access. |
| VT5A | Pit | General | Buffer(s), guards, sheaves, hydro packing, floor, lighting, and safety controls. |
| VT6A | Operating Conditions | General | Door open time, door close time, door thrust, acceleration, deceleration, leveling, dwell time, speed, OFR time, and nudging. |
| VT7A | General | Other | General information/projects relating to vertical transportation system components. |

FACILITY CONDITION ASSESSMENT

SECTION 2

COST SUMMARIES
AND TOTALS

RENEWAL COSTS MATRIX

All dollars shown as Present Value

| CATEGORY | NON-RECURRING PROJECT NEEDS | | | RECURRING COMPONENT REPLACEMENT NEEDS | | | | | | | | | | | |
|--|-----------------------------|-----------------|--------------------|--|----------------|------------|--------------------|------------|------------------|------------------|------------------|----------------|--------------------|--------------------|---------------------|
| | Immediate | Critical | Non-Critical | Deferred Renewal | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | TOTAL |
| ACCESSIBILITY | 0 | 77,227 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | \$77,227 |
| EXTERIOR | 0 | 0 | 5,930,909 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 157,491 | 0 | \$6,088,399 |
| INTERIOR | 0 | 0 | 0 | 0 | 0 | 0 | 1,711,495 | 0 | 892,165 | 32,623 | 0 | 0 | 0 | 0 | \$2,636,283 |
| PLUMBING | 0 | 0 | 0 | 0 | 2,154 | 0 | 0 | 0 | 0 | 21,499 | 0 | 1,455 | 0 | 0 | \$25,108 |
| HVAC | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 151,525 | 0 | 0 | 0 | 0 | \$151,525 |
| FIRE/LIFE SAFETY | 0 | 0 | 23,483 | 0 | 0 | 0 | 0 | 0 | 0 | 33,484 | 0 | 0 | 1,018,268 | 0 | \$1,075,235 |
| ELECTRICAL | 0 | 0 | 0 | 0 | 0 | 0 | 109,919 | 0 | 0 | 31,657 | 168,126 | 0 | 0 | 0 | \$309,702 |
| SITE | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | \$0 |
| VERT. TRANS. | 0 | 0 | 0 | 0 | 0 | 0 | 141,360 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | \$141,360 |
| HEALTH/EQUIP. | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8,585 | 0 | \$8,585 |
| SUBTOTAL | \$0 | \$77,227 | \$5,954,392 | \$0 | \$2,154 | \$0 | \$1,962,775 | \$0 | \$892,165 | \$270,788 | \$168,126 | \$1,455 | \$1,184,343 | \$0 | \$10,513,424 |
| TOTAL NON-RECURRING PROJECT NEEDS | | | \$6,031,619 | TOTAL RECURRING COMPONENT REPLACEMENT NEEDS | | | | | | | | | | \$4,481,806 | |

| | |
|---------------------------------------|---------------------|
| CURRENT REPLACEMENT VALUE | \$95,636,000 |
| FACILITY CONDITION NEEDS INDEX | 0.11 |
| FACILITY CONDITION INDEX | 0.00 |

| | | |
|----------------|---|-------------------------|
| GSF | TOTAL 10-YEAR FACILITY RENEWAL NEEDS | 10-YEAR NEEDS/SF |
| 303,406 | \$10,513,424 | \$34.65 |

RENEWAL COSTS BY SYSTEM

All costs shown as Present Value

| CATEGORY | NON-RECURRING ASSESSMENT RECOMENDATON | RECURRING COMPONENT REPLACEMENT COSTS | TOTAL 10-YEAR FACILITY RENEWAL COSTS |
|------------------|---|---|--|
| ACCESSIBILITY | \$77,227 | \$0 | \$77,227 |
| EXTERIOR | \$5,930,909 | \$157,491 | \$6,088,399 |
| INTERIOR | \$0 | \$2,636,283 | \$2,636,283 |
| PLUMBING | \$0 | \$25,108 | \$25,108 |
| HVAC | \$0 | \$151,525 | \$151,525 |
| FIRE/LIFE SAFETY | \$23,483 | \$1,051,752 | \$1,075,235 |
| ELECTRICAL | \$0 | \$309,702 | \$309,702 |
| SITE | \$0 | \$0 | \$0 |
| VERT. TRANS | \$0 | \$141,360 | \$141,360 |
| HEALTH | \$0 | \$8,585 | \$8,585 |
| TOTALS | \$6,031,619 | \$4,481,806 | \$10,513,424 |

FACILITIES RENEWAL PLAN

NON-RECURRING PROJECT COST

All costs shown as Present Value

| PROJECT NUMBER | PROJECT TITLE | UNI-FORMAT | PRIORITY CLASS | PROJECT CLASSIFICATION | PROJECT COST |
|----------------|---|------------|----------------|------------------------|--------------------|
| AHSBAC01 | TIERED CLASSROOM ACCESSIBILITY UPGRADES | C1010 | 2 | Plant Adaption | 77,227 |
| AHSBFS01 | INSTALL FM-200 OR INERGEN SYSTEM IN DATA CENTER | | 3 | Plant Adaption | 23,483 |
| AHSBES01 | EXTERIOR MASONRY AND CONCRETE VENEER RENEWAL | B2010 | 3 | Corrective Action | 5,918,937 |
| AHSBES02 | REFLASH AND RESEAL SKYLIGHTS | B2010 | 3 | Corrective Action | 11,971 |
| TOTAL | | | | | \$6,031,619 |

FACILITIES RENEWAL PLAN

RECURRING COMPONENT REPLACEMENT COSTS

All costs shown as Present Value

| ASSET CODE COMP CODE | COMPONENT | IDENTIFIER | UNI- FORMAT | REPLACEMENT YEAR | REPLACEMENT COST |
|-------------------------|--|---------------------------------|----------------|---------------------|---------------------|
| AHSB WH22 | WATER HEATER - RESIDENTIAL, ELECTRIC (15-25 GAL) | TAN-001 | D2020 | 2016 | 1,077 |
| AHSB WH22 | WATER HEATER - RESIDENTIAL, ELECTRIC (15-25 GAL) | TAN-002 | D2020 | 2016 | 1,077 |
| AHSB IF01 | FLOORING - CARPET, TILE OR ROLL, STANDARD | OFC, HALL, CONF RM, CLASSRMS | C3020 | 2018 | 1,711,495 |
| AHSB VT04 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR B | D1010 | 2018 | 47,120 |
| AHSB VT04 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR C | D1010 | 2018 | 47,120 |
| AHSB VT04 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR D | D1010 | 2018 | 47,120 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-1C | D5010 | 2018 | 1,239 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-1E | D5010 | 2018 | 1,859 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU1-2 | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU1-3 | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU2-2 | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU2-3 | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU3-2 | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU3-3 | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU4-2 | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU4-3 | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-3E | D5010 | 2018 | 3,099 |
| AHSB VF01 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-4E | D5010 | 2018 | 3,099 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3AB | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1AB | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2CD | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-4CD | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3C | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1D1 | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-4D2 | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3D | D5010 | 2018 | 2,810 |

FACILITIES RENEWAL PLAN
 RECURRING COMPONENT REPLACEMENT COSTS

All costs shown as Present Value

| ASSET CODE COMP CODE | COMPONENT | IDENTIFIER | UNI- FORMAT | REPLACEMENT YEAR | REPLACEMENT COST |
|-------------------------|--|----------------|----------------|---------------------|---------------------|
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2D2 | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1DE | D5010 | 2018 | 2,810 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | EF-1 | D5010 | 2018 | 4,496 |
| AHSB VF02 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2E | D5010 | 2018 | 4,496 |
| AHSB VF03 | VARIABLE FREQUENCY DRIVE (7.5-10 HP) | RAF-4B | D5010 | 2018 | 3,749 |
| AHSB VF03 | VARIABLE FREQUENCY DRIVE (7.5-10 HP) | RAF-2B | D5010 | 2018 | 4,687 |
| AHSB VF04 | VARIABLE FREQUENCY DRIVE (10-15 HP) | SAF-1E | D5010 | 2018 | 5,425 |
| AHSB VF05 | VARIABLE FREQUENCY DRIVE (15-20 HP) | EF-2 | D5010 | 2018 | 4,977 |
| AHSB VF05 | VARIABLE FREQUENCY DRIVE (15-20 HP) | HWP-1 | D5010 | 2018 | 6,636 |
| AHSB VF05 | VARIABLE FREQUENCY DRIVE (15-20 HP) | HWP-2 | D5010 | 2018 | 6,636 |
| AHSB VF05 | VARIABLE FREQUENCY DRIVE (15-20 HP) | SAF-4E | D5010 | 2018 | 6,636 |
| AHSB IW01 | WALL FINISH - PAINT, STANDARD | THROUGHOUT | C3010 | 2020 | 892,165 |
| AHSB IF15 | FLOORING - FLUID APPLIED, PAINT OR CLEAR SEAL | CONCRETE SLABS | C3020 | 2021 | 32,623 |
| AHSB BF01 | BACKFLOW PREVENTER (<=1 INCH) | BFP-003 | D2020 | 2021 | 928 |
| AHSB BF01 | BACKFLOW PREVENTER (<=1 INCH) | BFP-005 | D2020 | 2021 | 928 |
| AHSB BF02 | BACKFLOW PREVENTER (1-2 INCHES) | BFP-006 | D2020 | 2021 | 2,069 |
| AHSB BF02 | BACKFLOW PREVENTER (1-2 INCHES) | BFP-004 | D2020 | 2021 | 2,069 |
| AHSB BF04 | BACKFLOW PREVENTER (3-4 INCHES) | BFP-001 | D2020 | 2021 | 7,752 |
| AHSB BF04 | BACKFLOW PREVENTER (3-4 INCHES) | BFP-002 | D2020 | 2021 | 7,752 |
| AHSB AH41 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC2 | D3050 | 2021 | 37,881 |
| AHSB AH41 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC3 | D3050 | 2021 | 37,881 |
| AHSB AH41 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC1 | D3050 | 2021 | 37,881 |
| AHSB AH41 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC4 | D3050 | 2021 | 37,881 |
| AHSB FA01 | FIRE ALARM PANEL, DIALER, BATTERY, & CHARGER | 1514 | D4030 | 2021 | 33,484 |
| AHSB LE03 | LIGHTING - EXTERIOR, RECESSED (INC, CFL, LED) | CFL | D5020 | 2021 | 3,942 |
| AHSB LE07 | LIGHTING - EXTERIOR, WALL FLOOD (SV, MH, ID, LED) | HID | D5020 | 2021 | 14,865 |

FACILITIES RENEWAL PLAN
 RECURRING COMPONENT REPLACEMENT COSTS

All costs shown as Present Value

| ASSET CODE COMP CODE | COMPONENT | IDENTIFIER | UNI- FORMAT | REPLACEMENT YEAR | REPLACEMENT COST |
|-------------------------|---|------------|----------------|---------------------|---------------------|
| AHSB LE08 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | CFL | D5020 | 2021 | 12,851 |
| AHSB VF06 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1C | D5010 | 2022 | 6,277 |
| AHSB VF06 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-4CD | D5010 | 2022 | 6,277 |
| AHSB VF06 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1D1 | D5010 | 2022 | 6,277 |
| AHSB VF06 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-4D2 | D5010 | 2022 | 6,277 |
| AHSB VF06 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-3C | D5010 | 2022 | 6,277 |
| AHSB VF06 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-2D2 | D5010 | 2022 | 6,277 |
| AHSB VF06 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1DE | D5010 | 2022 | 6,277 |
| AHSB VF06 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-3E | D5010 | 2022 | 7,846 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-3AB | D5010 | 2022 | 7,548 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-4B | D5010 | 2022 | 7,548 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | CHWP-1 | D5010 | 2022 | 9,057 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-2CD | D5010 | 2022 | 9,057 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | CHWP-2 | D5010 | 2022 | 9,057 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-3D | D5010 | 2022 | 9,057 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU1-1 | D5010 | 2022 | 9,057 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU2-1 | D5010 | 2022 | 9,057 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU3-1 | D5010 | 2022 | 9,057 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU4-1 | D5010 | 2022 | 9,057 |
| AHSB VF07 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-2E | D5010 | 2022 | 9,057 |
| AHSB VF08 | VARIABLE FREQUENCY DRIVE (30-40 HP) | SAF-2B | D5010 | 2022 | 10,268 |
| AHSB VF09 | VARIABLE FREQUENCY DRIVE (40-50 HP) | SAF-1AB | D5010 | 2022 | 9,463 |
| AHSB WH24 | WATER HEATER - RESIDENTIAL, ELECTRIC (46-100 GAL) | WH-1 | D2020 | 2023 | 1,455 |
| AHSB RR03 | ROOF - 1-PLY, ADHERED (EPDM, PIB, CSPE, PVC) | FLAT | B3010 | 2024 | 157,491 |
| AHSB FA02 | FIRE ALARM SYSTEM - DEVICES | ALL | D4030 | 2024 | 1,018,268 |
| AHSB CR02 | REFRIGERATION SYSTEM - WALK-IN, 2 EVAP FANS, 6700 BTUH, CONDENSER | ROOM 3425B | E1020 | 2024 | 8,585 |

FACILITIES RENEWAL PLAN
RECURRING COMPONENT REPLACEMENT COSTS

All costs shown as Present Value

| ASSET CODE COMP CODE | COMPONENT | IDENTIFIER | UNI- FORMAT | REPLACEMENT YEAR | REPLACEMENT COST |
|-------------------------|-----------|------------|----------------|---------------------|---------------------|
| TOTAL | | | | | \$4,481,806 |

PROJECT LIST BY CLASSIFICATION

All costs shown as Present Value

| CORRECTIVE ACTION | | | | |
|------------------------------------|----------------|---|---------|------------------|
| PRI SEQ | PROJECT NUMBER | PROJECT TITLE | PRI CLS | TOTAL COST |
| 3 | AHSBES01 | EXTERIOR MASONRY AND CONCRETE VENEER RENEWAL | 3 | 5,918,937 |
| 4 | AHSBES02 | REFLASH AND RESEAL SKYLIGHTS | 3 | 11,971 |
| TOTAL FOR CORRECTIVE ACTION | | | | 5,930,909 |
| PLANT ADAPTION | | | | |
| PRI SEQ | PROJECT NUMBER | PROJECT TITLE | PRI CLS | TOTAL COST |
| 1 | AHSBAC01 | TIERED CLASSROOM ACCESSIBILITY UPGRADES | 2 | 77,227 |
| 2 | AHSBFS01 | INSTALL FM-200 OR INERGEN SYSTEM IN DATA CENTER | 3 | 23,483 |
| TOTAL FOR PLANT ADAPTION | | | | 100,710 |
| GRAND TOTAL: | | | | 6,031,619 |

PROJECT LIST BY CATEGORY CODE

All costs shown as Present Value

| PRI SEQ | PROJECT NUMBER | PRI CLS | PROJECT CLASSIFICATION | PROJECT TITLE | TOTAL COST |
|-----------------------------------|----------------|---------|------------------------|---|------------------|
| 1 | AHSBAC01 | 2 | Plant Adaption | TIERED CLASSROOM ACCESSIBILITY UPGRADES | 77,227 |
| TOTAL FOR ACCESSIBILITY | | | | | 77,227 |
| 3 | AHSBES01 | 3 | Corrective Action | EXTERIOR MASONRY AND CONCRETE VENEER RENEWAL | 5,918,937 |
| 4 | AHSBES02 | 3 | Corrective Action | REFLASH AND RESEAL SKYLIGHTS | 11,971 |
| TOTAL FOR EXTERIOR | | | | | 5,930,909 |
| 2 | AHSBFS01 | 3 | Plant Adaption | INSTALL FM-200 OR INERGEN SYSTEM IN DATA CENTER | 23,483 |
| TOTAL FOR FIRE/LIFE SAFETY | | | | | 23,483 |
| GRAND TOTAL: | | | | | 6,031,619 |

FACILITY CONDITION ASSESSMENT

SECTION 3

**NONRECURRING
PROJECT DETAILS**

All costs shown as Present Value

| TIERED CLASSROOM ACCESSIBILITY UPGRADES | | | |
|---|----------------|-----------------------|-------------------------|
| Project Number: | AHSBAC01 | Category Code: | |
| Priority Sequence: | 1 | AC3B | |
| Priority Class: | Critical | System: | ACCESSIBILITY |
| Project Class: | Plant Adaption | Component: | INTERIOR PATH OF TRAVEL |
| Date Basis: | 4/20/2016 | Element: | STAIRS AND RAILINGS |

| Code Application: | | Subclass/Savings: | Project Location: |
|-------------------|-----|-------------------|-----------------------|
| ADAAG | 505 | Not Applicable | Room Only: Floor(s) 1 |

Description

Present legislation pertaining to handicapped access within buildings requires that goods and services offered be generally accessible to all persons. Even though wheelchair access has been provided at the front of the six terraced classrooms on the first floor, the existing stepped aisles along the outer walls do not have the wall rail required for stepped egresses. It is recommended that wall-mounted compliant railings be installed along the side aisles to improve the access to these classrooms.

All costs shown as Present Value

Project Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|---|-----------|-----|--------------------|---------------------|-----------------|------------------|-----------------|
| Wall-mounted handrail system, painted (15 feet minimum) | LF | 650 | \$56.65 | \$36,823 | \$39.70 | \$25,805 | \$62,628 |
| Base Material/Labor Costs | | | | \$36,823 | | \$25,805 | |
| Indexed Material/Labor Costs | | | | \$37,080 | | \$18,399 | \$55,479 |
| General Contractor Mark Up at 20.0% | | | | | | | \$11,096 |
| Original Construction Cost | | | | | | | \$66,575 |
| Date of Original Estimate: | 4/20/2016 | | | | | Inflation | \$0 |
| Current Year Construction Cost | | | | | | | \$66,575 |
| Professional Fees at 16.0% | | | | | | | \$10,652 |
| TOTAL PROJECT COST | | | | | | | \$77,227 |

All costs shown as Present Value

| INSTALL FM-200 OR INERGEN SYSTEM IN DATA CENTER | | | |
|---|----------------|-----------------------|------------------|
| Project Number: | AHSBFS01 | Category Code: | |
| Priority Sequence: | 2 | FS3D | |
| Priority Class: | Non-Critical | System: | FIRE/LIFE SAFETY |
| Project Class: | Plant Adaption | Component: | SUPPRESSION |
| Date Basis: | 7/26/2016 | Element: | OTHER |

| Code Application: | | Subclass/Savings: | Project Location: |
|-------------------|------|-------------------|-----------------------|
| NFPA | 2001 | Not Applicable | Room Only: Floor(s) 1 |
| IBC | 904 | | |

Description

Room 1512 is the main data center for this facility and is currently protected by the wet-pipe fire suppression system. It is recommended that this area be equipped with a an FM-200 or Inergen based fire suppression system that would protect the data center equipment in the event of a fire.

All costs shown as Present Value

Project Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|--|-----------|-------|--------------------|---------------------|-----------------|------------------|-----------------|
| Install FM200 or Inergen fire suppression system | CF | 6,000 | \$1.90 | \$11,400 | \$1.26 | \$7,560 | \$18,960 |
| Base Material/Labor Costs | | | | \$11,400 | | \$7,560 | |
| Indexed Material/Labor Costs | | | | \$11,480 | | \$5,390 | \$16,870 |
| General Contractor Mark Up at 20.0% | | | | | | | \$3,374 |
| Original Construction Cost | | | | | | | \$20,244 |
| Date of Original Estimate: | 7/26/2016 | | | | | Inflation | \$0 |
| Current Year Construction Cost | | | | | | | \$20,244 |
| Professional Fees at 16.0% | | | | | | | \$3,239 |
| TOTAL PROJECT COST | | | | | | | \$23,483 |

All costs shown as Present Value

| EXTERIOR MASONRY AND CONCRETE VENEER RENEWAL | | | |
|--|-------------------|-----------------------|---------------------|
| Project Number: | AHSBES01 | Category Code: | |
| Priority Sequence: | 3 | ES2B | |
| Priority Class: | Non-Critical | System: | EXTERIOR |
| Project Class: | Corrective Action | Component: | COLUMNS/BEAMS/WALLS |
| Date Basis: | 4/20/2016 | Element: | FINISH |

| Code Application: | Subclass/Savings: | Project Location: |
|-------------------|-------------------|---------------------------|
| Not Applicable | Not Applicable | Building-wide: Floor(s) 1 |

Description

The existing brick masonry exterior envelope has water infiltration throughout the structure. Numerous areas of the exterior were uncovered and found to have systematic deficiencies throughout. This appears to be a result of improper flashing installation and/or faulty design and construction of the internal wall drainage cavity. Remove and replace the existing deficient flashing at the existing openings, and create an improved end-damn condition.

All costs shown as Present Value

Project Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|---|-----------|--------|--------------------|---------------------|-----------------|--------------------|--------------------|
| Repair brick exterior wall, average bond | SF | 91,000 | \$11.00 | \$1,001,000 | \$40.00 | \$3,640,000 | \$4,641,000 |
| General exterior wall surface clean and pressure wash with light chemical | SF | 20,000 | \$0.23 | \$4,600 | \$1.60 | \$32,000 | \$36,600 |
| Window flashing replacement | LF | 7,900 | \$25.00 | \$197,500 | \$75.00 | \$592,500 | \$790,000 |
| Base Material/Labor Costs | | | | \$1,203,100 | | \$4,264,500 | |
| Indexed Material/Labor Costs | | | | \$1,211,522 | | \$3,040,589 | \$4,252,110 |
| General Contractor Mark Up at 20.0% | | | | | | | \$850,422 |
| Original Construction Cost | | | | | | | \$5,102,532 |
| Date of Original Estimate: | 4/20/2016 | | | | | Inflation | \$0 |
| Current Year Construction Cost | | | | | | | \$5,102,532 |
| Professional Fees at 16.0% | | | | | | | \$816,405 |
| TOTAL PROJECT COST | | | | | | | \$5,918,937 |

All costs shown as Present Value

| REFLASH AND RESEAL SKYLIGHTS | | | |
|------------------------------|-------------------|-----------------------|----------|
| Project Number: | AHSBES02 | Category Code: | |
| Priority Sequence: | 4 | ES4A | |
| Priority Class: | Non-Critical | System: | EXTERIOR |
| Project Class: | Corrective Action | Component: | ROOF |
| Date Basis: | 4/20/2016 | Element: | REPAIR |

Code Application:

Not Applicable

Subclass/Savings:

Not Applicable

Project Location:

Area Wide: Floor(s) 2

Description

The existing skylights need the flashing reworked. Leaks were apparent at numerous locations. Reflash and recaulk/reseal skylights as required, and water-test prior to completion.

All costs shown as Present Value

Project Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|---|-----------|-----|--------------------|---------------------|-----------------|------------------|-----------------|
| Reflash and recaulk/reseal the existing skylights | LOT | 1 | \$5,000 | \$5,000 | \$5,000 | \$5,000 | \$10,000 |
| Base Material/Labor Costs | | | | \$5,000 | | \$5,000 | |
| Indexed Material/Labor Costs | | | | \$5,035 | | \$3,565 | \$8,600 |
| General Contractor Mark Up at 20.0% | | | | | | | \$1,720 |
| Original Construction Cost | | | | | | | \$10,320 |
| Date of Original Estimate: | 4/20/2016 | | | | | Inflation | \$0 |
| Current Year Construction Cost | | | | | | | \$10,320 |
| Professional Fees at 16.0% | | | | | | | \$1,651 |
| TOTAL PROJECT COST | | | | | | | \$11,971 |

FACILITY CONDITION ASSESSMENT

SECTION 4

LIFECYCLE COMPONENT
SUMMARY

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|--|---------------------|--------|-------|------------|-----------|-------------|--------------|-------------|-----------------|
| B2010 | WALL, EXTERIOR, STUCCO OR CONCRETE RESTORE | CONCRETE VENEER | 7,500 | SF | \$8.54 | 1.27 | \$81,341 | 2006 | 30 | |
| B2010 | GLASS, WINDOW, ALUMINUM OR WOOD, STANDARD | DUAL PANE | 20,000 | SF | \$135.41 | 1.27 | \$3,439,438 | 2006 | 40 | |
| B2010 | GLASS, WINDOW, ALUMINUM OR WOOD, CUSTOM | ATRIUMS | 2,690 | SF | \$186.22 | 1.27 | \$636,173 | 2006 | 40 | |
| B2030 | DOOR AND FRAME, EXTERIOR, SWINGING, ALUMINUM AND GLASS | ENTRY | 35 | LEAF | \$2,552.34 | | \$89,332 | 2006 | 25 | |
| B2030 | DOOR AND FRAME, EXTERIOR, SWINGING, HOLLOW METAL | EMERG. EXIT/SERVICE | 20 | LEAF | \$1,796.58 | | \$35,932 | 2006 | 40 | |
| B2030 | DOOR, EXTERIOR, OVERHEAD ROLLING METAL, LOCK | SO. LOADING DOCK | 160 | SF | \$86.82 | | \$13,891 | 2006 | 30 | |
| B2030 | DOOR OPERATOR, OVERHEAD DOOR, COMMERCIAL, PADS | SO. LOADING DOCK | 1 | EA | \$1,879.84 | | \$1,880 | 2006 | 15 | 6 |
| B3010 | ROOF - 1-PLY, ADHERED (EPDM, PIB, CSPE, PVC) | FLAT | 26,400 | SF | \$5.97 | | \$157,491 | 2006 | 20 | -2 |
| B3010 | ROOF - PANEL, ALUMINUM OR GALVANIZED, STANDING SEAM | PITCHED | 72,000 | SF | \$17.47 | | \$1,258,056 | 2006 | 40 | |
| B3020 | ROOF SKYLIGHT - GLASS WITH ALUMINUM FRAME | FLAT | 600 | SF | \$240.50 | | \$144,297 | 2006 | 35 | |
| C1020 | DOOR AND FRAME, INTERIOR, NON-RATED | NON RATED | 250 | LEAF | \$1,914.90 | | \$478,726 | 2006 | 40 | |
| C1020 | DOOR AND FRAME, INTERIOR, FIRE-RATED | RATED | 500 | LEAF | \$3,307.34 | | \$1,653,671 | 2006 | 40 | |
| C1020 | DOOR LOCK, COMMERCIAL-GRADE | NOT RATED DOORS | 250 | EA | \$658.73 | | \$164,683 | 2006 | 20 | |
| C1020 | DOOR LOCK, COMMERCIAL-GRADE | FIRE RATED DOORS | 500 | EA | \$658.73 | | \$329,366 | 2006 | 20 | |
| C1020 | DOOR PANIC HARDWARE | ENTRY | 35 | EA | \$1,077.73 | | \$37,721 | 2006 | 20 | |
| C1020 | DOOR PANIC HARDWARE | EMERG. EXIT/SERVICE | 20 | EA | \$1,077.73 | | \$21,555 | 2006 | 20 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|---|------------------------------|---------|-------|-------------|-----------|-------------|--------------|-------------|-----------------|
| C1030 | CASEWORK - WOOD BASE AND WALL, TOP, STANDARD | NON-LAB | 150 | LF | \$477.05 | | \$71,557 | 2006 | 20 | 5 |
| C1030 | KITCHENETTE UNIT WITH CABINETRY AND AMENITIES | 3RD FLR- SM. APT-KITCHEN | 1 | EA | \$10,992.79 | | \$10,993 | 2006 | 20 | 2 |
| C1030 | CASEWORK - LABORATORY, INCLUDES REAGENT SHELF AND TOP | TEACHING LAB | 20,330 | SF | \$132.73 | | \$2,698,317 | 2006 | 40 | |
| C1030 | CASEWORK - LABORATORY, INCLUDES REAGENT SHELF AND TOP | WET LAB | 10,010 | SF | \$132.73 | | \$1,328,586 | 2006 | 40 | |
| C3010 | WALL FINISH - PAINT, STANDARD | THROUGHOUT | 450,640 | SF | \$1.98 | | \$892,165 | 2006 | 12 | 2 |
| C3010 | WALL FINISH - TILE, CERAMIC / STONE, STANDARD | CERAMIC RR | 8,540 | SF | \$33.95 | | \$289,916 | 2006 | 30 | |
| C3010 | WALL FINISH - TILE, CERAMIC / STONE, PREMIUM | SLATE | 950 | SF | \$88.10 | | \$83,694 | 2006 | 40 | |
| C3010 | WALL FINISH - WALL COVERING, ROLL | WALLPAPER | 23,720 | SF | \$4.61 | | \$109,316 | 2006 | 20 | |
| C3020 | FLOORING - CARPET, TILE OR ROLL, STANDARD | OFC, HALL, CONF RM, CLASSRMS | 158,000 | SF | \$10.83 | | \$1,711,495 | 2006 | 12 | |
| C3020 | FLOORING - VINYL COMPOSITION TILE, STANDARD | LABS | 61,000 | SF | \$5.67 | | \$345,826 | 2006 | 20 | 3 |
| C3020 | FLOORING - VINYL SHEET, STANDARD | TEACHING LABS | 24,270 | SF | \$9.45 | | \$229,290 | 2006 | 15 | 6 |
| C3020 | FLOORING - TILE, CERAMIC / STONE / QUARRY STANDARD | CERAMIC RR | 8,500 | SF | \$28.13 | | \$239,113 | 2006 | 30 | |
| C3020 | FLOORING - HARDWOOD STRIP, PREMIUM | HISTORIC COLLECTIONS RM | 1,200 | SF | \$31.46 | | \$37,750 | 2006 | 50 | |
| C3020 | FLOORING - FLUID APPLIED, PAINT OR CLEAR SEAL | CONCRETE SLABS | 12,000 | SF | \$2.72 | | \$32,623 | 2006 | 10 | 5 |
| C3020 | FLOORING - SLATE | LOBBIES/1ST FLR CORRIDORS | 6,000 | SF | \$58.65 | | \$351,920 | 2006 | 50 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|--|---------------------------|---------|-------|--------------|-----------|-------------|--------------|-------------|-----------------|
| C3030 | CEILING FINISH - SUSPENDED ACOUSTICAL TILE, STANDARD | THROUGHOUT | 196,610 | SF | \$8.93 | | \$1,755,209 | 2006 | 30 | |
| C3030 | CEILING FINISH - SUSPENDED ACOUSTICAL TILE, PREMIUM | HISTORICAL COLLECTIONS RM | 21,850 | SF | \$11.07 | | \$241,851 | 2006 | 30 | |
| C3030 | CEILING FINISH - PAINTED OR STAINED, STANDARD | THROUGHOUT | 24,270 | SF | \$1.98 | | \$48,049 | 2006 | 24 | |
| D1010 | ELEVATOR MODERNIZATION - HYDRAULIC | ELEVATOR D | 1 | EA | \$267,217.03 | | \$267,217 | 2006 | 25 | |
| D1010 | ELEVATOR MODERNIZATION - HYDRAULIC | ELEVATOR C | 1 | EA | \$267,217.03 | | \$267,217 | 2006 | 25 | |
| D1010 | ELEVATOR MODERNIZATION - HYDRAULIC | ELEVATOR B | 1 | EA | \$267,217.03 | | \$267,217 | 2006 | 25 | |
| D1010 | ELEVATOR MODERNIZATION - HYDRAULIC | ELEVATOR E | 1 | EA | \$267,217.03 | | \$267,217 | 2006 | 25 | |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR B | 1 | EA | \$47,120.09 | | \$47,120 | 2006 | 12 | |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR C | 1 | EA | \$47,120.09 | | \$47,120 | 2006 | 12 | |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR D | 1 | EA | \$47,120.09 | | \$47,120 | 2006 | 12 | |
| D2010 | PLUMBING FIXTURE - LAVATORY, COUNTER | ALL | 94 | EA | \$1,165.93 | | \$109,597 | 2006 | 35 | |
| D2010 | PLUMBING FIXTURE - SINK, KITCHEN | STAFF APARTMENT | 1 | EA | \$1,910.44 | | \$1,910 | 2006 | 35 | |
| D2010 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | ALL | 16 | EA | \$1,585.76 | | \$25,372 | 2006 | 35 | |
| D2010 | PLUMBING FIXTURE - BATHTUB WITH FIXTURES | STAFF APARTMENT | 1 | EA | \$5,923.65 | | \$5,924 | 2006 | 35 | |
| D2010 | PLUMBING FIXTURE - URINAL | ALL | 30 | EA | \$1,873.57 | | \$56,207 | 2006 | 35 | |
| D2010 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | ALL | 137 | EA | \$1,723.71 | | \$236,148 | 2006 | 35 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|---|--------------------------|---------|-------|------------|-----------|-------------|--------------|-------------|-----------------|
| D2010 | PLUMBING FIXTURE - EMERGENCY SHOWER | SHOWERS | 4 | EA | \$1,334.81 | | \$5,339 | 2006 | 35 | |
| D2010 | PLUMBING FIXTURE - EMERGENCY EYEWASH | EYEWASH | 11 | EA | \$4,144.90 | | \$45,594 | 2006 | 35 | |
| D2010 | PLUMBING FIXTURE - EMERGENCY EYEWASH | DRENCH HOSE | 6 | EA | \$4,144.90 | | \$24,869 | 2006 | 35 | |
| D2010 | PLUMBING FIXTURE - EMERGENCY COMBINATION SHOWER/EYEWASH | COMBINATION | 5 | EA | \$7,125.26 | | \$35,626 | 2006 | 35 | |
| D2020 | BACKFLOW PREVENTER (<=1 INCH) | BFP-003 | 1 | EA | \$928.01 | | \$928 | 2006 | 10 | 5 |
| D2020 | BACKFLOW PREVENTER (<=1 INCH) | BFP-005 | 1 | EA | \$928.01 | | \$928 | 2006 | 10 | 5 |
| D2020 | BACKFLOW PREVENTER (1-2 INCHES) | BFP-006 | 1 | EA | \$2,069.32 | | \$2,069 | 2006 | 10 | 5 |
| D2020 | BACKFLOW PREVENTER (1-2 INCHES) | BFP-004 | 1 | EA | \$2,069.32 | | \$2,069 | 2006 | 10 | 5 |
| D2020 | BACKFLOW PREVENTER (3-4 INCHES) | BFP-001 | 1 | EA | \$7,752.34 | | \$7,752 | 2006 | 10 | 5 |
| D2020 | BACKFLOW PREVENTER (3-4 INCHES) | BFP-002 | 1 | EA | \$7,752.34 | | \$7,752 | 2006 | 10 | 5 |
| D2020 | SUPPLY PIPING SYSTEM - CLASSROOM | COOPER | 303,406 | SF | \$8.60 | 0.93 | \$2,426,889 | 2006 | 35 | |
| D2020 | WATER HEATER - RESIDENTIAL, ELECTRIC (15-25 GAL) | TAN-001 | 20 | GAL | \$53.84 | | \$1,077 | 2006 | 10 | |
| D2020 | WATER HEATER - RESIDENTIAL, ELECTRIC (15-25 GAL) | TAN-002 | 20 | GAL | \$53.84 | | \$1,077 | 2006 | 10 | |
| D2020 | WATER HEATER - RESIDENTIAL, ELECTRIC (46-100 GAL) | WH-1 | 50 | GAL | \$29.10 | | \$1,455 | 2013 | 10 | |
| D2020 | WATER HEATER - SHELL & TUBE (45-93 GPM) | DWH-1 | 48 | GPM | \$1,043.01 | | \$50,065 | 2006 | 30 | |
| D2030 | DRAIN PIPING SYSTEM - CLASSROOM | CAST IRON OR BLACK STEEL | 303,406 | SF | \$12.99 | 0.93 | \$3,665,435 | 2006 | 40 | |
| | | | | | | | | | | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|--|----------------------|-----|-------|-------------|-----------|------------|--------------|-------------|-----------------|
| D2090 | VACUUM PUMP - OIL RING SEAL (5-10 HP), WITH TRAP | LAB | 6 | HP | \$6,438.72 | | \$38,632 | 2006 | 20 | 5 |
| D2090 | AIR COMPRESSOR - UTILITY (< =5 HP) | FLOOR E PREACTION | 1 | HP | \$2,055.54 | | \$2,056 | 2006 | 25 | |
| D2090 | COMPRESSED AIR STORAGE TANK | TAN-008 | 1 | EA | \$8,292.83 | 0.70 | \$5,805 | 2006 | 20 | 10 |
| D3020 | EXPANSION TANK (41-60 GAL) | TAN-003 | 50 | GAL | \$161.73 | | \$8,087 | 2006 | 25 | |
| D3020 | EXPANSION TANK (41-60 GAL) | TAN-004 | 50 | GAL | \$161.73 | | \$8,087 | 2006 | 25 | |
| D3020 | EXPANSION TANK (41-60 GAL) | TAN-005 | 50 | GAL | \$161.73 | | \$8,087 | 2006 | 25 | |
| D3020 | EXPANSION TANK (41-60 GAL) | TAN-007 | 50 | GAL | \$161.73 | | \$8,087 | 2006 | 25 | |
| D3020 | CONDENSATE STORAGE TANK | FLASH TANK | 1 | EA | \$14,396.06 | 0.45 | \$6,478 | 2006 | 20 | 10 |
| D3040 | AIR HANDLING UNIT - INDOOR (12-17 HP) | AHU-1E | 15 | HP | \$6,099.73 | | \$91,496 | 2006 | 25 | 5 |
| D3040 | AIR HANDLING UNIT - INDOOR (17-23 HP) | AHU-1C | 20 | HP | \$5,761.76 | | \$115,235 | 2006 | 25 | 5 |
| D3040 | AIR HANDLING UNIT - INDOOR (17-23 HP) | AHU-1D1 | 20 | HP | \$5,761.76 | | \$115,235 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (17-23 HP) | AHU-1DE | 20 | HP | \$5,761.76 | | \$115,235 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (17-23 HP) | AHU-4E | 20 | HP | \$5,761.76 | | \$115,235 | 2006 | 25 | 5 |
| D3040 | AIR HANDLING UNIT - INDOOR (17-23 HP) | AHU-4CD | 20 | HP | \$5,761.76 | | \$115,235 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (17-23 HP) | AHU-4D2 | 20 | HP | \$5,761.76 | | \$115,235 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (17-23 HP) | AHU-2D2 | 20 | HP | \$5,761.76 | | \$115,235 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (17-23 HP) | AHU-3C | 20 | HP | \$5,761.76 | | \$115,235 | 2006 | 25 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|---|------------|-------|-------|------------|-----------|------------|--------------|-------------|-----------------|
| D3040 | AIR HANDLING UNIT - INDOOR (23-27 HP) | AHU-4B | 25 | HP | \$5,079.76 | | \$126,994 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (23-27 HP) | AHU-3AB | 25 | HP | \$5,079.76 | | \$126,994 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (23-27 HP) | AHU-3E | 25 | HP | \$5,079.76 | | \$126,994 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (27-35 HP) | AHU-2E | 30 | HP | \$5,430.77 | | \$162,923 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (27-35 HP) | ERU-4 | 30 | HP | \$5,430.77 | | \$162,923 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (27-35 HP) | AHU-2CD | 30 | HP | \$5,430.77 | | \$162,923 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (27-35 HP) | ERU-1 | 30 | HP | \$5,430.77 | | \$162,923 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (27-35 HP) | ERU-2 | 30 | HP | \$5,430.77 | | \$162,923 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (27-35 HP) | AHU-3D | 30 | HP | \$5,430.77 | | \$162,923 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (27-35 HP) | ERU-3 | 30 | HP | \$5,430.77 | | \$162,923 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (35-45 HP) | AHU-1AB | 40 | HP | \$5,080.65 | | \$203,226 | 2006 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (35-45 HP) | AHU-2AB | 40 | HP | \$5,080.65 | | \$203,226 | 2006 | 25 | |
| D3040 | ENTHALPY WHEEL, ENERGY RECOVERY, AIR TO AIR (20000-50000 CFM) | ERU-4 | 8,000 | CFM | \$2.28 | | \$18,203 | 2006 | 25 | |
| D3040 | ENTHALPY WHEEL, ENERGY RECOVERY, AIR TO AIR (20000-50000 CFM) | ERU-1 | 8,000 | CFM | \$2.28 | | \$18,203 | 2006 | 25 | |
| D3040 | ENTHALPY WHEEL, ENERGY RECOVERY, AIR TO AIR (20000-50000 CFM) | ERU-2 | 8,000 | CFM | \$2.28 | | \$18,203 | 2006 | 25 | |
| D3040 | ENTHALPY WHEEL, ENERGY RECOVERY, AIR TO AIR (20000-50000 CFM) | ERU-3 | 8,000 | CFM | \$2.28 | | \$18,203 | 2006 | 25 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|---|------------|-----|-------|------------|-----------|------------|--------------|-------------|-----------------|
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (<=3 HP) 9,200 CFM | RAF-1C | 2 | HP | \$3,183.45 | | \$6,367 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (<=3 HP) 9,200 CFM | RAF-1E | 3 | HP | \$3,183.45 | | \$9,550 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-3AB | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-1AB | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-4E | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-2CD | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-4CD | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-3C | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-3D | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-2D2 | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-1DE | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-1D1 | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-4D2 | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (3-5 HP) 13,200 CFM | RAF-3E | 5 | HP | \$2,148.60 | | \$10,743 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (5-7.5 HP) 16,500 CFM | RAF-2E | 8 | HP | \$1,770.95 | | \$14,168 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (5-7.5 HP) 16,500 CFM | RAF-4B | 8 | HP | \$1,770.95 | | \$14,168 | 2006 | 20 | 5 |
| D3040 | FAN - AXIAL, RETURN, 1.5" SP (7.5-10 HP) 19,500 CFM | RAF-2AB | 10 | HP | \$1,697.24 | | \$16,972 | 2006 | 20 | 5 |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|---|------------|---------|-------|------------|-----------|-------------|--------------|-------------|-----------------|
| D3040 | FAN - INLINE CENTRIFUGAL AIRFOIL, SUPPLY, 2.5" SP (<=30 HP) | EAJ-SF-1 | 5 | HP | \$1,240.44 | | \$6,202 | 2006 | 20 | 5 |
| D3040 | FAN - UTILITY SET, 1/4" SP (4-12 HP) | EAJ-ERU4 | 5 | HP | \$2,014.94 | | \$10,075 | 2006 | 20 | 5 |
| D3040 | FAN - UTILITY SET, 1/4" SP (4-12 HP) | EAJ-ERU1 | 5 | HP | \$2,014.94 | | \$10,075 | 2006 | 20 | 5 |
| D3040 | FAN - UTILITY SET, 1/4" SP (4-12 HP) | EAJ-EF-1 | 8 | HP | \$2,014.94 | | \$16,120 | 2006 | 20 | 5 |
| D3040 | FAN - UTILITY SET, 1/4" SP (4-12 HP) | EAJ-ERU2 | 5 | HP | \$2,014.94 | | \$10,075 | 2006 | 20 | 5 |
| D3040 | FAN - UTILITY SET, 1/4" SP (4-12 HP) | EAJ-ERU3 | 5 | HP | \$2,014.94 | | \$10,075 | 2006 | 20 | 5 |
| D3040 | FAN - UTILITY SET, 1/4" SP >12-17 HP) | EAJ-EF-2 | 15 | HP | \$1,401.47 | | \$21,022 | 2006 | 20 | 5 |
| D3040 | HOOD, FUME | 9 UNITS | 36 | LF | \$2,097.68 | | \$75,516 | 2006 | 20 | 5 |
| D3040 | HVAC DISTRIBUTION NETWORKS - CLASSROOM | ALL | 303,406 | SF | \$28.40 | 0.93 | \$8,014,140 | 2006 | 40 | |
| D3040 | HEAT EXCHANGER - SHELL & TUBE STEAM TO WATER (>85 GPM) | PHE-1 | 800 | GPM | \$130.08 | | \$104,061 | 2006 | 35 | |
| D3040 | PRESSURE REDUCING VALVE, STEAM SYSTEM (2") | PRV-001 | 1 | EA | \$3,950.83 | 0.65 | \$2,568 | 2006 | 20 | 5 |
| D3040 | PRESSURE REDUCING VALVE, STEAM SYSTEM (2") | PRV-113 | 1 | EA | \$3,950.83 | | \$3,951 | 2006 | 20 | 5 |
| D3040 | PRESSURE REDUCING VALVE, STEAM SYSTEM (2") | PRV-109 | 1 | EA | \$3,950.83 | | \$3,951 | 2006 | 20 | 5 |
| D3040 | PRESSURE REDUCING VALVE, STEAM SYSTEM (2") | PRV-111 | 1 | EA | \$3,950.83 | | \$3,951 | 2006 | 20 | 5 |
| D3040 | PRESSURE REDUCING VALVE, STEAM SYSTEM (2") | PRV-112 | 1 | EA | \$3,950.83 | | \$3,951 | 2006 | 20 | 5 |
| D3040 | PRESSURE REDUCING VALVE, STEAM SYSTEM (4") | PRV-002 | 1 | EA | \$8,690.27 | | \$8,690 | 2006 | 20 | 5 |
| D3040 | PUMP - ELECTRIC (<=10 HP) | PMP-001 | 3 | HP | \$1,455.41 | | \$4,366 | 2006 | 25 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|--|-------------|-----|-------|------------|-----------|------------|--------------|-------------|-----------------|
| D3040 | PUMP - ELECTRIC (<=10 HP) | DW-CP-01 | 1 | HP | \$1,455.41 | | \$1,455 | 2006 | 25 | |
| D3040 | PUMP - ELECTRIC (<=10 HP) | DW-CP-02 | 1 | HP | \$1,455.41 | | \$1,455 | 2006 | 25 | |
| D3040 | PUMP - ELECTRIC (<=10 HP) | DW-CP-03 | 1 | HP | \$1,455.41 | | \$1,455 | 2006 | 25 | |
| D3040 | PUMP - ELECTRIC (<=10 HP) | PCHW-1 | 1 | HP | \$1,455.41 | | \$1,455 | 2006 | 25 | |
| D3040 | PUMP - ELECTRIC (15 - 20 HP) | HWP-1 | 20 | HP | \$943.85 | | \$18,877 | 2006 | 25 | |
| D3040 | PUMP - ELECTRIC (15 - 20 HP) | HWP-2 | 20 | HP | \$943.85 | | \$18,877 | 2006 | 25 | |
| D3040 | PUMP - ELECTRIC (25 - 30 HP) | CHWP-1 | 30 | HP | \$833.59 | | \$25,008 | 2006 | 25 | |
| D3040 | PUMP - ELECTRIC (25 - 30 HP) | CHWP-2 | 30 | HP | \$833.59 | | \$25,008 | 2006 | 25 | |
| D3040 | CONDENSATE RECEIVER, ELECTRIC, 2 PUMPS | P-4 118/119 | 2 | HP | \$6,578.83 | | \$13,158 | 2006 | 20 | 5 |
| D3040 | CONDENSATE RECEIVER, PNEUMATIC (30-100 GPM) | PMP-VP-001 | 48 | GPM | \$1,050.10 | | \$50,405 | 2006 | 20 | 5 |
| D3050 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC2 | 18 | TON | \$2,104.52 | | \$37,881 | 2006 | 15 | |
| D3050 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC3 | 18 | TON | \$2,104.52 | | \$37,881 | 2006 | 15 | |
| D3050 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC1 | 18 | TON | \$2,104.52 | | \$37,881 | 2006 | 15 | |
| D3050 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC4 | 18 | TON | \$2,104.52 | | \$37,881 | 2006 | 15 | |
| D3060 | AIR COMPRESSOR SYSTEM - HVAC CONTROLS (<=6 TOTAL HP) | CONDENSATE | 2 | HP | \$1,587.17 | | \$3,174 | 2006 | 20 | 2 |
| D3060 | AIR COMPRESSOR SYSTEM - HVAC CONTROLS (>10 TOTAL HP) | AIR-001 | 15 | HP | \$1,667.08 | | \$25,006 | 2006 | 20 | 2 |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|--|--------------------|---------|-------|-------------|-----------|-------------|--------------|-------------|-----------------|
| D3060 | AIR DRYER - REFRIGERATED - 51-75 CFM | AIR DRYER #1 | 1 | EA | \$3,664.99 | 1.75 | \$6,414 | 2006 | 15 | 5 |
| D3060 | AIR DRYER - REFRIGERATED - 51-75 CFM | AIR DRYER #2 | 1 | EA | \$3,664.99 | 1.75 | \$6,414 | 2006 | 15 | 5 |
| D3060 | HVAC CONTROLS SYSTEM - CLASSROOM | ALL | 303,406 | SF | \$4.39 | 0.93 | \$1,237,333 | 2006 | 18 | 5 |
| D4010 | FIRE SPRINKLER SYSTEM | WET PIPE | 303,406 | SF | \$11.11 | 0.93 | \$3,133,669 | 2006 | 80 | |
| D4030 | EXIT SIGN - CENTRAL POWER | ALL | 270 | EA | \$304.20 | | \$82,135 | 2006 | 20 | |
| D4030 | EMERGENCY LIGHT - UNITARY WITH BATTERY BACK-UP | EMERGENCY BALLASTS | 300 | EA | \$528.05 | | \$158,416 | 2006 | 20 | |
| D4030 | EMERGENCY LIGHT - UNITARY WITH BATTERY BACK-UP | UNITARY FIXTURES | 11 | EA | \$528.05 | | \$5,809 | 2006 | 20 | |
| D4030 | FIRE ALARM PANEL, DIALER, BATTERY, & CHARGER | 1514 | 1 | EA | \$33,484.08 | | \$33,484 | 2006 | 15 | |
| D4030 | FIRE ALARM SYSTEM - DEVICES | ALL | 303,406 | SF | \$3.61 | 0.93 | \$1,018,268 | 2006 | 18 | |
| D5010 | ELECTRICAL DISTRIBUTION NETWORK - CLASSROOM | THROUGHOUT | 303,406 | SF | \$19.47 | 0.93 | \$5,493,572 | 2006 | 40 | |
| D5010 | MAIN SWITCHBOARD W/BREAKERS (>2500 AMP) | MSB1/MSB2/TIE | 3,200 | AMP | \$75.23 | 3.15 | \$758,300 | 2006 | 20 | 5 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-1C | 2 | HP | \$619.72 | | \$1,239 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU1-2 | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU1-3 | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU2-2 | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU2-3 | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-4E | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|-------------------------------------|------------|-----|-------|-----------|-----------|------------|--------------|-------------|-----------------|
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU4-2 | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU4-3 | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU3-2 | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU3-3 | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-3E | 5 | HP | \$619.72 | | \$3,099 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-1E | 3 | HP | \$619.72 | | \$1,859 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2E | 8 | HP | \$561.96 | | \$4,496 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1DE | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1D1 | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-4D2 | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | EF-1 | 8 | HP | \$561.96 | | \$4,496 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3D | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2D2 | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2CD | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-4CD | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3C | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3AB | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|--------------------------------------|------------|-----|-------|-----------|-----------|------------|--------------|-------------|-----------------|
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1AB | 5 | HP | \$561.96 | | \$2,810 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (7.5-10 HP) | RAF-4B | 8 | HP | \$468.67 | | \$3,749 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (7.5-10 HP) | RAF-2B | 10 | HP | \$468.67 | | \$4,687 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (10-15 HP) | SAF-1E | 15 | HP | \$361.69 | | \$5,425 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (15-20 HP) | SAF-4E | 20 | HP | \$331.79 | | \$6,636 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (15-20 HP) | HWP-1 | 20 | HP | \$331.79 | | \$6,636 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (15-20 HP) | HWP-2 | 20 | HP | \$331.79 | | \$6,636 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (15-20 HP) | EF-2 | 15 | HP | \$331.79 | | \$4,977 | 2006 | 12 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1DE | 20 | HP | \$313.85 | | \$6,277 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-3C | 20 | HP | \$313.85 | | \$6,277 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-2D2 | 20 | HP | \$313.85 | | \$6,277 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-4D2 | 20 | HP | \$313.85 | | \$6,277 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1D1 | 20 | HP | \$313.85 | | \$6,277 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-4CD | 20 | HP | \$313.85 | | \$6,277 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1C | 20 | HP | \$313.85 | | \$6,277 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-3E | 25 | HP | \$313.85 | | \$7,846 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-2E | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|------------|--|--------------|---------|-------|------------|-----------|-------------|--------------|-------------|-----------------|
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU4-1 | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU1-1 | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-4B | 25 | HP | \$301.90 | | \$7,548 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-2CD | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | CHWP-2 | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | CHWP-1 | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-3AB | 25 | HP | \$301.90 | | \$7,548 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-3D | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU3-1 | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU2-1 | 30 | HP | \$301.90 | | \$9,057 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (30-40 HP) | SAF-2B | 40 | HP | \$256.69 | | \$10,268 | 2006 | 16 | |
| D5010 | VARIABLE FREQUENCY DRIVE (40-50 HP) | SAF-1AB | 40 | HP | \$236.58 | | \$9,463 | 2006 | 16 | |
| D5020 | LIGHTING - EXTERIOR, RECESSED (INC, CFL, LED) | CFL | 19 | EA | \$207.45 | | \$3,942 | 2006 | 15 | |
| D5020 | LIGHTING - EXTERIOR, STANCHION LUMINAIRE, 12-FOOT | POLE-MOUNTED | 25 | EA | \$1,930.60 | | \$48,265 | 2006 | 15 | 8 |
| D5020 | LIGHTING - EXTERIOR, WALL FLOOD (SV, MH, ID, LED) | HID | 17 | EA | \$874.39 | | \$14,865 | 2006 | 15 | |
| D5020 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | CFL | 35 | EA | \$367.16 | | \$12,851 | 2006 | 15 | |
| D5020 | LIGHTING SYSTEM, INTERIOR - CLASSROOM | THROUGHOUT | 303,406 | SF | \$8.97 | 0.93 | \$2,529,901 | 2006 | 20 | |

ASSET COMPONENT SUMMARY

| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | UNIT COST | CMPLX ADJ | TOTAL COST | INSTALL DATE | USEFUL LIFE | USEFUL LIFE ADJ |
|---------------------|---|-------------------|-----|-------|------------|-----------|---------------------|--------------|-------------|-----------------|
| D5090 | SWITCH - AUTO TRANSFER, 480 V (100-400 AMP) | ATS LS | 300 | AMP | \$36.37 | | \$10,911 | 2006 | 25 | |
| D5090 | SWITCH - AUTO TRANSFER, 480 V (>400 AMP) | ATS EQ | 600 | AMP | \$25.64 | | \$15,381 | 2006 | 25 | |
| E1020 | REFRIGERATION SYSTEM - WALK-IN, 2 EVAP FANS, 6700 BTUH, CONDENSER | ROOM 3425B | 1 | EA | \$8,584.71 | | \$8,585 | 2006 | 10 | 8 |
| E2010 | SEATING, FIXED, FOLDING, STANDARD | TIERED CLASSROOMS | 444 | EA | \$311.79 | | \$138,433 | 2006 | 40 | |
| Grand Total: | | | | | | | \$53,875,712 | | | |

COMPONENT RENEWAL COST BY YEAR

All costs shown as Future Value using a 3% average inflation rate

No Projected Component Replacement Cost for Asset No. AHSB for DR

| 2016 | | | | | | | |
|-------------|--|------------|-----|-------|---|----------------|--|
| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | REPLACEMENT COST | YEAR | |
| D2020 | WATER HEATER - RESIDENTIAL, ELECTRIC (15-25 GAL) | TAN-001 | 20 | GAL | \$1,077 | 2016 | |
| D2020 | WATER HEATER - RESIDENTIAL, ELECTRIC (15-25 GAL) | TAN-002 | 20 | GAL | \$1,077 | 2016 | |
| 2016 | | | | | PROJECTED COMPONENT REPLACEMENT COST | \$2,154 | |

No Projected Component Replacement Cost for Asset No. AHSB for 2017

| 2018 | | | | | | |
|------------|---|------------------------------|---------|-------|------------------|------|
| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | REPLACEMENT COST | YEAR |
| C3020 | FLOORING - CARPET, TILE OR ROLL, STANDARD | OFC, HALL, CONF RM, CLASSRMS | 158,000 | SF | \$1,815,725 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (7.5-10 HP) | RAF-2B | 10 | HP | \$4,972 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3AB | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1AB | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (7.5-10 HP) | RAF-4B | 8 | HP | \$3,978 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-1C | 2 | HP | \$1,315 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2CD | 5 | HP | \$2,981 | 2018 |

COMPONENT RENEWAL COST BY YEAR

All costs shown as Future Value using a 3% average inflation rate

| | | | | | | |
|-------|-------------------------------------|---------|----|----|---------|------|
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-4CD | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3C | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1D1 | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-4D2 | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (15-20 HP) | EF-2 | 15 | HP | \$5,280 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | EF-1 | 8 | HP | \$4,769 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-3D | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2D2 | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-1DE | 5 | HP | \$2,981 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU1-2 | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU1-3 | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU2-2 | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU2-3 | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU3-2 | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU3-3 | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU4-2 | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | ERU4-3 | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (15-20 HP) | HWP-1 | 20 | HP | \$7,040 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (15-20 HP) | HWP-2 | 20 | HP | \$7,040 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-3E | 5 | HP | \$3,287 | 2018 |
| D5010 | VARIABLE FREQUENCY DRIVE (5-7.5 HP) | RAF-2E | 8 | HP | \$4,769 | 2018 |

COMPONENT RENEWAL COST BY YEAR

All costs shown as Future Value using a 3% average inflation rate

| | | | | | | | |
|-------------|-------------------------------------|------------|----|----|---|------|--------------------|
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-4E | 5 | HP | \$3,287 | 2018 | |
| D5010 | VARIABLE FREQUENCY DRIVE (15-20 HP) | SAF-4E | 20 | HP | \$7,040 | 2018 | |
| D5010 | VARIABLE FREQUENCY DRIVE (10-15 HP) | SAF-1E | 15 | HP | \$5,756 | 2018 | |
| D5010 | VARIABLE FREQUENCY DRIVE (<=5 HP) | RAF-1E | 3 | HP | \$1,972 | 2018 | |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR B | 1 | EA | \$49,990 | 2018 | |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR C | 1 | EA | \$49,990 | 2018 | |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR D | 1 | EA | \$49,990 | 2018 | |
| 2018 | | | | | PROJECTED COMPONENT REPLACEMENT COST | | \$2,082,307 |

No Projected Component Replacement Cost for Asset No. AHSB for 2019

| 2020 | | | | | | | |
|-------------|-------------------------------|------------|---------|-------|---|------|--------------------|
| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | REPLACEMENT COST | YEAR | |
| C3010 | WALL FINISH - PAINT, STANDARD | THROUGHOUT | 450,640 | SF | \$1,004,140 | 2020 | |
| 2020 | | | | | PROJECTED COMPONENT REPLACEMENT COST | | \$1,004,140 |

| 2021 | | | | | | |
|------------|---|----------------|--------|-------|------------------|------|
| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | REPLACEMENT COST | YEAR |
| C3020 | FLOORING - FLUID APPLIED, PAINT OR CLEAR SEAL | CONCRETE SLABS | 12,000 | SF | \$37,819 | 2021 |
| D5020 | LIGHTING - EXTERIOR, RECESSED (INC, CFL, LED) | CFL | 19 | EA | \$4,569 | 2021 |

COMPONENT RENEWAL COST BY YEAR

All costs shown as Future Value using a 3% average inflation rate

| | | | | | | | |
|-------------|--|---------|----|-----|---|------|------------------|
| D5020 | LIGHTING - EXTERIOR, WALL FLOOD (SV, MH, ID, LED) | HID | 17 | EA | \$17,232 | 2021 | |
| D5020 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | CFL | 35 | EA | \$14,897 | 2021 | |
| D4030 | FIRE ALARM PANEL, DIALER, BATTERY, & CHARGER | 1514 | 1 | EA | \$38,817 | 2021 | |
| D3050 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC2 | 18 | TON | \$43,915 | 2021 | |
| D3050 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC3 | 18 | TON | \$43,915 | 2021 | |
| D3050 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC1 | 18 | TON | \$43,915 | 2021 | |
| D3050 | COMPUTER ROOM AC UNIT - CHILLED WATER (10 -20 TON) | AC4 | 18 | TON | \$43,915 | 2021 | |
| D2020 | BACKFLOW PREVENTER (<=1 INCH) | BFP-003 | 1 | EA | \$1,076 | 2021 | |
| D2020 | BACKFLOW PREVENTER (1-2 INCHES) | BFP-006 | 1 | EA | \$2,399 | 2021 | |
| D2020 | BACKFLOW PREVENTER (3-4 INCHES) | BFP-001 | 1 | EA | \$8,987 | 2021 | |
| D2020 | BACKFLOW PREVENTER (3-4 INCHES) | BFP-002 | 1 | EA | \$8,987 | 2021 | |
| D2020 | BACKFLOW PREVENTER (1-2 INCHES) | BFP-004 | 1 | EA | \$2,399 | 2021 | |
| D2020 | BACKFLOW PREVENTER (<=1 INCH) | BFP-005 | 1 | EA | \$1,076 | 2021 | |
| 2021 | | | | | PROJECTED COMPONENT REPLACEMENT COST | | \$313,918 |

| 2022 | | | | | | |
|------------|-------------------------------------|------------|-----|-------|------------------|------|
| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | REPLACEMENT COST | YEAR |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | CHWP-1 | 30 | HP | \$10,815 | 2022 |
| D5010 | VARIABLE FREQUENCY DRIVE (30-40 HP) | SAF-2B | 40 | HP | \$12,260 | 2022 |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-3AB | 25 | HP | \$9,012 | 2022 |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1C | 20 | HP | \$7,495 | 2022 |

COMPONENT RENEWAL COST BY YEAR

All costs shown as Future Value using a 3% average inflation rate

| | | | | | | | |
|-------------|-------------------------------------|---------|----|----|---|------|------------------|
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-4B | 25 | HP | \$9,012 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-2CD | 30 | HP | \$10,815 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | CHWP-2 | 30 | HP | \$10,815 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-4CD | 20 | HP | \$7,495 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1D1 | 20 | HP | \$7,495 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-4D2 | 20 | HP | \$7,495 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-3C | 20 | HP | \$7,495 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-2D2 | 20 | HP | \$7,495 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-3D | 30 | HP | \$10,815 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-1DE | 20 | HP | \$7,495 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (40-50 HP) | SAF-1AB | 40 | HP | \$11,299 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU1-1 | 30 | HP | \$10,815 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU2-1 | 30 | HP | \$10,815 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU3-1 | 30 | HP | \$10,815 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | ERU4-1 | 30 | HP | \$10,815 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (20-25 HP) | SAF-3E | 25 | HP | \$9,369 | 2022 | |
| D5010 | VARIABLE FREQUENCY DRIVE (25-30 HP) | SAF-2E | 30 | HP | \$10,815 | 2022 | |
| 2022 | | | | | PROJECTED COMPONENT REPLACEMENT COST | | \$200,751 |

| 2023 | | | | | | |
|------------|-----------------------|------------|-----|-------|------------------|------|
| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | REPLACEMENT COST | YEAR |

COMPONENT RENEWAL COST BY YEAR


All costs shown as Future Value using a 3% average inflation rate

| | | | | | | |
|-------------|---|------|----|-----|---|----------------|
| D2020 | WATER HEATER - RESIDENTIAL, ELECTRIC (46-100 GAL) | WH-1 | 50 | GAL | \$1,789 | 2023 |
| 2023 | | | | | PROJECTED COMPONENT REPLACEMENT COST | \$1,789 |

| 2024 | | | | | | |
|-------------|---|------------|---------|-------|---|--------------------|
| UNI-FORMAT | COMPONENT DESCRIPTION | IDENTIFIER | QTY | UNITS | REPLACEMENT COST | YEAR |
| B3010 | ROOF - 1-PLY, ADHERED (EPDM, PIB, CSPE, PVC) | FLAT | 26,400 | SF | \$199,504 | 2024 |
| D4030 | FIRE ALARM SYSTEM - DEVICES | ALL | 303,406 | SF | \$1,289,911 | 2024 |
| E1020 | REFRIGERATION SYSTEM - WALK-IN, 2 EVAP FANS, 6700 BTUH, CONDENSER | ROOM 3425B | 1 | EA | \$10,875 | 2024 |
| 2024 | | | | | PROJECTED COMPONENT REPLACEMENT COST | \$1,500,290 |

No Projected Component Replacement Cost for Asset No. AHSB for 2025

RECURRING COMPONENT EXPENDITURE PROJECTIONS




Average Annual Renewal Cost per SF \$4.87

FACILITY CONDITION ASSESSMENT


SECTION 5

DRAWINGS/PROJECT
LOCATIONS



ES01

FS01



FACILITY
CONDITION
ASSESSMENT
3100 Breckinridge Boulevard
Suite 400, Duluth GA 30096
770.879-7825

PROJECT NUMBER
APPLIES TO
ONE ROOM ONLY

PROJECT NUMBER
APPLIES TO
ONE ITEM ONLY

PROJECT NUMBER
APPLIES TO
ENTIRE BUILDING

PROJECT NUMBER
APPLIES TO
ENTIRE FLOOR


PROJECT NUMBER
APPLIES TO A SITUATION
OF UNDEFINED EXTENTS

PROJECT NUMBER
APPLIES TO AREA
AS NOTED

Date: 8/11/2016
Drawn by: A.W.
Project No. 15-124

FIRST
FLOOR
PLAN

Sheet No.



ALLIED HEALTH
SCIENCES
BUILDING

BLDG NO. AHSB



FACILITY
CONDITION
ASSESSMENT


3100 Breckinridge Boulevard
Suite 400, Duluth GA 30096
770.879-7825

 PROJECT NUMBER
APPLIES TO
ONE ROOM ONLY

 PROJECT NUMBER
APPLIES TO
ONE ITEM ONLY

 PROJECT NUMBER
APPLIES TO
ENTIRE BUILDING

 PROJECT NUMBER
APPLIES TO
ENTIRE FLOOR

 PROJECT NUMBER
APPLIES TO A SITUATION
OF UNDEFINED EXTENTS

 PROJECT NUMBER
APPLIES TO AREA
AS NOTED

Date: 8/11/2016


Drawn by: A.W.

Project No. 15-124

SECOND
FLOOR
PLAN

Sheet No.

2 of 4



FACILITY
CONDITION
ASSESSMENT


3100 Breckinridge Boulevard
Suite 400, Duluth GA 30096
770.879-7825

 PROJECT NUMBER
APPLIES TO
ONE ROOM ONLY

 PROJECT NUMBER
APPLIES TO
ONE ITEM ONLY

 PROJECT NUMBER
APPLIES TO
ENTIRE BUILDING

 PROJECT NUMBER
APPLIES TO
ENTIRE FLOOR


 PROJECT NUMBER
APPLIES TO A SITUATION
OF UNDEFINED EXTENTS

 PROJECT NUMBER
APPLIES TO AREA
AS NOTED

Date: 8/11/2016
Drawn by: A.W.
Project No. 15-124

THIRD
FLOOR
PLAN

Sheet No.



ALLIED HEALTH
SCIENCES
BUILDING

BLDG NO. AHSB



FACILITY
CONDITION
ASSESSMENT


3100 Breckinridge Boulevard
Suite 400, Duluth GA 30096
770.879-7825

 PROJECT NUMBER
APPLIES TO
ONE ROOM ONLY

 PROJECT NUMBER
APPLIES TO
ONE ITEM ONLY

 PROJECT NUMBER
APPLIES TO
ENTIRE BUILDING

 PROJECT NUMBER
APPLIES TO
ENTIRE FLOOR

 PROJECT NUMBER
APPLIES TO A SITUATION
OF UNDEFINED EXTENTS

 PROJECT NUMBER
APPLIES TO AREA
AS NOTED

Date: 8/11/2016

Drawn by: A.W.

Project No. 15-124

FOURTH
FLOOR
PLAN

Sheet No.

4 of 4

FACILITY CONDITION ASSESSMENT

SECTION 6

PHOTOGRAPHS



AHSB001a 4/20/2016
Single-ply TPO, flat roof
Lower level roof



AHSB001e 4/20/2016
Interior light fixture
East penthouse



AHSB002a 4/20/2016
Single-ply TPO, flat roof with drain
Mid level roof



AHSB002e 4/20/2016
Typical exit signage
East penthouse



AHSB003a 4/20/2016
Single-ply TPO, flat roof and pitched standing seam metal
roof
Upper level roof



AHSB003e 4/20/2016
Duct-mounted smoke detector
East penthouse



AHSB004a 4/20/2016
Single-ply TPO, flat roof and pitched standing seam metal
roof
Upper level roof



AHSB004e 4/20/2016
Hydronic unit heater
East penthouse



AHSB005a 4/20/2016
Pitched standing seam metal roof
Upper level roof



AHSB005e 4/20/2016
Inline return air fan RAF-3E
East penthouse



AHSB006a 4/20/2016
Typical stairwell with compliant handrails and
guardrailing
Stairwell



AHSB006e 4/20/2016
Variable frequency drive AHU-3E
East penthouse



AHSB007a 4/20/2016
Adhered acoustical tile ceiling
Library



AHSB007e 4/20/2016
Fire alarm system device with visual and audible
annunciation
East penthouse



AHSB008a 4/20/2016
Compliant dual-level drinking fountain
Fourth floor



AHSB008e 4/20/2016
Air handler AHU-3E
East penthouse



AHSB009a 4/20/2016
Exterior patio/roof
Fourth floor



AHSB009e 4/20/2016
18 ton computer room air conditioner
East penthouse



AHSB010a 4/20/2016
Suspended grid acoustical tile ceilings, painted walls, and
carpeted floors
Fourth floor



AHSB010e 4/20/2016
One-inch backflow preventer
East penthouse



AHSB011a 4/20/2016
Ceramic tiled lower walls and floors and accessible
fixtures
Typical restrooms



AHSB011e 4/20/2016
Energy recovery unit ERU-4
East Penthouse



AHSB012a 4/20/2016
Ceramic tiled lower walls and floors and accessible
fixtures
Typical restrooms



AHSB012e 4/20/2016
Heating water supply and return and waste water piping
East penthouse



AHSB013a 4/20/2016
Lavatories
Typical restrooms



AHSB013e 4/20/2016
Pneumatic control system piping
East penthouse



AHSB014a 4/20/2016
Heart of pine floors, replica tin ceiling panels, and
chandeliers
Historic Collections Reading Room



AHSB014e 4/20/2016
Various direct digital and pneumatic control panels
East penthouse



AHSB015a 4/20/2016
Heart of pine floors, painted walls, and fire rated glazing
Historic Collections Reading room



AHSB015e 4/20/2016
Preaction fire system air compressor
East penthouse



AHSB016a 4/20/2016
Vinyl tiled floors and suspended grid ceilings
Preservation lab



AHSB016e 4/20/2016
Fire riser with tamper switch and control valves
Fifth floor, stairwell 6



AHSB017a 4/20/2016
Hand-built wooden cabinetry
Historic Collections Reading room



AHSB017e 4/20/2016
Recessed, 1x4 fluorescent lighting with T8 lamps
Fourth floor, common space near 4508



AHSB018a 4/20/2016
Exterior exhausted fume hood
Preservation Lab



AHSB018e 4/20/2016
Various elegant, sconce, and recessed lighting
Fourth floor, common space near terrace



AHSB019a 4/20/2016
Laminated wooden lab cabinetry
Preservation lab



AHSB019e 4/20/2016
Exterior sconce fixture with CFL lamp
Fourth floor, terrace



AHSB020a 4/20/2016
High bay ceiling with carpeted floors
Library



AHSB020e 4/20/2016
Recessed, 2x4 foot fluorescent lighting with T8 lamps
Room 4508



AHSB021a 4/20/2016
Suspended grid acoustical tile ceilings with painted walls
and carpeted floors
Third floor



AHSB021e 4/20/2016
Typical glass bulb fire system sprinkler head
Room 4508



AHSB022a 4/20/2016
Suspended grid acoustical tile ceilings, painted walls, and
carpeted floors
First floor



AHSB022e 4/20/2016
Secondary electric system transformers and panelboards
Room 4520



AHSB023a 4/20/2016
Vinyl tiled floors, suspended grid ceilings, and built-in
cabinetry
First floor, break room



AHSB023e 4/20/2016
Pressure reducing valve systems
Room 1510B



AHSB024a 4/20/2016
First floor skylight
First floor, break room



AHSB024e 4/20/2016
Steam trap
Room 1510B



AHSB025a 4/20/2016
Vinyl tiled floors, suspended grid ceilings, and built-in
cabinetry
First floor



AHSB025e 4/20/2016
Flash tank #1
Room 1510B



AHSB026a 4/20/2016
Slate tiled floor
First floor



AHSB026e 4/20/2016
Unfired domestic water heating skid DWH-1
Room 1510B



AHSB027a 4/20/2016
Slate tiled floor and staircase
First floor, southern entrance



AHSB027e 4/20/2016
Twin, sealed emergency light fixture
Room 1510B



AHSB028a 4/20/2016
Vinyl flooring, painted walls, and suspended grid ceiling
First floor



AHSB028e 4/20/2016
Vacuum condensate return skid
Room 1510B



AHSB029a 4/20/2016
Suspended grid acoustical tile ceilings, painted walls, and
carpeted floors
Fourth floor, lounge



AHSB029e 4/20/2016
Heating water pumps HWP-1 and HWP-2
Room 1510B



AHSB030a 4/20/2016
Built-in cabinetry
Fourth floor, kitchen



AHSB030e 4/20/2016
Shell-and-tube heat exchanger PHE-1
Room 1510B



AHSB031a 4/20/2016
Vinyl tiled floors and suspended grid ceilings
Fourth floor, teaching lab



AHSB031e 4/20/2016
Various condensate return piping systems
Room 1510B



AHSB032a 4/20/2016
Vinyl tiled floors, suspended grid ceilings, and lab
cabinetry
Fourth floor, northern lab



AHSB032e 4/20/2016
Chilled water pumps CHWP-1 and CHWP-2
Room 1510B



AHSB033a 4/20/2016
Vinyl tiled floors, suspended grid ceilings, and metal lab
cabinetry
Fourth floor, northern lab



AHSB033e 4/20/2016
Two double-check, domestic water backflow preventers
Room 1510B



AHSB034a 4/20/2016
Vinyl tiled floors and suspended grid ceilings
Third floor, teaching lab



AHSB034e 4/20/2016
Minor calcification of the DW BFP valve stem
Room 1510B



AHSB035a 4/20/2016
Vinyl tiled floors, suspended grid ceilings, and built-in
cabinetry
Third floor, multi-activity lab



AHSB035e 4/20/2016
Wet-pipe fire system risers #1 and #2
Room 1510B



AHSB036a 4/20/2016
Ceiling tile water stained from fire suppression system
Second floor



AHSB036e 4/20/2016
Combination emergency shower and eyewash station
Room 1510B



AHSB037a 4/20/2016
Slate tiled floor
First floor, northeastern lobby



AHSB037e 4/20/2016
Pumped condensate air compressor
Room 1510B



AHSB038a 4/20/2016
Slate tiled floor
First floor, northwestern lobby



AHSB038e 4/20/2016
Air dryers #1 and #2
Room 1510B



AHSB039a 4/20/2016
Accessible service counter
Second floor, north



AHSB039e 4/20/2016
Laboratory duplex vacuum pump system
Room 1510B



AHSB040a 4/20/2016
Terraced classroom without handrails along the outer wall
First floor, north



AHSB040e 4/20/2016
Control systems air compressor
Room 1510B



AHSB041a 4/20/2016
Terraced classroom without handrails along the outer wall
First floor, north



AHSB041e 4/20/2016
Point addressable fire alarm control panel
Room 1514



AHSB042a 4/20/2016
Slate floor tile and wall tile
First floor, north



AHSB042e 4/20/2016
3,200 amp low-voltage circuit breaker switchgear
Room 1514



AHSB043a 4/20/2016
Chipped slate floor tile
First floor, north



AHSB043e 4/20/2016
Power circuit breaker main MSB1
Room 1514



AHSB044a 4/20/2016
Painted and suspended ceilings
First floor, snack bar



AHSB044e 4/20/2016
Automatic transfer switch ATS EQ
Room 1514



AHSB045a 4/20/2016
Stained exterior brick masonry
Exterior envelope



AHSB045e 4/20/2016
Automatic transfer switch ATS LS
Room 1514



AHSB046a 4/20/2016
Stained and deficient exterior brick masonry
Exterior envelope



AHSB046e 4/20/2016
Hydraulic elevator machine D
Room 1427



AHSB047a 4/20/2016
Stained and deficient exterior brick masonry
Exterior envelope



AHSB047e 4/20/2016
Fume hood FH-4165-1
Room 4165B



AHSB048a 4/20/2016
Stained and deficient exterior brick masonry
Exterior envelope



AHSB048e 4/20/2016
Utility set exhaust fan EF-1
Penthouse B



AHSB049a 4/20/2016
Stained and deficient exterior brick masonry
Exterior envelope



AHSB049e 4/20/2016
Two electric water heaters
Penthouse B



AHSB050a 4/20/2016
Stained and deficient exterior brick masonry
Exterior envelope



AHSB050e 4/20/2016
Surface-mounted exterior light fixture
Roof



AHSB051a 4/20/2016
Previous masonry repair
Exterior envelope



AHSB051e 4/20/2016
Variable air volume terminal
Penthouse D



AHSB052a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB052e 4/20/2016
Updated electric domestic water heater WH-1
Penthouse D



AHSB053a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB053e 4/20/2016
Dedicated mixing valve for emergency plumbing fixture
Penthouse D



AHSB054a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB054e 4/20/2016
Various lighting systems
Room 1120



AHSB055a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB055e 4/20/2016
Surface-mounted exterior light fixtures
Exterior



AHSB056a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB056e 4/20/2016
Hydraulic dock leveler
Exterior, loading dock



AHSB057a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
North elevation, E wing



AHSB058a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
East elevation, D wing



AHSB059a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB060a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
North elevation, C wing



AHSB061a 4/20/2016
Concrete panel exterior veneer
North elevation, C wing



AHSB062a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB063a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB064a 4/20/2016
Stained and deficient exterior brick masonry
Exterior envelope



AHSB065a 4/20/2016
Aluminum-framed glass entrance doors
Exterior envelope




AHSB066a 4/20/2016
Brick masonry and dual-pane or tempered glazing
North main entrance



AHSB067a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
North elevation, B and C wings



AHSB068a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
East side A and B wings



AHSB069a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB070a 4/20/2016
Stained and deficient exterior brick masonry
Exterior envelope



AHSB071a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB072a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
West elevation, A wing



AHSB073a 4/20/2016
Rubber gasket seal coming out in interior
West elevation, A wing



AHSB074a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
East elevation, A wing



AHSB075a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB076a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
West elevation, D wing



AHSB077a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
West elevation, D wing



AHSB078a 4/20/2016
Aluminum-framed glass entrance doors
Exterior envelope



AHSB079a 4/20/2016
Aluminum-framed glass entrance doors
Exterior envelope



AHSB080a 4/20/2016
Corrosion stain on exterior concrete veneer
Exterior envelope



AHSB081a 4/20/2016
Rubber gasket seal coming out in interior
South elevation, E wing



AHSB082a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
concrete veneer crown
South elevation, E wing



AHSB083a 4/20/2016
Deficient exterior brick masonry and a previous weep
repair
Exterior envelope



AHSB084a 4/20/2016
Hollow metal service door
Exterior envelope



AHSB085a 4/20/2016
Deficient exterior brick masonry and a previous repair
Exterior envelope



AHSB086a 4/20/2016
Brick masonry, dual-pane or tempered glazing, and
standing seam metal roof
Southeastern view