

# EAST CAROLINA UNIVERSITY

## GREENE RESIDENCE HALL

ASSET CODE: GREE

FACILITY CONDITION ANALYSIS

DECEMBER 3, 2009





EAST CAROLINA UNIVERSITY  
Facility Condition Analysis

---

**TABLE OF CONTENTS**

**Section 1: GENERAL ASSET INFORMATION**

A. Asset Executive Summary.....	1.1.1
B. Asset Summary.....	1.2.1
C. Inspection Team Data.....	1.3.1
D. Facility Condition Analysis - Definitions .....	1.4.1
1. Report Description .....	1.4.1
2. Project Classification.....	1.4.2
3. Project Subclass Type .....	1.4.2
4. Priority Class / Sequence .....	1.4.2
5. Priority Class .....	1.4.3
6. City Index Material / Labor Cost / Cost Summaries.....	1.4.3
7. Project Number .....	1.4.4
8. Photo Number .....	1.4.4
9. Life Cycle Cost Model Description and Definitions .....	1.4.4
10. Category Code .....	1.4.5
E. Category Code Report.....	1.5.1

**Section 2: DETAILED PROJECT SUMMARIES AND TOTALS**

A. Detailed Project Totals – Matrix with FCNI Data and Associated Charts .....	2.1.1
B. Detailed Projects by Priority Class / Priority Sequence .....	2.2.1
C. Detailed Projects by Cost within range [ \$0 - < \$100,000 ] .....	2.3.1
D. Detailed Projects by Cost within range [ ≥ \$100,000 - < \$500,000 ].....	2.3.2
E. Detailed Projects by Cost within range [ ≥ \$500,000 ].....	2.3.3
F. Detailed Projects by Project Classification.....	2.4.1
G. Detailed Projects by Project Subclass - Energy Conservation.....	2.5.1
H. Detailed Projects by Category / System Code.....	2.6.1

**Section 3: SPECIFIC PROJECT DETAILS ILLUSTRATING DESCRIPTION / COST .....** 3.1.1

**Section 4: DRAWINGS / PROJECT LOCATIONS**

**Section 5: LIFE CYCLE MODEL SUMMARY AND PROJECTIONS**

A. Building Component Summary.....	5.1.1
B. Expenditure Projections.....	5.2.1

**Section 6: PHOTOGRAPHIC LOG .....** 6.1.1



# FACILITY CONDITION ANALYSIS


## SECTION 1

### GENERAL ASSET INFORMATION



## EXECUTIVE SUMMARY - GREENE RESIDENCE HALL

### PROJECT COSTS BY CLASSIFICATION




**Building Code:** GREE  
**Building Name:** GREENE RESIDENCE HALL  
**Year Built:** 1966  
**Building Use:** Dormitory / Apartments  
**Square Feet:** 82,731

#### Project Costs by Priority


Priority 1:	\$12,146
Priority 2:	\$746,250
Priority 3:	\$3,008,906
Priority 4:	\$575,094
<b>Total Project Costs:</b>	<b>\$4,342,395</b>

**Facility Replacement Cost: \$25,697,000**


**Facility Condition Needs Index (FCNI): 0.17**  
 (Project Costs / Replacement Cost)



### PROJECT COSTS BY SYSTEM CODE



### LIFE CYCLE MODEL EXPENDITURE PROJECTIONS



**Average Annual Renewal Cost Per SqFt \$3.31**





## B. ASSET SUMMARY

Greene Residence Hall was constructed in 1966 and is located on the western edge of the main East Carolina University campus immediately adjacent to downtown Greenville. This building contains 82,731 square feet of area on ten levels of dormitory and communal space and is just east off of Cotanche Street between Reade Circle and Seventh Street. All ten levels are above grade. The cast-in-place concrete pier foundation supports a reinforced concrete and steel structure. There are approximately 200 dormitory rooms on floors two through ten, with a coordinator's suite and a visiting guest resident suite on the second floor. The first floor houses the coordinator's office, living room, recreation room, vending room, a handicapped unisex restroom, the dorm mail room, a former kitchen location, and housekeeping.

The building has a brick masonry facade and a flat built-up roof. All exterior windows on floors two through ten have been replaced with new dual pane, thermally insulated systems along with dripless window air conditioning units in each dorm room. The building is not generally considered to be handicapped accessible because it has sloped sidewalks and exterior steps without compliant handrails, and very few amenities within the facility have been improved for handicapped accessibility.

The information for this report was gathered during a site visit that concluded on September 16, 2009.

### SITE

The building sits on a slightly sloped parcel of land in a small suburban campus setting. Landscaping consists of minimal ornamental planting beds, shrubbery, specimen trees, and areas of turf. Vehicular access is from the south from Seventh Street. Only service parking and several handicapped parking spaces are nearby the facility. The adjacent sidewalks lead to a sidewalk system that serves all entrances and the entire campus.

### EXTERIOR STRUCTURE

It is recommended that aged and inefficient exterior glass storefront entry door systems be replaced. This project includes only the primary entrance doors. The replacement units should maintain the architectural design aspects of this facility and be modern, energy-efficient applications. The remaining secondary and service doors are satisfactory.

It is recommended that the single pane, aluminum-framed original window applications on the first floor be upgraded to thermal pane systems. Such double pane systems will reduce the energy required to operate the building. Repair or replacement of the windowsills and trim may also be necessary. As previously mentioned, the window systems on the second through tenth floors have been replaced with energy-efficient, dual pane systems.

The flat single ply membrane roofing system is not expected to outlast the scope of this analysis. Future budget modeling should include a provision for the replacement of the entire roofing system in the next ten years. Replace this roof with a similar application or the campus standard.

## INTERIOR FINISHES / SYSTEMS

The common areas within the facility, such as the corridors, study lounges, social rooms, and the coordinator's office, are generally carpeted, with the exception of the first floor common areas, including the living, recreation, and vending rooms, which are primarily terrazzo. The individual dormitory rooms have vinyl floor tile, along with the laundries and housekeeping space. Carpet and vinyl tile floor finish upgrades should be considered as part of any future cosmetic improvements or major comprehensive renovation efforts. The ceramic tile applications within the bathrooms appear to be sound and should provide satisfactory service over the next ten years.

The interior walls are all painted and constructed of either masonry block or sheetrock partitions. Most of the ceilings within the facility are painted, although there are some suspended grid acoustical tile systems in the first floor common areas. Wall and ceiling finishes should be repainted as part of future cosmetic improvements or major comprehensive renovation efforts. The interior doors are in satisfactory condition and should outlast the ten-year scope of this analysis.

## ACCESSIBILITY

Current legislation related to accessibility requires that building entrances be wheelchair accessible. There are several sidewalk locations immediately adjacent to the building and leading to the building that have exterior steps that require handrails to be installed in accordance with handicapped accessibility guidelines. To comply with the intent of this legislation, it is recommended that compliant painted metal handrails be installed at the sidewalk steps leading to the facility from the northwest as required.

Current accessibility legislation requires that building amenities be generally accessible to all persons. The configurations of the first floor's common kitchenette and the drinking fountains located on each floor are barriers to accessibility. The installation of wheelchair-accessible kitchenette cabinetry is recommended where applicable. All single level drinking fountains throughout the building should be replaced with dual level, refrigerated units.

While the interior doors are suitable for ten future years of service, the knob actuated door hardware presents a barrier to accessibility. Accessibility legislation requires that door hardware be designed for operation by people with little or no ability to grasp objects with their hands. To comply with the intent of this legislation, it is recommended that lever handle door hardware be installed on all doors that currently still have knobs. In addition, the signage to the permanent spaces is non-compliant. It is recommended that all non-compliant signage be upgraded to conform to appropriate accessibility standards. Compliant signage should meet specific size, graphical, Braille, height, and location requirements. This scope includes all directional signage.

There are minimal handicapped accessible features within this residential facility primarily aimed at handicapped guests. A handicapped accessible unisex restroom is located on the first floor by the mailroom, and some minor modifications have been made within the bathrooms on each floor. Provisions for resident accessibility for this facility are recommended. These should include the installation of ADA compliant signage, a wheelchair accessible bathroom facility, accessible storage space, specialized alarms, lever door hardware, and the adaptation of a sleeping room. To comply with the intent of the current accessibility legislation, it is recommended that at least two residential units be converted within this facility.

The overall level of bathroom accessibility is good but short of full compliance with modern accessibility legislation. While the clearances and clear floor spaces are adequate, compliant mirrors and new accessible plumbing fixtures are recommended over the next ten years in the common bathrooms on floors two through ten.

Current legislation regarding building accessibility by the handicapped requires that stairs have graspable handrails on both sides, that the rails have specific cross-sectional geometry, and that the handrails continue horizontally at the landings with extensions. In addition, guardrails must prevent the passage of a 4 inch diameter sphere (6 inches in the triangle formed by the lower rail and tread / riser angle). Although the stairs are compliant with the code enforced at the time of construction until a major renovation occurs, they are deficient in handrail and guardrail design relative to current standards. Future renovation efforts should include comprehensive stair railing upgrades.

## HEALTH

Based on the date of original construction and latest renovations, it is highly possible that lead paint or asbestos containing material (ACM) were used in the construction of this facility. However, no lead paint or suspected asbestos was observed during the inspection of the building. The lead paint and asbestos health risks are minimal, but workers present during any and all remodeling should be made aware of the potential hazards of working with such materials.

## FIRE / LIFE SAFETY

The paths of egress in this building are adequate in regard to fire rating. There are no compromises involving doors, partitions, elevators lobbies, or stairs. No fire or life safety issues related to architectural features were observed during the inspection of this facility.

The building is protected by a central fire alarm system. The point addressable fire alarm control panel was manufactured by Simplex and is located on the ground floor. The devices that serve this system include manual pull stations, audible / visible devices, and smoke detectors. The fire alarm system is adequate and in good condition. With proper testing and maintenance, it will outlast the purview of this analysis.

This facility is not protected by any form of automatic fire suppression. Manual, dry chemical fire extinguishers are available. However, it is recommended that an automatic fire suppression system be retrofitted. Install an automatic fire sprinkler system in unprotected areas throughout the facility. This project will reduce overall liability and the potential for loss. The project outline includes a budget for the installation of a fire pump.

Exit signs in the facility are LED-illuminated and are connected to the emergency power network. Emergency lighting is available through standard interior light fixtures with battery backup ballasts. All egress lighting systems are adequate and in good condition. There are no related projects to recommend at this time.

## HVAC

The facility is connected to the campus steam loop. Steam is supplied to a heat exchanger in the main mechanical room that produces heating hot water. The hot water is then circulated throughout the building by pumps to the associated HVAC equipment to heat the facility. The heat exchanger and pumps appear to be newer installations and should continue to provide heating hot water for the facility.

The facility incorporates a hydronic system that heats the individual student rooms. This system is original to the construction of the facility and is showing signs of age. It is recommended that the hydronic heating system be replaced.

Heating and cooling for the common areas of the facility are provided by multizone air handling equipment. The units are equipped with hot water coils for heating and DX refrigerant for cooling. The equipment is located on the roof and ground floor. The units were installed in 2004 and appear to be in good condition. No projects are recommended for the air handling equipment.

Cooling for the student rooms in this facility is provided by through-wall air conditioning units. These systems are currently in good working order. However, it should be anticipated that they will require replacement within the scope of this report.

## ELECTRICAL

Power is supplied to the facility at a rate of 120/208 volts from an oil-filled transformer located onsite. The unit is rated at 750 kVA and was installed in 2004. It is then distributed by a switchgear device that is rated for 2,000 amp service and was manufactured by Square D. All of the main electrical distribution system components are serviceable and will likely remain so throughout the scope of this report.

The secondary electrical consists of panelboards located throughout the facility. Power is distributed from these panelboards in the form of mechanical, lighting, and general purpose loads. The secondary electrical system appears to be mostly original, with some upgrades where new circuits have been installed on each floor to handle the window air conditioning units in the student rooms. However, the electrical devices in this facility are aged and visibly worn. It should be anticipated that the electrical distribution network will no longer be able to support normal loads and expansion. Replace this network within the scope of this analysis.

The interior lighting is a combination of new and original fixtures. New lay-in fixtures or surface-mount fixtures that contain T8 bulbs are present in corridors and common spaces. These light fixtures are in good condition and require no recommendations. Student rooms contain overhead surface-mount fixtures that are possibly original with ballast upgrades. It is recommended that all original or aged student room lighting be replaced in a project representing approximately 60 percent of the facility. Specify energy-efficient light fixtures for the new interior lighting systems.

The exterior areas adjacent to the building are illuminated by building-mounted high intensity discharge (HID), compact fluorescent, and stanchion-mounted fixtures. These exterior lighting systems appear to be in good condition and provide adequate coverage. No projects are recommended for the exterior lighting.

Emergency power for this facility is produced by a local diesel-fired emergency generator. This unit has a 12 kW capacity, generates 120/208 volt power, and was manufactured by Onan. This generator has served beyond its intended life cycle. In order to provide reliable emergency power to the critical systems in this facility, it is recommended that the generator be replaced.

## PLUMBING

The main incoming domestic water enters the facility in the main mechanical room on the ground floor. Copper piping is then utilized to distribute water throughout the facility. The system appears to be in average condition, with a combination of new and aged piping. An upgrade project is recommended to replace the original or aged domestic water piping. Additionally, no backflow preventer was observed on the system. Install backflow devices as needed to protect the water supply.

The drain piping network consists of cast-iron piping with bell-and-spigot and no-hub connections. The piping network appears to be a combination of new and aged piping where repairs have taken place, indicating that the older piping is starting to fail. Remove the existing sanitary and storm drain piping. Install new cast-iron drain piping networks with copper runouts to all fixtures. Install new floor drains, roof drains, and traps as needed.

The plumbing fixtures consist of ceramic and stainless steel construction and appear to be original. The units utilize hand operation control. It is recommended that the plumbing fixtures be upgraded. This action is detailed in the Accessibility section of this report.

Domestic water for this facility is heated by heat exchangers that utilize steam. The units have served beyond their expected life cycle, and the insulation is worn and showing signs of age. It is recommended that the units be replaced.

A booster pump pack aids in the pressurization of the domestic water system in this building. This system is currently adequate and appears to be a newer installation. No projects are recommended for the booster pump system at this time.

## VERTICAL TRANSPORTATION

The University commissioned an outside contractor to perform an elevator condition study in 2009. The aforementioned study did not identify any deficiencies requiring capital funding.

Note: The deficiencies outlined in this report were noted from a visual inspection. ISES engineers and architects developed projects with related costs that are needed over the next ten-year period to bring the facility to “like-new” condition. The costs developed do not represent the cost of a complete facility renovation. Soft costs not represented in this report include telecommunications, furniture, window treatment, space change, program issues, relocation, swing space, contingency, or costs that could not be identified or determined from the visual inspection and available building information. However, existing fixed building components and systems were thoroughly inspected. The developed costs represent correcting existing deficiencies and anticipated life cycle failures (within a ten-year period) to bring the facility to modern standards without any anticipation of change to facility space layout or function. Please refer to Section Three of this report for recommended Specific Project Details.

### C. INSPECTION TEAM DATA

**DATE OF INSPECTION:** September 16, 2009

**INSPECTION TEAM PERSONNEL:**

<u>NAME</u>	<u>POSITION</u>	<u>SPECIALTY</u>
Thomas Ferguson, AIA, LEED® AP	Project Architect	Interior Finishes / Exterior / ADA- Handicapped Accessibility / Site / Fire Safety / Life Safety / Health
Rob Gasaway, Q.E.I.	Facility Analyst	Interior Finishes / Exterior / ADA- Handicapped Accessibility / Site / Fire Safety / Life Safety / Health
John Holder, Q.E.I.	Project Engineer	Mechanical / Electrical / Plumbing / Energy / Fire Safety / Life Safety / Health
Imelda Jordan	Project Engineer	Mechanical / Electrical / Plumbing / Energy / Fire Safety / Life Safety / Health
James Lewis	Project Engineer	Mechanical / Electrical / Plumbing / Energy / Fire Safety / Life Safety / Health
Carl Mason, PE, BSCP	Project Engineer	Interior Finishes / Exterior / ADA- Handicapped Accessibility / Site / Fire Safety / Life Safety / Health
Paul Southwell	Project Engineer	Mechanical / Electrical / Plumbing / Energy / Fire Safety / Life Safety / Health
Norm Teahan, RA, AIA, NCARB	Project Architect	Interior Finishes / Exterior / ADA- Handicapped Accessibility / Site / Fire Safety / Life Safety / Health

**FACILITY CONTACTS:**

<u>NAME</u>	<u>POSITION</u>
William Bagwell	Associate Vice Chancellor, Campus Operations

**REPORT DEVELOPMENT:**

Report Development by: ISES Corporation  
2165 West Park Court  
Suite N  
Stone Mountain, GA 30087

Contact: Kyle Thompson, Project Manager  
770-879-7376

## D. FACILITY CONDITION ANALYSIS - DEFINITIONS

The following information is a clarification of Asset Report Sections using example definitions.

### 1. REPORT DESCRIPTION

Section 1: Asset Executive Summary, Asset Summary, and General Report Information

Section 2: Detailed Project Summaries and Totals

- A. Detailed Project Totals – Matrix with FCNI Data and Associated Charts
- B. Detailed Projects by Priority Class / Priority Sequence
- C. Detailed Projects by Cost within range [ \$0 - < \$100,000 ]
- D. Detailed Projects by Cost within range [ ≥ \$100,000 - < \$500,000 ]
- E. Detailed Projects by Cost within range [ ≥ \$500,000 ]
- F. Detailed Projects by Project Classification
- G. Detailed Projects by Project Rating Type - Energy Conservation
- H. Detailed Projects by Category / System Code

FCNI = Facility Condition Needs Index, Total Cost vs. Replacement Cost. The FCNI provides a life cycle cost comparison. Facility replacement cost is based on replacement with current construction standards for facility use type, and not original design parameters. This index gives the University a comparison within all buildings for identifying worst case / best case building conditions.

$$\text{FCNI} = \frac{\text{Deferred Maintenance / Modernization} + \text{Capital Renewal} + \text{Plant Adaption}}{\text{Plant / Facility Replacement Cost}}$$

Section 3: Specific Project Details Illustrating Description / Cost

Section 4: Drawings with Iconography

The drawings for this facility are marked with ICONS (see legend), denoting the specific location(s) for each project. Within each ICON is the last four characters of the respective project number (e.g., 0001IS01 is marked on plan by IS01). There is one set of drawings marked with ICONS representing all priority classes (1, 2, 3, and 4).

Section 5: Life Cycle Model Summary and Projections

Section 6: Photographic Log



## 2. PROJECT CLASSIFICATION

- A. Plant / Program Adaption: Expenditures required to adapt the physical plant to the evolving needs of the institution and to changing codes or standards. These are expenditures beyond normal maintenance. Examples include compliance with changing codes (e.g. accessibility), facility alterations required by changed teaching or research methods, and improvements occasioned by the adoption of modern technology (e.g., the use of personal computer networks).
- B. Deferred Maintenance: Refers to expenditures for repairs which were not accomplished as a part of normal maintenance or capital repair which have accumulated to the point that facility deterioration is evident and could impair the proper functioning of the facility. Costs estimated for deferred maintenance projects should include compliance with applicable codes, even if such compliance requires expenditures beyond those essential to affect the needed repairs. Deferred maintenance projects represent catch up expenses.
- C. Capital Renewal: A subset of regular or normal facility maintenance which refers to major repairs or the replacement / rebuilding of major facility components (e.g., roof replacement at the end of its normal useful life is capital repair; roof replacement several years after its normal useful life is deferred maintenance).

## 3. PROJECT SUBCLASS TYPE

- A. Energy Conservation: Projects with energy conservation opportunities, based on simple payback analysis.

## 4. PRIORITY SEQUENCE BY PRIORITY CLASS (Shown in Sections 2 and 3)

All projects are assigned both a Priority Sequence number and Priority Class number for categorizing and sorting projects based on criticality and recommended execution order.

Example:

	<u>PRIORITY CLASS 1</u>	
CODE	PROJECT NO.	PRIORITY SEQUENCE
HV2C	0001HV04	01
PL1D	0001PL02	02

	<u>PRIORITY CLASS 2</u>	
CODE	PROJECT NO.	PRIORITY SEQUENCE
IS1E	0001IS06	03
EL4C	0001EL03	04

## 5. PRIORITY CLASS (Shown in Sections 2 and 3)

### PRIORITY 1 - Currently Critical (Immediate)

Projects in this category require immediate action to:

- a. return a facility to normal operation
- b. stop accelerated deterioration
- c. correct a cited safety hazard

### PRIORITY 2 - Potentially Critical (Year One)

Projects in this category, if not corrected expeditiously, will become critical within a year. Situations in this category include:

- a. intermittent interruptions
- b. rapid deterioration
- c. potential safety hazards

### PRIORITY 3 - Necessary - Not Yet Critical (Years Two to Five)

Projects in this category include conditions requiring appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further.

### PRIORITY 4 - Recommended (Years Six to Ten)

Projects in this category include items that represent a sensible improvement to existing conditions. These items are not required for the most basic function of a facility; however, Priority 4 projects will either improve overall usability and / or reduce long-term maintenance.

## 6. COST SUMMARIES AND TOTALS

The cost summaries and totals are illustrated by Detailed Projects sorted in multiple formats (shown in Sections 2 and 3).

City Index material / labor cost factors: (shown in Sections 2 and 3)

Cost factors are based on the Greenville City Index and are adjusted for material and labor cost factors (2009). Refer to the project related labor report found later in this section.

#### Global Markup Percentages

#### R.S. MEANS

Local Labor Index:	51.3 %	of National Average
Local Materials Index:	100.7 %	of National average
General Contractor Markup:	20.0 %	Contractor profit & overhead, bonds & insurance
Professional Fees:	16.0 %	Arch. / Eng. Firm design fees and in-house design cost

**7. PROJECT NUMBER** (Shown in Sections 2 and 3)

Example:

Project Number = 0001-EL-04 (unique for each independent project)

- 0001 - Building Identification Number
- EL - System Code, EL represents Electrical
- 04 - Sequential Assignment Project Number by Category / System

**8. PHOTO NUMBER** (Shown in Section 6)

A code shown on the Photographic Log identifies the building number, photo sequence, and architect, engineer, or vertical transportation.

Example: 0001006e

<u>Building Number</u>	<u>Photo Sequence</u>	<u>Arch / Eng / VT</u>
0001	006	e

**9. LIFE CYCLE COST MODEL DESCRIPTION AND DEFINITIONS** (Shown in Section 5)

Included in this report is a Life Cycle Cost Model. This model consists of two elements, one is the component listing (starting on page 5.1.1) and the other is the Life Cycle Cost Projections Graph (page 5.2.1). The component list is a summary of all major systems and components within the facility. Each indicated component has the following associated information:

Uniformat Code	This is the standard Uniformat Code that applies to the component
Component Description	This line item describes the individual component
Qty	The quantity of the listed component
Units	The unit of measure associated with the quantity
Unit Cost	The cost to replace each individual component unit (This cost is in today's dollars)
Total Cost	Unit cost multiplied by Quantity, also in today's dollars. Note that this is a one time renewal / replacement cost
Install Date	Year that the component was installed. Where this data is not available, it defaults to the year the asset was constructed
Life Exp	Average life expectancy for each individual component

The component listing forms the basis for the Life Cycle Cost Projections Graph shown on page 5.2.1. This graph represents a projection over a fifty-year period (starting from the date the report is run) of expected component renewals based on each individual item's renewal cost and life span. Some components might require renewal several times within the fifty-year model, while others might not occur at all. Each individual component is assigned a renewal year based on life cycles, and the costs for each item are inflated forward to the appropriate year. The vertical bars shown on the graph represent the accumulated (and inflated) total costs for each individual year. At the bottom of the graph, the average annual cost per gross square foot (\$/GSF) is shown for the facility. In this calculation, all costs are not inflated. This figure can be utilized to assess the adequacy of existing capital renewal and repair budgets.

**10. CATEGORY CODE** (Shown in Sections 2 and 3)

Refer to the following Category Code Report.

Example: Category Code = EL5A

EL = System Description  
5 = Component Description  
A = Element Description

**CATEGORY CODE**

AC1A - AC4B  
EL1A - EL8A  
ES1A - ES6E  
FS1A - FS6A  
HE1A - HE7A  
HV1A - HV8B  
IS1A - IS6D  
PL1A - PL5A  
SI1A - SI4A  
SS1A - SS7A  
VT1A - VT7A

**SYSTEM DESCRIPTION**

ACCESSIBILITY  
ELECTRICAL  
EXTERIOR STRUCTURE  
FIRE / LIFE SAFETY  
HEALTH  
HVAC  
INTERIOR FINISHES / SYSTEMS  
PLUMBING  
SITE  
SECURITY SYSTEMS  
VERTICAL TRANSPORTATION

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
<b>SYSTEM DESCRIPTION: ACCESSIBILITY</b>			
AC1A	SITE	STAIR AND RAILINGS	Includes exterior stairs and railings which are not part of the building entrance points.
AC1B	SITE	RAMPS AND WALKS	Includes sidewalks, grade change ramps (except for a building entrance), curb ramps, etc.
AC1C	SITE	PARKING	Designated parking spaces including striping, signage, access aisles and ramps, etc.
AC1D	SITE	TACTILE WARNINGS	Raised tactile warnings located at traffic crossing and elevation changes.
AC2A	BUILDING ENTRY	GENERAL	Covers all aspects of entry into the building itself including ramps, lifts, doors and hardware, power operators, etc.
AC3A	INTERIOR PATH OF TRAVEL	LIFTS/RAMPS/ELEVATORS	Interior lifts, ramps and elevators designed to accommodate level changes inside a building. Includes both installation and retrofitting.
AC3B	INTERIOR PATH OF TRAVEL	STAIRS AND RAILINGS	Upgrades to interior stairs and handrails for accessibility reasons.
AC3C	INTERIOR PATH OF TRAVEL	DOORS AND HARDWARE	Accessibility upgrades to the interior doors including widening, replacing hardware power, assisted operators, etc.
AC3D	INTERIOR PATH OF TRAVEL	SIGNAGE	Interior building signage upgrades for compliance with ADA.
AC3E	INTERIOR PATH OF TRAVEL	RESTROOMS/BATHROOMS	Modifications to and installation of accessible public restrooms and bathrooms. Bathrooms, which are an integral part of residential suites, are catalogued under HC4A.
AC3F	INTERIOR PATH OF TRAVEL	DRINKING FOUNTAINS	Upgrading/replacing drinking fountains for reasons of accessibility.
AC3G	INTERIOR PATH OF TRAVEL	PHONES	Replacement/modification of public access telephones.
AC4A	GENERAL	FUNCTIONAL SPACE MODIFICATIONS	This category covers all necessary interior modifications necessary to make the services and functions of a building accessible. It includes installation of assistive listening systems, modification of living quarters, modifications to laboratory workstations, etc. Bathrooms, which are integral to efficiency suites, are catalogued here.
AC4B	GENERAL	OTHER	All accessibility issues not catalogued elsewhere.
<b>SYSTEM DESCRIPTION: ELECTRICAL</b>			
EL1A	INCOMING SERVICE	TRANSFORMER	Main building service transformer.
EL1B	INCOMING SERVICE	DISCONNECTS	Main building disconnect and switchgear.
EL1C	INCOMING SERVICE	FEEDERS	Incoming service feeders. Complete incoming service upgrades, including transformers, feeders, and main distribution panels are catalogued here.
EL1D	INCOMING SERVICE	METERING	Installation of meters to record consumption and/or demand.
EL2A	MAIN DISTRIBUTION PANELS	CONDITION UPGRADE	Main distribution upgrade due to deficiencies in condition.
EL2B	MAIN DISTRIBUTION PANELS	CAPACITY UPGRADE	Main distribution upgrades due to inadequate capacity.
EL3A	SECONDARY DISTRIBUTION	STEP DOWN TRANSFORMERS	Secondary distribution stepdown and isolation transformers.
EL3B	SECONDARY DISTRIBUTION	DISTRIBUTION NETWORK	Includes conduit, conductors, sub-distribution panels, switches, outlets, etc. Complete interior rewiring of a facility is catalogued here.
EL3C	SECONDARY DISTRIBUTION	MOTOR CONTROLLERS	Mechanical equipment motor starters and control centers.
EL4A	DEVICES AND FIXTURES	EXTERIOR LIGHTING	Exterior building lighting fixtures including supply conductors and conduit.
EL4B	DEVICES AND FIXTURES	INTERIOR LIGHTING	Interior lighting fixtures (also system wide emergency lighting) including supply conductors and conduits.
EL4C	DEVICES AND FIXTURES	LIGHTING CONTROLLERS	Motion sensors, photocell controllers, lighting contactors, etc.

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
EL4D	DEVICES AND FIXTURES	GFCI PROTECTION	Ground fault protection including GFCI receptacles and breakers.
EL4E	DEVICES AND FIXTURES	LIGHTNING PROTECTION	Lightning arrestation systems including air terminals and grounding conductors.
EL5A	EMERGENCY POWER SYSTEM	GENERATION/DISTRIBUTION	Includes generators, central battery banks, transfer switches, emergency power grid, etc.
EL6A	SYSTEMS	UPS/DC POWER SUPPLY	Uninterruptible power supply systems and DC motor-generator sets and distribution systems.
EL7A	INFRASTRUCTURE	ABOVE GROUND TRANSMISSION	Includes poles, towers, conductors, insulators, fuses, disconnects, etc.
EL7B	INFRASTRUCTURE	UNDERGROUND TRANSMISSION	Includes direct buried feeders, ductbanks, conduit, manholes, feeders, switches, disconnects, etc.
EL7C	INFRASTRUCTURE	SUBSTATIONS	Includes incoming feeders, breakers, buses, switchgear, meters, CTs, PTs, battery systems, capacitor banks, and all associated auxiliary equipment.
EL7D	INFRASTRUCTURE	DISTRIBUTION SWITCHGEAR	Stand-alone sectionalizing switches, distribution switchboards, etc.
EL7F	INFRASTRUCTURE	AREA AND STREET LIGHTING	Area and street lighting systems including stanchions, fixtures, feeders, etc.
EL8A	GENERAL	OTHER	Electrical system components not catalogued elsewhere.
<b>SYSTEM DESCRIPTION: EXTERIOR</b>			
ES1A	FOUNDATION/FOOTING	STRUCTURE	Structural foundation improvements involving structural work on foundation wall/footing, piers, caissons, piles including crack repairs, shoring & pointing
ES1B	FOUNDATION/FOOTING	DAMPPROOFING/DEWATERING	Foundation/footing waterproofing work including, damp proofing, dewatering, insulation, etc.
ES2A	COLUMNS/BEAMS/WALLS	STRUCTURE	Structural work to primary load-bearing structural components aside from floors including columns, beams, bearing walls, lintels, arches, etc.
ES2B	COLUMNS/BEAMS/WALLS	FINISH	Work involving restoration of the appearance and weatherproof integrity of exterior wall/structural envelope components including masonry/pointing, expansion joints, efflorescence & stain removal, grouting, surfacing, chimney repairs, etc.
ES3A	FLOOR	STRUCTURE	Work concerning the structural integrity of the load supporting floors both exposed and unexposed including deformation, delamination, spalling, shoring, crack repair, etc.
ES4A	ROOF	REPAIR	Work on waterproof horizontal finish (roof) involving repair and/or limited replacement (<40% total) including membrane patching, flashing repair, coping caulk/resetting, PPT wall parging/coating, walkpad installation, skylight and roof hatch R&R, etc.
ES4B	ROOF	REPLACEMENT	Work involving total refurbishment of roofing system including related component rehab.
ES5A	FENESTRATIONS	DOORS	Work on exterior exit/access door including storefronts, airlocks, air curtains, vinyl slat doors, all power/manual operating hardware (except handicapped), etc.
ES5B	FENESTRATIONS	WINDOWS	Work on exterior fenestration closure & related components including glass/metal/wood curtain walls, fixed or operable window sashes, glazing, frames, sills, casings, stools, seats, coatings, treatments, screens, storm windows, etc.
ES6A	GENERAL	ATTACHED STRUCTURE	Work on attached exterior structure components not normally considered in above categories including porches, stoops, decks, monumental entrance stairs, cupolas, tower, etc.
ES6B	GENERAL	AREAWAYS	Work on attached grade level or below structural features including subterranean light wells, areaways, basement access stairs, etc.
ES6C	GENERAL	TRIM	Work on ornamental exterior (generally non-structural) elements including beltlines, quoins, porticos, soffits, cornices, moldings, trim, etc.
ES6D	GENERAL	SUPERSTRUCTURE	Finish and structural work on non-standard structures with exposed load-bearing elements such as stadiums, bag houses, bleachers, freestanding towers, etc.

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
ES6E	GENERAL	OTHER	Any exterior work not specifically categorized elsewhere including finish and structural work on freestanding boiler stacks.
<b>SYSTEM DESCRIPTION: FIRE / LIFE SAFETY</b>			
FS1A	LIGHTING	EGRESS LIGHTING/EXIT SIGNAGE	R & R work on exit signage and packaged AC/DC emergency lighting.
FS2A	DETECTION/ALARM	GENERAL	Repair or replacement of fire alarm/detection system/components including alarms, pull boxes, smoke/heat detectors, annunciator panels, central fire control stations, remote dialers, fire station communications, etc.
FS3A	SUPPRESSION	SPRINKLERS	Repair or installation of water sprinklers type automatic fire suppressions including wet pipe & dry pipe systems, heads, piping, deflectors, valves, monitors, associated fire pump, etc.
FS3B	SUPPRESSION	STANDPIPE/HOSE	Repair or installation of standpipe system or components including hardware, hoses, cabinets, nozzles, necessary fire pumping system, etc.
FS3C	SUPPRESSION	EXTINGUISHERS	Repairs or upgrades to F.E. cabinets/wall fastenings and handheld extinguisher testing/replacement.
FS3D	SUPPRESSION	OTHER	Other fire suppression items not specifically categorized elsewhere including fire blankets, carbon dioxide automatic systems, Halon systems, dry chemical systems, etc.
FS4A	HAZARDOUS MATERIALS	STORAGE ENVIRONMENT	Installation or repair of special storage environment for the safe holding of flammable or otherwise dangerous materials/supplies including vented flammables storage cabinets, holding pens/rooms, cages, fire safe chemical storage rooms, etc.
FS4B	HAZARDOUS MATERIALS	USER SAFETY	Improvements, repairs, installation, or testing of user safety equipment including emergency eyewashes, safety showers, emergency panic/shut-down system, etc.
FS5A	EGRESS PATH	DESIGNATION	Installation, relocation or repair of posted diagrammatic emergency evacuation routes.
FS5B	EGRESS PATH	DISTANCE/GEOMETRY	Work involving remediation of egress routing problems including elimination of dead end corridors, excessive egress distance modifications and egress routing inadequacies.
FS5C	EGRESS PATH	SEPARATION RATING	Restoration of required fire protective barriers including wall rating compromises, fire rated construction, structural fire proofing, wind/safety glazing, transom retrofitting, etc.
FS5D	EGRESS PATH	OBSTRUCTION	Clearance of items restricting the required egress routes.
FS5E	EGRESS PATH	STAIRS RAILING	Retrofit of stair/landing configurations/structure, railing heights/geometries, etc.
FS5F	EGRESS PATH	FIRE DOORS/HARDWARE	Installation/replacement/repair of fire doors and hardware including labeled fire doors, fire shutters, closers, magnetic holders, panic hardware, etc.
FS5G	EGRESS PATH	FINISH/FURNITURE RATINGS	Remediation of improper fire/smoke ratings of finishes and furniture along egress routes.
FS6A	GENERAL	OTHER	Life/fire safety items not specifically categorized elsewhere.
<b>SYSTEM DESCRIPTION: HEALTH</b>			
HE1A	ENVIRONMENTAL CONTROL	EQUIPMENT AND ENCLOSURES	Temperature control chambers (both hot and cold) for non-food storage. Includes both chamber and all associated mechanical equipment.
HE1B	ENVIRONMENTAL CONTROL	OTHER	General environmental control problems not catalogued elsewhere.
HE2A	PEST CONTROL	GENERAL	Includes all measures necessary to control and destroy insects, rodents and other pests.
HE3A	REFUSE	GENERAL	Issues related to the collection, handling and disposal of refuse.
HE4A	SANITATION EQUIPMENT	LABORATORY AND PROCESS	Includes autoclaves, cage washers, steam cleaners, etc.
HE5A	FOOD SERVICE	KITCHEN EQUIPMENT	Includes ranges, grilles, cookers, sculleries, etc.
HE5B	FOOD SERVICE	COLD STORAGE	Includes the cold storage room and all associated refrigeration equipment.



CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
HE6A	HAZARDOUS MATERIAL	STRUCTURAL ASBESTOS	Testing, abatement and disposal of structural and building finish materials containing asbestos.
HE6B	HAZARDOUS MATERIAL	MECHANICAL ASBESTOS	Testing, abatement and disposal of mechanical insulation materials containing asbestos.
HE6C	HAZARDOUS MATERIAL	PCBs	Includes testing, demolition, disposal and cleanup of PCB contaminated substances.
HE6D	HAZARDOUS MATERIAL	FUEL STORAGE	Includes monitoring, removal and replacement of above and below ground fuel storage and distribution systems. Also includes testing and disposal of contaminated soils.
HE6E	HAZARDOUS MATERIAL	LEAD PAINT	Testing, removal and disposal of lead-based paint systems.
HE6F	HAZARDOUS MATERIAL	OTHER	Handling, storage, and disposal of other hazardous materials.
HE7A	GENERAL	OTHER	Health related issues not catalogued elsewhere.
<b>SYSTEM DESCRIPTION: HVAC</b>			
HV1A	HEATING	BOILERS/STACKS/ CONTROLS	Boilers for heating purposes including their related stacks, flues, and controls.
HV1B	HEATING	RADIATORS/ CONVECTORS	Including cast iron radiators, fin tube radiators, baseboard radiators, etc.
HV1C	HEATING	FURNACE	Furnaces and their related controls, flues, etc.
HV1D	HEATING	FUEL SUPPLY/STORAGE	Storage and/or distribution of fuel for heating purposes, including tanks and piping networks and related leak detection/monitoring.
HV2A	COOLING	CHILLERS/ CONTROLS	Chiller units for production of chilled water for cooling purposes, related controls (not including mods for CFC compliance).
HV2B	COOLING	HEAT REJECTION	Repair/replacement of cooling towers, dry coolers, air-cooling and heat rejection. (Includes connection of once-through system to cooling tower.)
HV3A	HEATING/COOLING	SYSTEM RETROFIT/ REPLACE	Replacement or major retrofit of HVAC systems.
HV3B	HEATING/COOLING	WATER TREATMENT	Treatment of hot water, chilled water, steam, condenser water, etc.
HV3C	HEATING/COOLING	PACKAGE/SELF-CONTAINED UNITS	Repair/replacement of self-contained/package type units including stand up units, rooftop units, window units, etc; both air conditioners and heat pumps.
HV3D	HEATING/COOLING	CONVENTIONAL SPLIT SYSTEMS	Repair, installation, or replacement of conventional split systems; both air conditioners and heat pumps including independent component replacements of compressors and condensers.
HV4A	AIR MOVING/ VENTILATION	AIR HANDLERS/ FAN UNITS	Includes air handlers & coils, fan coil units, unit ventilators, filtration upgrades, etc., not including package/self-contained units, split systems or other specifically categorized systems.
HV4B	AIR MOVING/ VENTILATION	EXHAUST FANS	Exhaust fan systems including fans, range and fume hoods, controls, and related ductwork.
HV4C	AIR MOVING/ VENTILATION	OTHER FANS	Supply, return, or any other fans not incorporated into a component categorized elsewhere.
HV4D	AIR MOVING/ VENTILATION	AIR DISTRIBUTION NETWORK	Repair, replacement, or cleaning of air distribution network including ductwork, terminal reheat/cool, VAV units, induction units, power induction units, insulation, dampers, linkages, etc.
HV5A	STEAM/HYDRONIC DISTRIBUTION	PIPING NETWORK	Repair/replacement of piping networks for heating and cooling systems including pipe, fittings, insulation, related components, etc.
HV5B	STEAM/HYDRONIC DISTRIBUTION	PUMPS	Repair or replacement of pumps used in heating and cooling systems, related control components, etc.
HV5C	STEAM/HYDRONIC DISTRIBUTION	HEAT EXCHANGERS	Including shell and tube heat exchangers and plate heat exchangers for heating and cooling.
HV6A	CONTROLS	COMPLETE SYSTEM	Replacement of HVAC control systems.



CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
		UPGRADE	
HV6B	CONTROLS	MODIFICATIONS/ REPAIRS	Repair or modification of HVAC control system.
HV6C	CONTROLS	AIR COMPRESSORS/ DRYERS	Repair or modification of control air compressors and dryers.
HV7A	INFRASTRUCTURE	STEAM/HOT WATER GENERATION	Generation of central steam and/or hot water including boilers and related components.
HV7B	INFRASTRUCTURE	STEAM/HOT WATER DISTRIBUTION	Distribution system for central hot water and/or steam.
HV7C	INFRASTRUCTURE	CHILLED WATER GENERATION	Generation of central chilled water including chillers and related components.
HV7D	INFRASTRUCTURE	CHILLED WATER DISTRIBUTION	Distribution system for central chilled water.
HV7E	INFRASTRUCTURE	TUNNELS/ MANHOLES/ TRENCHES	Repairs, installation, replacement of utility system access chambers.
HV7F	INFRASTRUCTURE	OTHER	HVAC infrastructure issues not specifically categorized elsewhere.
HV8A	GENERAL	CFC COMPLIANCE	Chiller conversions/replacements for CFC regulatory compliance, monitoring, etc.
HV8B	GENERAL	OTHER	HVAC issues not catalogued elsewhere.
<b>SYSTEM DESCRIPTION: INTERIOR FINISHES / SYSTEMS</b>			
IS1A	FLOOR	FINISHES-DRY	R & R of carpet, hardwood strip flooring, concrete coating, vinyl linoleum & tile, marble, terrazzo, rubber flooring, underlayment in predominantly dry areas ("dry" includes non-commercial kitchens)
IS1B	FLOOR	FINISHES-WET	Flooring finish/underlayment work in predominantly "wet" areas including work with linoleum, rubber, terrazzo, concrete coating, quarry tile, ceramic tile, epoxy aggregate, etc.
IS2A	PARTITIONS	STRUCTURE	Structural work on full height permanent interior partitions including wood/metal stud & drywall systems, CMU systems, structural brick, tile, glass block, etc.
IS2B	PARTITIONS	FINISHES	Work on full height permanent interior partitions including R & R to gypsum board, plaster, lath, wood paneling, acoustical panels, wall coverings, column coverings, tile, paint, etc.
IS3A	CEILINGS	REPAIR	Repair of interior ceilings (<40% of total) including tiles, gypsum board, plaster, paint, etc.
IS3B	CEILINGS	REPLACEMENT	Major refurbishments (>40% of total) to interior ceiling systems including grid system replacements, structural framing, new suspended systems, paint, plastering, etc.
IS4A	DOORS	GENERAL	Any work on interior non-fire rated doors, roll-up counter doors, mechanical/plumbing access doors, and all door hardware (except for reasons of access improvement).
IS5A	STAIRS	FINISH	Any finish restorative work to stair tower walking surfaces including replacement of rubber treads, safety grips, nosings, etc. (except as required to accommodate disabled persons).
IS6A	GENERAL	MOLDING	R & R to interior trim/molding systems including rubber/vinyl/wood base, crown/chair/ornamental moldings, cased openings, etc.
IS6B	GENERAL	CABINETY	R & R work to interior casework systems including cabinets, countertops, wardrobes, lockers, mail boxes, built-in bookcases, lab/work benches, reagent shelving, etc. (except as required for access by the disabled).
IS6C	GENERAL	SCREENING	Work on temporary or partial height partitioning systems including toilet partitions, urinal/vanity screens, etc.
IS6D	GENERAL	OTHER	Any work on interior elements not logically or specifically categorized elsewhere including light coves, phone booths, interior light wells, etc.
<b>SYSTEM DESCRIPTION: PLUMBING</b>			

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
PL1A	DOMESTIC WATER	PIPING NETWORK	Repair or replacement of domestic water supply piping network, insulation, hangers, etc.
PL1B	DOMESTIC WATER	PUMPS	Domestic water booster pumps, circulating pumps, related controls, etc.
PL1C	DOMESTIC WATER	STORAGE/TREATMENT	Equipment or vessels for storage or treatment of domestic water.
PL1D	DOMESTIC WATER	METERING	Installation, repair, or replacement of water meters.
PL1E	DOMESTIC WATER	HEATING	Domestic water heaters including gas, oil, and electric water heaters, shell and tube heat exchangers, tank type and instantaneous.
PL1F	DOMESTIC WATER	COOLING	Central systems for cooling and distributing drinking water.
PL1G	DOMESTIC WATER	FIXTURES	Plumbing fixtures including sinks, drinking fountains, water closets, urinals, etc.
PL1H	DOMESTIC WATER	CONSERVATION	Alternations made to the water distribution system to conserve water.
PL1I	DOMESTIC WATER	BACKFLOW PROTECTION	Backflow protection devices including backflow preventers, vacuum breakers, etc.
PL2A	WASTEWATER	PIPING NETWORK	Repair or replacement of building wastewater piping network.
PL2B	WASTEWATER	PUMPS	Pump systems used to lift wastewater including sewage ejectors and other sump systems.
PL3A	SPECIAL SYSTEMS	PROCESS GAS/FLUIDS	Generation and/or distribution of process steam, compressed air, natural and LP gas, process water, vacuum, etc.
PL4A	INFRASTRUCTURE	POTABLE WATER STORAGE/TREATMENT	Storage and treatment of potable water for distribution.
PL4B	INFRASTRUCTURE	INDUSTRIAL WATER DISTRIBUTION/TREATMENT	Storage and treatment of industrial water for distribution.
PL4C	INFRASTRUCTURE	SANITARY WATER COLLECTION	Sanitary water collection systems, sanitary sewer systems; including combined systems.
PL4D	INFRASTRUCTURE	STORM WATER COLLECTION	Storm water collection systems, storm sewer systems; storm water only.
PL4E	INFRASTRUCTURE	POTABLE WATER DISTRIBUTION	Potable water distribution network.
PL4F	INFRASTRUCTURE	WASTEWATER TREATMENT	Wastewater treatment plants, associated equipment, etc.
PL5A	GENERAL	OTHER	Plumbing issues not categorized elsewhere.
<b>SYSTEM DESCRIPTION: SITE</b>			
SI1A	ACCESS	PEDESTRIAN	Paved pedestrian surfaces including walks, site stairs, step ramps, paths, pedestrian signage, sidewalk bridges/canopies, pedestrian plaza/mall areas, etc.
SI1B	ACCESS	VEHICULAR	Paved vehicular surfaces including roads, paths, curbs, guards, bollards, bridges, skyways, joints, shoulder work, culverts, ditches, vehicular signage, etc.
SI2A	LANDSCAPE	GRADE/FLORA	Landscape related work including new grass/turf refurbishment, grade improvements, catch basins, swales, berms, pruning, new ornamental flora, etc.
SI3A	HARDSCAPE	STRUCTURE	Permanent hard site features, predominantly ornamental, including terraces, fences, statues, freestanding signage, fountains, benches, etc.
SI4A	GENERAL	OTHER	Other site work not specifically categorized elsewhere.
<b>SYSTEM DESCRIPTION: SECURITY SYSTEMS</b>			
SS1A	LIGHTING	EXTERIOR	Fixtures, stanchions, foliage interference, cleanliness, locations, etc.

CATEGORY CODE REPORT			
CODE	COMPONENT DESCRIPTION	ELEMENT DESCRIPTION	DEFINITION
SS2A	SITE	FENCING	Perimeter campus fencing, individual building fencing, includes both pedestrian and vehicular control fences.
SS2B	SITE	GENERAL	Hidden areas due to foliage, fencing, parking, walls, etc.
SS3A	COMMUNICATIONS	EMERGENCY PHONES	Access, locations, visibility, function, reliability, etc.
SS4A	ACCESS CONTROL	DOORS	Access, locks, keys, two way speakers, reliability, redundancy, etc.
SS4B	ACCESS CONTROL	WINDOWS	Locks, screens, access, reliability, etc.
SS4C	ACCESS CONTROL	SYSTEMS	Card key, proximity devices, data control, data use, reliability, system design, etc.
SS5A	MONITORING	SYSTEMS	Cameras, audio communication, monitoring stations, locations, system design, etc.
SS6A	CIRCULATION	PEDESTRIAN	On campus as well as to and from off campus housing and class locations, etc.
SS6B	CIRCULATION	VEHICULAR	Guard gates, access, systems, data control and use, identification, etc.
SS7A	GENERAL	OTHER	General information/projects pertaining to security issues.
<b>SYSTEM DESCRIPTION: VERTICAL TRANSPORTATION</b>			
VT1A	MACHINE ROOM	GENERAL	Machine, worm gear, thrust bearing, brake, motors, sheaves, generator, controller, selector, governor, pump(s), valves, oil, access, lighting, ventilation, floor.
VT2A	CAR	GENERAL	Position indicator, lighting, floor, gate-doors, operation devices, safeties, safety shoe, light ray/detection, emergency light, fire fighter service, car top, door operator, stop switch, car frame, car guides, sheaves, phone, ventilation.
VT3A	HOISTWAY	GENERAL	Enclosure, fascia, interlock, doors, hangers, closers, sheaves, rails, hoistway switches, ropes, traveling cables, selector tape, weights, compensation.
VT4A	HALL FIXTURES	GENERAL	Operating panel, position indicator, hall buttons, lobby panel, hall lanterns, fire fighter service, audible signals, card/key access.
VT5A	PIT	GENERAL	Buffer(s), guards, sheaves, hydro packing, floor, lighting, safety controls.
VT6A	OPERATING CONDITIONS	GENERAL	Door open time, door close time, door thrust, acceleration, deceleration, leveling, dwell time, speed, OFR time, nudging.
VT7A	GENERAL	OTHER	General information/projects relating to vertical transportation system components.



FACILITY CONDITION ANALYSIS

**SECTION 2**

DETAILED PROJECT SUMMARIES  
AND TOTALS

**Detailed Project Totals  
 Facility Condition Analysis  
 System Code by Priority Class  
 GREE : GREENE RESIDENCE HALL**

System Code	System Description	Priority Classes				Subtotal
		1	2	3	4	
AC	ACCESSIBILITY	12,146	0	252,759	214,914	479,819
EL	ELECTRICAL	0	0	911,496	0	911,496
ES	EXTERIOR	0	0	54,348	99,720	154,068
FS	FIRE/LIFE SAFETY	0	746,250	0	0	746,250
HV	HVAC	0	0	385,071	218,520	603,591
IS	INTERIOR/FINISH SYS.	0	0	613,511	41,941	655,452
PL	PLUMBING	0	0	791,721	0	791,721
	<b>TOTALS</b>	12,146	746,250	3,008,906	575,094	4,342,395

<b>Facility Replacement Cost</b>	<b>\$25,697,000</b>
<b>Facility Condition Needs Index</b>	<b>0.17</b>


<b>Gross Square Feet</b>	<b>82,731</b>
--------------------------	---------------

<b>Total Cost Per Square Foot</b>	<b>\$52.49</b>
-----------------------------------	----------------

# FACILITY CONDITION ANALYSIS

## System Code by Priority Class

GREE : GREENE RESIDENCE HALL



**Detailed Project Totals  
 Facility Condition Analysis  
 System Code by Project Class  
 GREE : GREENE RESIDENCE HALL**

System Code	System Description	Project Classes			Subtotal
		Capitla Renewal	Deferred Maintenance	Plant Adaption	
AC	ACCESSIBILITY	0	0	479,819	479,819
EL	ELECTRICAL	0	911,496	0	911,496
ES	EXTERIOR	154,068	0	0	154,068
FS	FIRE/LIFE SAFETY	0	0	746,250	746,250
HV	HVAC	218,520	385,071	0	603,591
IS	INTERIOR/FINISH SYS.	240,536	414,916	0	655,452
PL	PLUMBING	0	791,721	0	791,721
	<b>TOTALS</b>	613,124	2,503,203	1,226,068	4,342,395

<b>Facility Replacement Cost</b>	<b>\$25,697,000</b>
<b>Facility Condition Needs Index</b>	<b>0.17</b>

<b>Gross Square Feet</b>	<b>82,731</b>
--------------------------	---------------


<b>Total Cost Per Square Foot</b>	<b>\$52.49</b>
-----------------------------------	----------------



# FACILITY CONDITION ANALYSIS

## System Code by Project Class

GREE : GREENE RESIDENCE HALL



**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Class by Priority Class**  
**GREE : GREENE RESIDENCE HALL**

Project Class	Priority Classes				Subtotal
	1	2	3	4	
Capital Renewal	0	0	252,944	360,181	613,124
Deferred Maintenance	0	0	2,503,203	0	2,503,203
Plant Adaption	12,146	746,250	252,759	214,914	1,226,068
<b>TOTALS</b>	12,146	746,250	3,008,906	575,094	4,342,395

Facility Replacement Cost	\$25,697,000
Facility Condition Needs Index	0.17


Gross Square Feet	82,731
-------------------	--------

Total Cost Per Square Foot	\$52.49
----------------------------	---------

# FACILITY CONDITION ANALYSIS

## Project Class by Priority Class

GREE : GREENE RESIDENCE HALL



Detailed Project Summary  
Facility Condition Analysis  
**Priority Class - Priority Sequence**  
GREE : GREENE RESIDENCE HALL

Cat. Code	Project Number	Pri Cls	Pri Seq	Project Title	Construction Cost	Professional Fee	Total Cost
AC2A	GREEAC05	1	1	BUILDING ENTRY ACCESSIBILITY UPGRADES	12,146	0	12,146
<b>Totals for Priority Class 1</b>					<b>12,146</b>		<b>12,146</b>
FS3A	GREEFS01	2	2	FIRE SPRINKLER SYSTEM INSTALLATION	643,319	102,931	746,250
<b>Totals for Priority Class 2</b>					<b>643,319</b>	<b>102,931</b>	<b>746,250</b>
AC4A	GREEAC06	3	3	INTERIOR AMENITY ACCESSIBILITY UPGRADES	39,438	6,310	45,748
AC4A	GREEAC02	3	4	ACCESSIBILITY UPGRADES FOR RESIDENTIAL FACILITIES	39,324	6,292	45,616
AC3B	GREEAC04	3	5	STAIR AND RAILING SAFETY UPGRADES	139,134	22,261	161,395
ES4B	GREEES03	3	6	MEMBRANE ROOF REPLACEMENT	46,852	7,496	54,348
HV5A	GREEHV01	3	7	REPLACE HYDRONIC HEATING SYSTEM	331,958	53,113	385,071
EL5A	GREEEL01	3	8	REPLACE EMERGENCY GENERATOR	65,305	10,449	75,754
EL3B	GREEEL03	3	9	UPGRADE ELECTRICAL DISTRIBUTION NETWORK	525,061	84,010	609,071
EL4B	GREEEL02	3	10	INTERIOR LIGHTING UPGRADE	195,406	31,265	226,671
IS1A	GREEIS01	3	11	REFINISH FLOORING	357,686	57,230	414,916
IS2B	GREEIS02	3	12	REFINISH WALLS	198,595	0	198,595
PL1A	GREEPL02	3	13	WATER SUPPLY PIPING REPLACEMENT	259,116	41,459	300,575
PL2A	GREEPL03	3	14	DRAIN PIPING REPLACEMENT	393,324	62,932	456,256
PL1E	GREEPL01	3	15	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT	30,077	4,812	34,889
<b>Totals for Priority Class 3</b>					<b>2,621,277</b>	<b>387,629</b>	<b>3,008,906</b>
AC3E	GREEAC03	4	16	RESTROOM ACCESSIBILITY UPGRADES	42,346	6,775	49,122
AC4B	GREEAC01	4	17	INTERIOR SIGNAGE AND DOOR HARDWARE UPGRADES	142,924	22,868	165,792
ES5A	GREEES01	4	18	EXTERIOR DOOR REPLACEMENT	14,483	2,317	16,801
ES5B	GREEES02	4	19	WINDOW REPLACEMENT	71,482	11,437	82,919
HV2B	GREEHV02	4	20	MODULAR COOLING EQUIPMENT REPLACEMENT	188,379	30,141	218,520
IS3B	GREEIS03	4	21	REFINISH CEILINGS	41,941	0	41,941
<b>Totals for Priority Class 4</b>					<b>501,556</b>	<b>73,538</b>	<b>575,094</b>
<b>Grand Total:</b>					<b>3,778,297</b>	<b>564,098</b>	<b>4,342,395</b>

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Cost Range**  
GREE : GREENE RESIDENCE HALL

<b>Cat. Code</b>	<b>Project Number</b>	<b>Pri Cls</b>	<b>Pri Seq</b>	<b>Project Title</b>	<b>Construction Cost</b>	<b>Professional Fee</b>	<b>Total Cost</b>
AC2A	GREEAC05	1	1	BUILDING ENTRY ACCESSIBILITY UPGRADES	12,146	0	12,146
<b>Totals for Priority Class 1</b>					<b>12,146</b>		<b>12,146</b>
EL5A	GREEEL01	3	8	REPLACE EMERGENCY GENERATOR	65,305	10,449	75,754
PL1E	GREEPL01	3	15	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT	30,077	4,812	34,889
AC4A	GREEAC02	3	4	ACCESSIBILITY UPGRADES FOR RESIDENTIAL FACILITIES	39,324	6,292	45,616
AC4A	GREEAC06	3	3	INTERIOR AMENITY ACCESSIBILITY UPGRADES	39,438	6,310	45,748
ES4B	GREEES03	3	6	MEMBRANE ROOF REPLACEMENT	46,852	7,496	54,348
<b>Totals for Priority Class 3</b>					<b>220,996</b>	<b>35,359</b>	<b>256,355</b>
AC3E	GREEAC03	4	16	RESTROOM ACCESSIBILITY UPGRADES	42,346	6,775	49,122
ES5A	GREEES01	4	18	EXTERIOR DOOR REPLACEMENT	14,483	2,317	16,801
ES5B	GREEES02	4	19	WINDOW REPLACEMENT	71,482	11,437	82,919
IS3B	GREEIS03	4	21	REFINISH CEILINGS	41,941	0	41,941
<b>Totals for Priority Class 4</b>					<b>170,253</b>	<b>20,530</b>	<b>190,783</b>
<b>Grand Totals for Projects &lt; 100,000</b>					<b>403,395</b>	<b>55,889</b>	<b>459,284</b>

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Cost Range**  
 GREE : GREENE RESIDENCE HALL

<b>Cat. Code</b>	<b>Project Number</b>	<b>Pri Cls</b>	<b>Pri Seq</b>	<b>Project Title</b>	<b>Construction Cost</b>	<b>Professional Fee</b>	<b>Total Cost</b>
HV5A	GREEHV01	3	7	REPLACE HYDRONIC HEATING SYSTEM	331,958	53,113	385,071
EL4B	GREEEL02	3	10	INTERIOR LIGHTING UPGRADE	195,406	31,265	226,671
PL1A	GREEPL02	3	13	WATER SUPPLY PIPING REPLACEMENT	259,116	41,459	300,575
PL2A	GREEPL03	3	14	DRAIN PIPING REPLACEMENT	393,324	62,932	456,256
AC3B	GREEAC04	3	5	STAIR AND RAILING SAFETY UPGRADES	139,134	22,261	161,395
IS1A	GREEIS01	3	11	REFINISH FLOORING	357,686	57,230	414,916
IS2B	GREEIS02	3	12	REFINISH WALLS	198,595	0	198,595
<b>Totals for Priority Class 3</b>					<b>1,875,220</b>	<b>268,260</b>	<b>2,143,480</b>
HV2B	GREEHV02	4	20	MODULAR COOLING EQUIPMENT REPLACEMENT	188,379	30,141	218,520
AC4B	GREEAC01	4	17	INTERIOR SIGNAGE AND DOOR HARDWARE UPGRADES	142,924	22,868	165,792
<b>Totals for Priority Class 4</b>					<b>331,303</b>	<b>53,008</b>	<b>384,312</b>
<b>Grand Totals for Projects &gt;= 100,000 and &lt; 500,000</b>					<b>2,206,523</b>	<b>321,268</b>	<b>2,527,791</b>

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Cost Range**  
 GREE : GREENE RESIDENCE HALL

<b>Cat. Code</b>	<b>Project Number</b>	<b>Pri Cls</b>	<b>Pri Seq</b>	<b>Project Title</b>	<b>Construction Cost</b>	<b>Professional Fee</b>	<b>Total Cost</b>
FS3A	GREEFS01	2	2	FIRE SPRINKLER SYSTEM INSTALLATION	643,319	102,931	746,250
				<b>Totals for Priority Class 2</b>	<b>643,319</b>	<b>102,931</b>	<b>746,250</b>
EL3B	GREEEL03	3	9	UPGRADE ELECTRICAL DISTRIBUTION NETWORK	525,061	84,010	609,071
				<b>Totals for Priority Class 3</b>	<b>525,061</b>	<b>84,010</b>	<b>609,071</b>
				<b>Grand Totals for Projects &gt;= 500,000</b>	<b>1,168,380</b>	<b>186,941</b>	<b>1,355,321</b>
				<b>Grand Totals For All Projects:</b>	<b>3,778,297</b>	<b>564,098</b>	<b>4,342,395</b>

**Detailed Project Summary**  
**Facility Condition Analysis**  
**Project Classification**  
GREE : GREENE RESIDENCE HALL

<b>Cat Code</b>	<b>Project Number</b>	<b>Pri. Seq.</b>	<b>Project Classification</b>	<b>Pri. Cls</b>	<b>Project Title</b>	<b>Total Cost</b>
ES4B	GREEES03	6	Capital Renewal	3	MEMBRANE ROOF REPLACEMENT	54,348
IS2B	GREEIS02	12	Capital Renewal	3	REFINISH WALLS	198,595
ES5A	GREEES01	18	Capital Renewal	4	EXTERIOR DOOR REPLACEMENT	16,801
ES5B	GREEES02	19	Capital Renewal	4	WINDOW REPLACEMENT	82,919
HV2B	GREEHV02	20	Capital Renewal	4	MODULAR COOLING EQUIPMENT REPLACEMENT	218,520
IS3B	GREEIS03	21	Capital Renewal	4	REFINISH CEILINGS	41,941
<b>Totals for Capital Renewal</b>						<b>613,124</b>
HV5A	GREEHV01	7	Deferred Maintenance	3	REPLACE HYDRONIC HEATING SYSTEM	385,071
EL5A	GREEEL01	8	Deferred Maintenance	3	REPLACE EMERGENCY GENERATOR	75,754
EL3B	GREEEL03	9	Deferred Maintenance	3	UPGRADE ELECTRICAL DISTRIBUTION NETWORK	609,071
EL4B	GREEEL02	10	Deferred Maintenance	3	INTERIOR LIGHTING UPGRADE	226,671
IS1A	GREEIS01	11	Deferred Maintenance	3	REFINISH FLOORING	414,916
PL1A	GREEPL02	13	Deferred Maintenance	3	WATER SUPPLY PIPING REPLACEMENT	300,575
PL2A	GREEPL03	14	Deferred Maintenance	3	DRAIN PIPING REPLACEMENT	456,256
PL1E	GREEPL01	15	Deferred Maintenance	3	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT	34,889
<b>Totals for Deferred Maintenance</b>						<b>2,503,203</b>
AC2A	GREEAC05	1	Plant Adaption	1	BUILDING ENTRY ACCESSIBILITY UPGRADES	12,146
FS3A	GREEFS01	2	Plant Adaption	2	FIRE SPRINKLER SYSTEM INSTALLATION	746,250
AC4A	GREEAC06	3	Plant Adaption	3	INTERIOR AMENITY ACCESSIBILITY UPGRADES	45,748
AC4A	GREEAC02	4	Plant Adaption	3	ACCESSIBILITY UPGRADES FOR RESIDENTIAL FACILITIES	45,616
AC3B	GREEAC04	5	Plant Adaption	3	STAIR AND RAILING SAFETY UPGRADES	161,395
AC3E	GREEAC03	16	Plant Adaption	4	RESTROOM ACCESSIBILITY UPGRADES	49,122
AC4B	GREEAC01	17	Plant Adaption	4	INTERIOR SIGNAGE AND DOOR HARDWARE UPGRADES	165,792
<b>Totals for Plant Adaption</b>						<b>1,226,068</b>
<b>Grand Total:</b>						<b>4,342,395</b>



**Detailed Project Summary**  
**Facility Condition Analysis**  
**Energy Conservation**  
 GREE : GREENE RESIDENCE HALL

<b>Cat Code</b>	<b>Project Number</b>	<b>Pri Cls</b>	<b>Pri Seq</b>	<b>Project Title</b>	<b>Total Cost</b>	<b>Annual Savings</b>	<b>Simple Payback</b>
ES4B	GREES03	3	6	MEMBRANE ROOF REPLACEMENT	54,348	700	77.64
EL4B	GREEL02	3	10	INTERIOR LIGHTING UPGRADE	226,671	7,900	28.69
<b>Totals for Priority Class 3</b>					<b>281,019</b>	<b>8,600</b>	<b>32.68</b>
ES5B	GREES02	4	19	WINDOW REPLACEMENT	82,919	200	414.6
<b>Totals for Priority Class 4</b>					<b>82,919</b>	<b>200</b>	<b>414.6</b>
<b>Grand Total:</b>					<b>363,938</b>	<b>8,800</b>	<b>41.36</b>

Detailed Project Summary  
Facility Condition Analysis  
Category/System Code  
GREE : GREENE RESIDENCE HALL

Cat. Code	Project Number	Pri Cls	Pri Seq	Project Title	Construction Cost	Professional Fee	Total Cost
AC2A	GREEAC05	1	1	BUILDING ENTRY ACCESSIBILITY UPGRADES	12,146	0	12,146
AC4A	GREEAC06	3	3	INTERIOR AMENITY ACCESSIBILITY UPGRADES	39,438	6,310	45,748
AC4A	GREEAC02	3	4	ACCESSIBILITY UPGRADES FOR RESIDENTIAL FACILITIES	39,324	6,292	45,616
AC3B	GREEAC04	3	5	STAIR AND RAILING SAFETY UPGRADES	139,134	22,261	161,395
AC3E	GREEAC03	4	16	RESTROOM ACCESSIBILITY UPGRADES	42,346	6,775	49,122
AC4B	GREEAC01	4	17	INTERIOR SIGNAGE AND DOOR HARDWARE UPGRADES	142,924	22,868	165,792
<b>Totals for System Code: ACCESSIBILITY</b>					<b>415,312</b>	<b>64,507</b>	<b>479,819</b>
EL5A	GREEEL01	3	8	REPLACE EMERGENCY GENERATOR	65,305	10,449	75,754
EL3B	GREEEL03	3	9	UPGRADE ELECTRICAL DISTRIBUTION NETWORK	525,061	84,010	609,071
EL4B	GREEEL02	3	10	INTERIOR LIGHTING UPGRADE	195,406	31,265	226,671
<b>Totals for System Code: ELECTRICAL</b>					<b>785,772</b>	<b>125,724</b>	<b>911,496</b>
ES4B	GREEES03	3	6	MEMBRANE ROOF REPLACEMENT	46,852	7,496	54,348
ES5A	GREEES01	4	18	EXTERIOR DOOR REPLACEMENT	14,483	2,317	16,801
ES5B	GREEES02	4	19	WINDOW REPLACEMENT	71,482	11,437	82,919
<b>Totals for System Code: EXTERIOR</b>					<b>132,817</b>	<b>21,251</b>	<b>154,068</b>
FS3A	GREEFS01	2	2	FIRE SPRINKLER SYSTEM INSTALLATION	643,319	102,931	746,250
<b>Totals for System Code: FIRE/LIFE SAFETY</b>					<b>643,319</b>	<b>102,931</b>	<b>746,250</b>
HV5A	GREEHV01	3	7	REPLACE HYDRONIC HEATING SYSTEM	331,958	53,113	385,071
HV2B	GREEHV02	4	20	MODULAR COOLING EQUIPMENT REPLACEMENT	188,379	30,141	218,520
<b>Totals for System Code: HVAC</b>					<b>520,337</b>	<b>83,254</b>	<b>603,591</b>
IS1A	GREEIS01	3	11	REFINISH FLOORING	357,686	57,230	414,916
IS2B	GREEIS02	3	12	REFINISH WALLS	198,595	0	198,595
IS3B	GREEIS03	4	21	REFINISH CEILINGS	41,941	0	41,941
<b>Totals for System Code: INTERIOR/FINISH SYS.</b>					<b>598,222</b>	<b>57,230</b>	<b>655,452</b>
PL1A	GREEPL02	3	13	WATER SUPPLY PIPING REPLACEMENT	259,116	41,459	300,575
PL2A	GREEPL03	3	14	DRAIN PIPING REPLACEMENT	393,324	62,932	456,256
PL1E	GREEPL01	3	15	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT	30,077	4,812	34,889
<b>Totals for System Code: PLUMBING</b>					<b>682,518</b>	<b>109,203</b>	<b>791,721</b>
<b>Grand Total:</b>					<b>3,778,297</b>	<b>564,098</b>	<b>4,342,395</b>

FACILITY CONDITION ANALYSIS

**SECTION 3**

SPECIFIC PROJECT DETAILS  
ILLUSTRATING DESCRIPTION / COST

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEAC05	<b>Title:</b>	BUILDING ENTRY ACCESSIBILITY UPGRADES
<b>Priority Sequence:</b>	1		
<b>Priority Class:</b>	1		
<b>Category Code:</b>	AC2A	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	BUILDING ENTRY
		<b>Element:</b>	GENERAL
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	403.6, 505	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/21/2009		
<b>Project Location:</b>	Undefined: Floor(s) 1		

**Project Description**

Current legislation related to accessibility requires that building entrances be wheelchair accessible. There are several sidewalk locations immediately adjacent to the building and leading to the building that have exterior steps that require handrails to be installed in accordance with handicapped accessibility guidelines. To comply with the intent of this legislation, it is recommended that compliant painted metal handrails be installed at the sidewalk steps leading to the facility from the northwest as required.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEAC05

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Freestanding handrail system, painted (15 feet minimum)	LF	60	\$91.11	\$5,467	\$150	\$9,000	\$14,467
<b>Project Totals:</b>				<b>\$5,467</b>		<b>\$9,000</b>	<b>\$14,467</b>

<b>Material/Labor Cost</b>		<b>\$14,467</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$10,122</u>
<b>General Contractor Mark Up at 20.0%</b>	+	<u>\$2,024</u>
<b>Construction Cost</b>		<u>\$12,146</u>
<b>No Professional Fees Required</b>		
<b>Total Project Cost</b>		<u><b>\$12,146</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEFS01	<b>Title:</b>	FIRE SPRINKLER SYSTEM INSTALLATION
<b>Priority Sequence:</b>	2		
<b>Priority Class:</b>	2		
<b>Category Code:</b>	FS3A	<b>System:</b>	FIRE/LIFE SAFETY
		<b>Component:</b>	SUPPRESSION
		<b>Element:</b>	SPRINKLERS
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	NFPA	1, 13, 13R, 101	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

Install an automatic fire sprinkler system in unprotected areas throughout the facility. This includes piping, valves, sprinkler heads, and piping supports. Install flow switches and sensors to interface with the fire alarm system. Cost has been included in this project for the installation of a fire pump if necessary.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
 GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEFS01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Install wet-pipe sprinkler system, including valves, piping, sprinkler heads, piping supports, etc.	SF	82,731	\$3.08	\$254,811	\$3.77	\$311,896	\$566,707
Fire pump, controls, piping, valves, and connections	GPM	1,000	\$115	\$115,410	\$6.40	\$6,400	\$121,810
<b>Project Totals:</b>				<b>\$370,221</b>		<b>\$318,296</b>	<b>\$688,517</b>

<b>Material/Labor Cost</b>		<b>\$688,517</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$536,099</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$107,220</b>
<b>Construction Cost</b>		<b>\$643,319</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$102,931</b>
<b>Total Project Cost</b>		<b>\$746,250</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEAC06	<b>Title:</b>	INTERIOR AMENITY ACCESSIBILITY UPGRADES
<b>Priority Sequence:</b>	3		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	AC4A	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	GENERAL
		<b>Element:</b>	FUNCTIONAL SPACE MOD.
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	211, 602, 804	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/21/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

Current accessibility legislation requires that building amenities be generally accessible to all persons. The configurations of the first floor's common kitchenette and the drinking fountains located on each floor are barriers to accessibility. The installation of wheelchair-accessible kitchenette cabinetry is recommended where applicable. All single level drinking fountains throughout the building should be replaced with dual level, refrigerated units.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
 GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEAC06

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
ADA compliant kitchenette unit with base cabinetry, overhead cabinetry, and amenities	SYS	1	\$4,894	\$4,894	\$1,999	\$1,999	\$6,893
Dual level drinking fountain	EA	19	\$1,216	\$23,104	\$374	\$7,106	\$30,210
<b>Project Totals:</b>				<b>\$27,998</b>		<b>\$9,105</b>	<b>\$37,103</b>

<b>Material/Labor Cost</b>		<b>\$37,103</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$32,865</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$6,573</b>
<b>Construction Cost</b>		<b>\$39,438</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$6,310</b>
<b>Total Project Cost</b>		<b>\$45,748</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEAC02	<b>Title:</b>	ACCESSIBILITY UPGRADES FOR RESIDENTIAL FACILITIES
<b>Priority Sequence:</b>	4		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	AC4A	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	GENERAL
		<b>Element:</b>	FUNCTIONAL SPACE MOD.
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	224, 806.1, 603, 604, 605, 606, 607, 608	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/20/2009		
<b>Project Location:</b>	Undefined: Floor(s) 2		

**Project Description**

There are minimal handicapped accessible features within this residential facility primarily aimed at handicapped guests. A handicapped accessible unisex restroom is located on the first floor by the mailroom, and some minor modifications have been made within the bathrooms on each floor. Provisions for resident accessibility for this facility are recommended. These should include the installation of ADA compliant signage, a wheelchair accessible bathroom facility, accessible storage space, specialized alarms, lever door hardware, and the adaptation of a sleeping room. To comply with the intent of the current accessibility legislation, it is recommended that at least two residential units be converted within this facility.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEAC02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Sleeping room specialty alarms, etc.	SYS	2	\$3,176	\$6,352	\$1,635	\$3,270	\$9,622
Bathroom accessibility upgrade	SYS	2	\$8,420	\$16,840	\$7,542	\$15,084	\$31,924
<b>Project Totals:</b>				<b>\$23,192</b>		<b>\$18,354</b>	<b>\$41,546</b>

<b>Material/Labor Cost</b>		<b>\$41,546</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$32,770</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$6,554</b>
<b>Construction Cost</b>		<b>\$39,324</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$6,292</b>
<b>Total Project Cost</b>		<b>\$45,616</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEAC04	<b>Title:</b>	STAIR AND RAILING SAFETY UPGRADES
<b>Priority Sequence:</b>	5		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	AC3B	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	INTERIOR PATH OF TRAVEL
		<b>Element:</b>	STAIRS AND RAILINGS
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	IBC	1003.3	
	ADAAG	505	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/20/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

Current legislation regarding building accessibility by the handicapped requires that stairs have graspable handrails on both sides, that the rails have specific cross-sectional geometry, and that the handrails continue horizontally at the landings with extensions. In addition, guardrails must prevent the passage of a 4 inch diameter sphere (6 inches in the triangle formed by the lower rail and tread / riser angle). Although the stairs are compliant with the code enforced at the time of construction until a major renovation occurs, they are deficient in handrail and guardrail design relative to current standards. Future renovation efforts should include comprehensive stair railing upgrades.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEAC04

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Wall-mounted handrail system per floor	FLR	18	\$573	\$10,314	\$521	\$9,378	\$19,692
Center handrail / guardrail system per floor	FLR	18	\$1,297	\$23,346	\$833	\$14,994	\$38,340
Railing system up to 42 inches high with pickets at 4-1/2 inches on center	LF	550	\$107	\$58,850	\$36.45	\$20,048	\$78,898
<b>Project Totals:</b>				<b>\$92,510</b>		<b>\$44,420</b>	<b>\$136,930</b>

<b>Material/Labor Cost</b>		<b>\$136,930</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$115,945</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$23,189</b>
<b>Construction Cost</b>		<b>\$139,134</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$22,261</b>
<b>Total Project Cost</b>		<b>\$161,395</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEES03	<b>Title:</b>	MEMBRANE ROOF REPLACEMENT
<b>Priority Sequence:</b>	6		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	ES4B	<b>System:</b>	EXTERIOR
		<b>Component:</b>	ROOF
		<b>Element:</b>	REPLACEMENT
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Energy Conservation	\$700	
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/21/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) R		

**Project Description**

The flat single ply membrane roofing system is not expected to outlast the scope of this analysis. Future budget modeling should include a provision for the replacement of the entire roofing system in the next ten years. Replace this roof with a similar application or the campus standard.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
 GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEES03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Membrane roof	SF	8,300	\$3.79	\$31,457	\$1.73	\$14,359	\$45,816
<b>Project Totals:</b>				<b>\$31,457</b>		<b>\$14,359</b>	<b>\$45,816</b>

<b>Material/Labor Cost</b>		<b>\$45,816</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$39,043</u>
<b>General Contractor Mark Up at 20.0%</b>	+	<u>\$7,809</u>
<b>Construction Cost</b>		<u>\$46,852</u>
<b>Professional Fees at 16.0%</b>	+	<u>\$7,496</u>
<b>Total Project Cost</b>		<u><b>\$54,348</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEHV01	<b>Title:</b>	REPLACE HYDRONIC HEATING SYSTEM
<b>Priority Sequence:</b>	7		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	HV5A	<b>System:</b>	HVAC
		<b>Component:</b>	STEAM/HYDRONIC DISTRIB.
		<b>Element:</b>	PIPING NETWORK
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

Remove the existing hydronic heating system. Install a new hydronic heating system, including piping, insulation, valves, radiators, unit heaters, and controls.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
 GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:**        GREEHV01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Replace hydronic heating system including piping, radiators, unit heaters, and demolition	SF	51,626	\$3.10	\$160,041	\$4.36	\$225,089	\$385,130
<b>Project Totals:</b>				<b>\$160,041</b>		<b>\$225,089</b>	<b>\$385,130</b>

<b>Material/Labor Cost</b>		\$385,130
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		\$276,632
<b>General Contractor Mark Up at 20.0%</b>	+	\$55,326
<b>Construction Cost</b>		\$331,958
<b>Professional Fees at 16.0%</b>	+	\$53,113
<b>Total Project Cost</b>		<b>\$385,071</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEEL01	<b>Title:</b>	REPLACE EMERGENCY GENERATOR
<b>Priority Sequence:</b>	8		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	EL5A	<b>System:</b>	ELECTRICAL
		<b>Component:</b>	EMERGENCY POWER SYSTEM
		<b>Element:</b>	GENERATION/DISTRIBUTION
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	NEC	Article 700	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Item Only: Floor(s) 1		

**Project Description**

Replace the existing emergency generator set with an appropriately sized unit based on current facility requirements. Replacement costs include the demolition of existing equipment and installation a new generator, automatic transfer switches (ATS), diesel fuel tank, battery and charger, exhaust system, and necessary electrical connections. Specify a diesel-fired unit unless otherwise directed by local standards.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEEL01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Diesel generator set, including fuel tank, battery, charger, exhaust, and automatic transfer switches	KW	150	\$318	\$47,700	\$83.00	\$12,450	\$60,150
<b>Project Totals:</b>				<b>\$47,700</b>		<b>\$12,450</b>	<b>\$60,150</b>

<b>Material/Labor Cost</b>		\$60,150
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		\$54,421
<b>General Contractor Mark Up at 20.0%</b>	+	\$10,884
<b>Construction Cost</b>		\$65,305
<b>Professional Fees at 16.0%</b>	+	\$10,449
<b>Total Project Cost</b>		<b>\$75,754</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEEL03	<b>Title:</b>	UPGRADE ELECTRICAL DISTRIBUTION NETWORK
<b>Priority Sequence:</b>	9		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	EL3B	<b>System:</b>	ELECTRICAL
		<b>Component:</b>	SECONDARY DISTRIBUTION
		<b>Element:</b>	DISTRIBUTION NETWORK
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	NEC	Articles 110, 210, 220, 230	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

An upgrade of the building electrical system is recommended. Aging components, such as the circuit breakers, could serve as fire hazards if they fail to open a circuit in an overload or short circuit condition. Remove existing aged electrical components and branch circuitry. Install new power panels, switches, raceways, conductors, and devices. Provide molded case thermal magnetic circuit breakers and HACR circuit breakers for HVAC equipment. Redistribute the electrical loads to the appropriate areas to ensure safe and reliable power to building occupants. Provide ground fault circuit interrupter (GFCI) protection where required, and clearly label all panels for circuit identification.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEEL03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Power panels, conductors, raceways, devices, demolition, and cut and patching materials	SF	82,731	\$2.98	\$246,538	\$4.46	\$368,980	\$615,519
<b>Project Totals:</b>				<b>\$246,538</b>		<b>\$368,980</b>	<b>\$615,519</b>

<b>Material/Labor Cost</b>		<b>\$615,519</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$437,551</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$87,510</b>
<b>Construction Cost</b>		<b>\$525,061</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$84,010</b>
<b>Total Project Cost</b>		<b>\$609,071</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEEL02	<b>Title:</b>	INTERIOR LIGHTING UPGRADE
<b>Priority Sequence:</b>	10		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	EL4B	<b>System:</b>	ELECTRICAL
		<b>Component:</b>	DEVICES AND FIXTURES
		<b>Element:</b>	INTERIOR LIGHTING
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Energy Conservation	\$7,900	
<b>Code Application:</b>	NEC	Articles 210, 410	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

An interior lighting upgrade is recommended. Replace existing aged and / or inefficient light fixtures with modern fixtures of the latest energy-efficient design. Select lamps with the same color temperature and rendering index for lighting uniformity. Install occupancy sensors in select areas for additional energy conservation.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEEL02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
High efficiency fluorescent fixtures, occupancy sensors, and demolition of existing lighting	SF	51,626	\$1.93	\$99,638	\$2.36	\$121,837	\$221,476
<b>Project Totals:</b>				<b>\$99,638</b>		<b>\$121,837</b>	<b>\$221,476</b>

<b>Material/Labor Cost</b>		<b>\$221,476</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$162,838</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$32,568</b>
<b>Construction Cost</b>		<b>\$195,406</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$31,265</b>
<b>Total Project Cost</b>		<b>\$226,671</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEIS01	<b>Title:</b>	REFINISH FLOORING
<b>Priority Sequence:</b>	11		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS1A	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	FLOOR
		<b>Element:</b>	FINISHES-DRY
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/20/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

The common areas within the facility, such as the corridors, study lounges, social rooms, and the coordinator's office, are generally carpeted, with the exception of the first floor common areas, including the living, recreation, and vending rooms, which are primarily terrazzo. The individual dormitory rooms have vinyl floor tile, along with the laundries and housekeeping space. Carpet and vinyl tile floor finish upgrades should be considered as part of any future cosmetic improvements or major comprehensive renovation efforts. The ceramic tile applications within the bathrooms appear to be sound and should provide satisfactory service over the next ten years.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEIS01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Carpet	SF	26,470	\$5.36	\$141,879	\$2.00	\$52,940	\$194,819
Vinyl floor tile	SF	26,470	\$3.53	\$93,439	\$2.50	\$66,175	\$159,614
<b>Project Totals:</b>				<b>\$235,318</b>		<b>\$119,115</b>	<b>\$354,433</b>

<b>Material/Labor Cost</b>		<b>\$354,433</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$298,072</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$59,614</b>
<b>Construction Cost</b>		<b>\$357,686</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$57,230</b>
<b>Total Project Cost</b>		<b>\$414,916</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEIS02	<b>Title:</b>	REFINISH WALLS
<b>Priority Sequence:</b>	12		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	IS2B	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	PARTITIONS
		<b>Element:</b>	FINISHES

**Building Code:** GREE  
**Building Name:** GREENE RESIDENCE HALL  
**Subclass/Savings:** Not Applicable

**Code Application:** Not Applicable

**Project Class:** Capital Renewal  
**Project Date:** 10/20/2009

**Project Location:** Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9

**Project Description**

The interior walls are all painted and constructed of either masonry block or sheetrock partitions. Wall finish upgrades should be considered as part of any future cosmetic improvements or major comprehensive renovation efforts.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEIS02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Standard wall finish (paint, wall covering, etc.)	SF	282,070	\$0.17	\$47,952	\$0.81	\$228,477	\$276,429
<b>Project Totals:</b>				<b>\$47,952</b>		<b>\$228,477</b>	<b>\$276,429</b>

<b>Material/Labor Cost</b>		<b>\$276,429</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$165,496</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$33,099</b>
<b>Construction Cost</b>		<b>\$198,595</b>
<b>No Professional Fees Required</b>		
<b>Total Project Cost</b>		<b>\$198,595</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEPL02	<b>Title:</b>	WATER SUPPLY PIPING REPLACEMENT
<b>Priority Sequence:</b>	13		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	PL1A	<b>System:</b>	PLUMBING
		<b>Component:</b>	DOMESTIC WATER
		<b>Element:</b>	PIPING NETWORK
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	IPC	Chapter 6	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

The replacement of the aging water piping network is recommended. Failure to replace the water piping will result in frequent leaks and escalating maintenance costs. Remove the existing water supply network. Install new copper water supply piping with fiberglass insulation. Install isolation valves, pressure regulators, shock absorbers, backflow preventers, and vacuum breakers as needed.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
 GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEPL02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Copper pipe and fittings, valves, backflow prevention devices, insulation, hangers, demolition, and cut and patching materials	SF	82,731	\$1.14	\$94,313	\$2.85	\$235,783	\$330,097
<b>Project Totals:</b>				<b>\$94,313</b>		<b>\$235,783</b>	<b>\$330,097</b>

<b>Material/Labor Cost</b>		<b>\$330,097</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$215,930</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$43,186</b>
<b>Construction Cost</b>		<b>\$259,116</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$41,459</b>
<b>Total Project Cost</b>		<b>\$300,575</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEPL03	<b>Title:</b>	DRAIN PIPING REPLACEMENT
<b>Priority Sequence:</b>	14		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	PL2A	<b>System:</b>	PLUMBING
		<b>Component:</b>	WASTEWATER
		<b>Element:</b>	PIPING NETWORK
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	IPC	Chapters 7-11	
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

The replacement of the aging drain piping is recommended throughout the facility. Failure to replace the old piping will result in frequent leaks and escalating maintenance costs. Remove sanitary and storm drain piping as needed. Install new cast-iron drain piping networks with copper runouts to the fixtures. Install new floor drains, roof drains, and traps.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEPL03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Cast-iron drain piping and fittings, copper pipe and fittings, floor / roof drains, traps, hangers, demolition, and cut and patching materials	SF	82,731	\$1.81	\$149,743	\$4.17	\$344,988	\$494,731
<b>Project Totals:</b>				<b>\$149,743</b>		<b>\$344,988</b>	<b>\$494,731</b>

<b>Material/Labor Cost</b>		<b>\$494,731</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$327,770</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$65,554</b>
<b>Construction Cost</b>		<b>\$393,324</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$62,932</b>
<b>Total Project Cost</b>		<b>\$456,256</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEPL01	<b>Title:</b>	DOMESTIC HOT WATER HEAT EXCHANGER REPLACEMENT
<b>Priority Sequence:</b>	15		
<b>Priority Class:</b>	3		
<b>Category Code:</b>	PL1E	<b>System:</b>	PLUMBING
		<b>Component:</b>	DOMESTIC WATER
		<b>Element:</b>	HEATING
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Deferred Maintenance		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Item Only: Floor(s) 1		

**Project Description**

The replacement of the domestic hot water converters is recommended. With age, heat exchanger efficiency is reduced by internal tube scaling. Internal wear will eventually lead to failure, allowing contaminants to enter the water system. Remove the existing systems. Install new heat exchangers, pumps, piping, and controls as needed.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEPL01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Heat exchanger, pumps, piping, valves, controls, insulation, and demolition	GPM	96	\$183	\$17,578	\$150	\$14,354	\$31,932
<b>Project Totals:</b>				<b>\$17,578</b>		<b>\$14,354</b>	<b>\$31,932</b>

<b>Material/Labor Cost</b>		\$31,932
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		\$25,064
<b>General Contractor Mark Up at 20.0%</b>	+	\$5,013
<b>Construction Cost</b>		\$30,077
<b>Professional Fees at 16.0%</b>	+	\$4,812
<b>Total Project Cost</b>		<b>\$34,889</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEAC03	<b>Title:</b>	RESTROOM ACCESSIBILITY UPGRADES
<b>Priority Sequence:</b>	16		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	AC3E	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	INTERIOR PATH OF TRAVEL
		<b>Element:</b>	RESTROOMS/BATHROOMS
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	604, 605, 606, 607, 608	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/20/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

The overall level of bathroom accessibility is good but short of full compliance with modern accessibility legislation. While the clearances and clear floor spaces are adequate, compliant mirrors and new accessible plumbing fixtures are recommended over the next ten years in the common bathrooms on floors two through ten.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEAC03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Mirror	EA	9	\$292	\$2,628	\$224	\$2,016	\$4,644
ADA compliant plumbing fixture	EA	27	\$810	\$21,870	\$692	\$18,684	\$40,554
<b>Project Totals:</b>				<b>\$24,498</b>		<b>\$20,700</b>	<b>\$45,198</b>

<b>Material/Labor Cost</b>		<b>\$45,198</b>
<b>Material Index</b>		<b>100.7%</b>
<b>Labor Index</b>		<b>51.3%</b>
<b>Material/Labor Indexed Cost</b>		<b>\$35,289</b>
<b>General Contractor Mark Up at 20.0%</b>	<b>+</b>	<b>\$7,058</b>
<b>Construction Cost</b>		<b>\$42,346</b>
<b>Professional Fees at 16.0%</b>	<b>+</b>	<b>\$6,775</b>
<b>Total Project Cost</b>		<b>\$49,122</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEAC01	<b>Title:</b>	INTERIOR SIGNAGE AND DOOR HARDWARE UPGRADES
<b>Priority Sequence:</b>	17		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	AC4B	<b>System:</b>	ACCESSIBILITY
		<b>Component:</b>	GENERAL
		<b>Element:</b>	OTHER
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	ADAAG	309.4, 703.1	
<b>Project Class:</b>	Plant Adaption		
<b>Project Date:</b>	10/20/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9, R		

**Project Description**

While the interior doors are suitable for ten future years of service, the knob actuated door hardware presents a barrier to accessibility. Accessibility legislation requires that door hardware be designed for operation by people with little or no ability to grasp objects with their hands. To comply with the intent of this legislation, it is recommended that lever handle door hardware be installed on all doors that currently still have knobs. In addition, the signage to the permanent spaces is non-compliant. It is recommended that all non-compliant signage be upgraded to conform to appropriate accessibility standards. Compliant signage should meet specific size, graphical, Braille, height, and location requirements. This scope includes all directional signage.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEAC01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
ADA compliant signage	EA	320	\$53.11	\$16,995	\$15.62	\$4,998	\$21,994
Lever actuated door hardware	EA	320	\$273	\$87,360	\$69.77	\$22,326	\$109,686
<b>Project Totals:</b>				<b>\$104,355</b>		<b>\$27,325</b>	<b>\$131,680</b>

<b>Material/Labor Cost</b>		<b>\$131,680</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$119,103</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$23,821</b>
<b>Construction Cost</b>		<b>\$142,924</b>
<b>Professional Fees at 16.0%</b>	+	<b>\$22,868</b>
<b>Total Project Cost</b>		<b>\$165,792</b>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEES01	<b>Title:</b>	EXTERIOR DOOR REPLACEMENT
<b>Priority Sequence:</b>	18		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	ES5A	<b>System:</b>	EXTERIOR
		<b>Component:</b>	FENESTRATIONS
		<b>Element:</b>	DOORS
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/20/2009		
<b>Project Location:</b>	Building-wide: Floor(s) 1		

**Project Description**

It is recommended that aged and inefficient exterior glass storefront entry door systems be replaced. This project includes only the primary entrance doors. The replacement units should maintain the architectural design aspects of this facility and be modern, energy-efficient applications.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
 GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:**        GREEES01

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
High traffic door system	LEAF	4	\$1,978	\$7,912	\$1,999	\$7,996	\$15,908
<b>Project Totals:</b>				<b>\$7,912</b>		<b>\$7,996</b>	<b>\$15,908</b>

<b>Material/Labor Cost</b>		<b>\$15,908</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$12,069</u>
<b>General Contractor Mark Up at 20.0%</b>	+	<u>\$2,414</u>
<b>Construction Cost</b>		<u>\$14,483</u>
<b>Professional Fees at 16.0%</b>	+	<u>\$2,317</u>
<b>Total Project Cost</b>		<u><b>\$16,801</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREES02	<b>Title:</b>	WINDOW REPLACEMENT
<b>Priority Sequence:</b>	19		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	ES5B	<b>System:</b>	EXTERIOR
		<b>Component:</b>	FENESTRATIONS
		<b>Element:</b>	WINDOWS
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Energy Conservation	\$200	
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/20/2009		
<b>Project Location:</b>	Building-wide: Floor(s) 1		

**Project Description**

It is recommended that the single pane, aluminum-framed original window applications on the first floor be upgraded to thermal pane systems. Such double pane systems will reduce the energy required to operate the building. Repair or replacement of the windowsills and trim may also be necessary.



**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEES02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Typical standard glazing applications	SF	780	\$57.27	\$44,671	\$36.45	\$28,431	\$73,102
<b>Project Totals:</b>				<b>\$44,671</b>		<b>\$28,431</b>	<b>\$73,102</b>

<b>Material/Labor Cost</b>		\$73,102
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$59,568</u>
<b>General Contractor Mark Up at 20.0%</b>	+	<u>\$11,914</u>
<b>Construction Cost</b>		<u>\$71,482</u>
<b>Professional Fees at 16.0%</b>	+	<u>\$11,437</u>
<b>Total Project Cost</b>		<u><b>\$82,919</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEHV02	<b>Title:</b>	MODULAR COOLING EQUIPMENT REPLACEMENT
<b>Priority Sequence:</b>	20		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	HV2B	<b>System:</b>	HVAC
		<b>Component:</b>	COOLING
		<b>Element:</b>	HEAT REJECTION
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/14/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

The replacement of the existing through-wall air conditioners is recommended. Remove the existing units, and install new units of the latest energy-efficient design.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:**       GREEHV02

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Through-wall air conditioner, connections, and demolition	TON	140	\$843	\$118,020	\$531	\$74,340	\$192,360
<b>Project Totals:</b>				<b>\$118,020</b>		<b>\$74,340</b>	<b>\$192,360</b>

<b>Material/Labor Cost</b>		<b>\$192,360</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<u>\$156,983</u>
<b>General Contractor Mark Up at 20.0%</b>	+	<u>\$31,397</u>
<b>Construction Cost</b>		<u>\$188,379</u>
<b>Professional Fees at 16.0%</b>	+	<u>\$30,141</u>
<b>Total Project Cost</b>		<u><b>\$218,520</b></u>

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
GREE : GREENE RESIDENCE HALL

**Project Description**

<b>Project Number:</b>	GREEIS03	<b>Title:</b>	REFINISH CEILINGS
<b>Priority Sequence:</b>	21		
<b>Priority Class:</b>	4		
<b>Category Code:</b>	IS3B	<b>System:</b>	INTERIOR/FINISH SYS.
		<b>Component:</b>	CEILINGS
		<b>Element:</b>	REPLACEMENT
<b>Building Code:</b>	GREE		
<b>Building Name:</b>	GREENE RESIDENCE HALL		
<b>Subclass/Savings:</b>	Not Applicable		
<b>Code Application:</b>	Not Applicable		
<b>Project Class:</b>	Capital Renewal		
<b>Project Date:</b>	10/20/2009		
<b>Project Location:</b>	Floor-wide: Floor(s) 1, 10, 2, 3, 4, 5, 6, 7, 8, 9		

**Project Description**

Most of the ceilings within the facility are painted, although there are some suspended grid acoustical tile systems in the first floor common areas. Painted ceiling finish upgrades should be considered as part of any future cosmetic improvements or major comprehensive renovation efforts.

**Specific Project Details**  
**Facility Condition Analysis**  
**Section Three**  
 GREE : GREENE RESIDENCE HALL

**Project Cost**

**Project Number:** GREEIS03

**Task Cost Estimate**

<b>Task Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Material Unit Cost</b>	<b>Total Material Cost</b>	<b>Labor Unit Cost</b>	<b>Total Labor Cost</b>	<b>Total Cost</b>
Painted ceiling finish application	SF	59,570	\$0.17	\$10,127	\$0.81	\$48,252	\$58,379
<b>Project Totals:</b>				<b>\$10,127</b>		<b>\$48,252</b>	<b>\$58,379</b>

<b>Material/Labor Cost</b>		<b>\$58,379</b>
<b>Material Index</b>		100.7%
<b>Labor Index</b>		51.3%
<b>Material/Labor Indexed Cost</b>		<b>\$34,951</b>
<b>General Contractor Mark Up at 20.0%</b>	+	<b>\$6,990</b>
<b>Construction Cost</b>		<b>\$41,941</b>
<b>No Professional Fees Required</b>		
<b>Total Project Cost</b>		<b>\$41,941</b>



FACILITY CONDITION ANALYSIS

**SECTION 4**

**DRAWINGS  
AND PROJECT LOCATIONS**







FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376

PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING

PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09




Drawn by: J.T.V.

Project No. 09-041

FIRST  
FLOOR  
PLAN

Sheet No.


1 of 10





FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING


PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS


PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09  
Drawn by: J.T.V.  
Project No. 09-041

SECOND  
FLOOR  
PLAN




AC02





FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING

PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED



Date: 12/04/09

Drawn by: J.T.V.

Project No. 09-041

THIRD  
FLOOR  
PLAN


Sheet No.  
3 of 10





FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING

PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09



Drawn by: J.T.V.

Project No. 09-041

FOURTH  
FLOOR  
PLAN

Sheet No.



4 of 10





FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING

PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09


Drawn by: J.T.V.

Project No. 09-041

FIFTH  
FLOOR  
PLAN

Sheet No.



5 of 10





FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING

PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09


Drawn by: J.T.V.

Project No. 09-041

SIXTH  
FLOOR  
PLAN

Sheet No.


6 of 10





FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING

PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09



Drawn by: J.T.V.

Project No. 09-041

SEVENTH  
FLOOR  
PLAN

Sheet No.



7 of 10





FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING


PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09  
Drawn by: J.T.V.  
Project No. 09-041

EIGHTH  
FLOOR  
PLAN









FACILITY  
CONDITION  
ANALYSIS

2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376



PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING


PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09  
Drawn by: J.T.V.  
Project No. 09-041


NINTH  
FLOOR  
PLAN





FACILITY  
CONDITION  
ANALYSIS


2165 West Park Court  
Suite N  
Stone Mountain GA 30087  
770.879.7376

  
PROJECT NUMBER  
APPLIES TO  
ONE ROOM ONLY

  
PROJECT NUMBER  
APPLIES TO  
ONE ITEM ONLY

  
PROJECT NUMBER  
APPLIES TO  
ENTIRE BUILDING

  
PROJECT NUMBER  
APPLIES TO  
ENTIRE FLOOR

  
PROJECT NUMBER  
APPLIES TO A SITUATION  
OF UNDEFINED EXTENTS

  
PROJECT NUMBER  
APPLIES TO AREA  
AS NOTED

Date: 12/04/09




Drawn by: J.T.V.

Project No. 09-041

TENTH  
FLOOR  
PLAN

Sheet No.  
10 of 10

ROOF  
AC01 ES03



FACILITY CONDITION ANALYSIS

**SECTION 5**

LIFE CYCLE MODEL SUMMARY  
AND PROJECTIONS



**Life Cycle Model**  
**Building Component Summary**  
**GREE : GREENE RESIDENCE HALL**


<b>Unifomat Code</b>	<b>Component Description</b>	<b>Qty</b>	<b>Units</b>	<b>Unit Cost</b>	<b>Complex Adj</b>	<b>Total Cost</b>	<b>Install Date</b>	<b>Life Exp</b>
B2010	EXTERIOR FINISH RENEWAL	14,990	SF	\$1.30		\$19,541	1966	10
B2010	EXTERIOR FINISH RENEWAL	27,850	SF	\$1.30	.31	\$11,255	1966	10
B2020	STANDARD GLAZING AND CURTAIN WALL	760	SF	\$104.04		\$79,068	1966	55
B2020	STANDARD GLAZING AND CURTAIN WALL	6,800	SF	\$104.04		\$707,449	2003	55
B2030	HIGH TRAFFIC EXTERIOR DOOR SYSTEM	4	LEAF	\$4,311.24		\$17,245	1966	20
B2030	LOW TRAFFIC EXTERIOR DOOR SYSTEM	8	LEAF	\$2,863.29		\$22,906	1966	40
B3010	MEMBRANE ROOF	8,300	SF	\$6.41		\$53,176	1990	15
C1020	STANDARD DOOR AND FRAME INCLUDING HARDWARE	20	LEAF	\$783.68		\$15,674	1966	35
C1020	STANDARD DOOR AND FRAME INCLUDING HARDWARE	200	LEAF	\$783.68		\$156,736	1966	35
C1020	RATED DOOR AND FRAME INCLUDING HARDWARE	300	LEAF	\$1,489.06		\$446,718	1966	35
C1020	INTERIOR DOOR HARDWARE	300	EA	\$423.04		\$126,913	1966	15
C1020	INTERIOR DOOR HARDWARE	20	EA	\$423.04		\$8,461	1966	15
C1020	INTERIOR DOOR HARDWARE	200	EA	\$423.04		\$84,608	1966	15
C3010	STANDARD WALL FINISH (PAINT, WALL COVERING, ETC.)	282,070	SF	\$0.80		\$225,949	1966	10
C3020	CARPET	26,470	SF	\$8.75		\$231,519	1966	10
C3020	VINYL FLOOR TILE	26,470	SF	\$6.59		\$174,381	1966	15
C3020	CERAMIC FLOOR TILE	7,940	SF	\$17.36		\$137,857	1966	20
C3020	RESURFACE AND SEAL CONCRETE OR TERRAZZO	5,290	SF	\$5.85		\$30,929	1966	50
C3030	ACOUSTICAL TILE CEILING SYSTEM	6,620	SF	\$4.99		\$33,054	1966	15
C3030	PAINTED CEILING FINISH APPLICATION	59,570	SF	\$0.80		\$47,718	1966	15
D1010	ELEVATOR MODERNIZATION - TRACTION - HIGH RISE	2	EA	\$160,245.86		\$320,492	2005	25
D1010	ELEVATOR CAB RENOVATION - PASSENGER	2	EA	\$26,616.80		\$53,234	2005	12
D2010	PLUMBING FIXTURES - DORMITORY / APARTMENTS	82,731	SF	\$4.99		\$412,605	1966	35
D2020	WATER PIPING - DORMITORY / APARTMENTS	82,731	SF	\$3.55		\$293,802	1966	35
D2020	DOMESTIC WATER PRESSURE BOOSTER SYSTEM	1	SYS	\$8,868.58		\$8,869	1990	20
D2020	WATER HEATER, SHELL AND TUBE HEAT EXCHANGER	96	GPM	\$355.69		\$34,146	1966	24
D2030	DRAIN PIPING - DORMITORY / APARTMENTS	82,731	SF	\$5.40		\$446,841	1966	40
D2050	AIR COMPRESSOR PACKAGE (AVERAGE SIZE)	1	SYS	\$6,456.49		\$6,456	1990	25
D3020	HEATING SYSTEM, STEAM OR HYDRONIC	51,626	SF	\$7.30		\$376,967	1966	25

**Life Cycle Model**  
**Building Component Summary**  
**GREE : GREENE RESIDENCE HALL**

<b>Unifomat Code</b>	<b>Component Description</b>	<b>Qty</b>	<b>Units</b>	<b>Unit Cost</b>	<b>Complex Adj</b>	<b>Total Cost</b>	<b>Install Date</b>	<b>Life Exp</b>
D3040	CONDENSATE RECEIVER	1	SYS	\$9,504.01		\$9,504	1966	15
D3040	EXHAUST FAN - CENTRIFUGAL ROOF EXHAUSTER OR SIMILAR	2	EA	\$2,768.62		\$5,537	2005	20
D3040	EXHAUST FAN - UTILITY SET OR SIMILAR	3	EA	\$3,660.81		\$10,982	2005	20
D3040	EXHAUST FAN - PROPELLER TYPE OR SIMILAR	1	EA	\$1,357.34		\$1,357	2005	20
D3040	HVAC SYSTEM - DORMITORY / APARTMENTS	31,105	SF	\$19.20		\$597,183	2004	25
D3040	BASE MTD. PUMP - UP TO 15 HP	9	HP	\$3,175.77		\$28,582	2004	20
D3050	THRU-WALL AC UNIT	140	TON	\$1,528.27		\$213,958	2005	10
D5010	ELECTRICAL SYSTEM - DORMITORY / APARTMENTS	82,731	SF	\$7.21		\$596,280	1966	50
D5010	ELECTRICAL SWITCHGEAR 120/208V	2,000	AMP	\$32.96		\$65,927	2005	20
D5020	EXIT SIGNS (CENTRAL POWER)	90	EA	\$163.78		\$14,740	2005	20
D5020	EXTERIOR LIGHT (HID)	2	EA	\$689.58		\$1,379	2000	20
D5020	LIGHTING - DORMITORY / APARTMENTS	51,626	SF	\$4.30		\$222,006	1966	20
D5020	LIGHTING - DORMITORY / APARTMENTS	31,105	SF	\$4.30		\$133,760	2005	20
D5030	FIRE ALARM SYSTEM, POINT ADDRESSABLE	82,731	SF	\$2.61		\$216,308	2004	15
D5040	GENERATOR, DIESEL (UP TO 50 KW)	12	KW	\$1,123.84		\$13,486	1966	25
E2010	KITCHENETTE UNIT WITH CABINETS AND AMENITIES	1	LOT	\$5,940.22		<u>\$5,940</u>	1966	20
						<b>\$6,721,498</b>		

# Life Cycle Model Expenditure Projections

GREE : GREENE RESIDENCE HALL



Average Annual Renewal Cost Per SqFt \$3.31





FACILITY CONDITION ANALYSIS

**SECTION 6**

PHOTOGRAPHIC LOG



**Photo Log - Facility Condition  
Analysis  
GREE : GREENE RESIDENCE HALL**

<b>Photo ID No</b>	<b>Description</b>	<b>Location</b>	<b>Date</b>
GREE001a	Single ply membrane roof application	Roof	9/16/2009
GREE001e	HVAC equipment	Roof	9/16/2009
GREE002a	Single ply membrane roof application	Roof	9/16/2009
GREE002e	Air handling equipment	Roof	9/16/2009
GREE003a	Non-accessible handrails	Stairwell	9/16/2009
GREE003e	Condensing unit	Roof	9/16/2009
GREE004a	Typical door hardware and room signage	Tenth floor	9/16/2009
GREE004e	HVAC equipment	Roof	9/16/2009
GREE005a	Previous ceramic tile repair	Tenth floor, showers	9/16/2009
GREE005e	Elevator machine	Roof, penthouse	9/16/2009
GREE006a	Stained carpet with tear	Tenth floor	9/16/2009
GREE006e	Lavatories	Tenth floor, restroom	9/16/2009
GREE007a	Standard dorm room cabinetry	Ninth floor, AV room	9/16/2009
GREE007e	Water closet	Tenth floor, restroom	9/16/2009
GREE008a	Metal pan floor structure and inter-wall pipes	Sixth floor, pipe chase	9/16/2009
GREE008e	Shower components	Tenth floor, restroom	9/16/2009
GREE009a	Stained carpet	First floor, coordinator's office	9/16/2009
GREE009e	Drain piping	Tenth floor, restroom	9/16/2009
GREE010a	Inaccessible sink and countertop stove	First floor, kitchen	9/16/2009
GREE010e	Secondary electrical panel	Tenth floor, corridor	9/16/2009
GREE011a	Brick masonry and concrete panel facade with dual pane windows	South side	9/16/2009
GREE011e	Radiator	Ninth floor, room 907	9/16/2009
GREE012a	Brick masonry and concrete panel facade with dual pane windows	South side	9/16/2009
GREE012e	Interior lighting	Ninth floor, room 907	9/16/2009
GREE013a	Brick masonry and concrete panel facade with dual pane windows	West side	9/16/2009
GREE013e	Interior lighting	Sixth floor, room 621	9/16/2009
GREE014a	Exterior steps needing handrails	Northwest corner	9/16/2009
GREE014e	Interior lighting	Sixth floor, room 621	9/16/2009
GREE015a	Brick masonry and concrete panel facade with dual pane windows	North side	9/16/2009
GREE015e	Radiator	Sixth floor, room 621	9/16/2009
GREE016a	Brick masonry and concrete panel facade with dual pane windows	North side	9/16/2009

**Photo Log - Facility Condition  
Analysis  
GREE : GREENE RESIDENCE HALL**

<b>Photo ID No</b>	<b>Description</b>	<b>Location</b>	<b>Date</b>
GREE016e	Drain piping	Sixth floor, pipe chase	9/16/2009
GREE017a	Brick masonry and concrete panel facade with dual pane windows	East side	9/16/2009
GREE017e	Interior lighting and exit signage	First floor, room 123	9/16/2009
GREE018a	Original single pane, aluminum-framed windows	First floor	9/16/2009
GREE018e	Stainless steel sink	First floor, room 115	9/16/2009
GREE019e	Electrical receptacles	First floor, room 115	9/16/2009
GREE020e	Fire alarm panels	First floor, room 103	9/16/2009
GREE021e	Air handling equipment	First floor, room 122	9/16/2009
GREE022e	Main electrical distribution equipment	First floor, room 119-OS	9/16/2009
GREE023e	Electrical distribution equipment	First floor, room 121-OS	9/16/2009
GREE024e	Pump equipment	First floor, room 121-OS	9/16/2009
GREE025e	Pump equipment	First floor, room 121-OS	9/16/2009
GREE026e	Condensate return system	First floor, room 121-OS	9/16/2009
GREE027e	Heat exchangers	First floor, room 121-OS	9/16/2009
GREE028e	Booster pump system	First floor, room 121-OS	9/16/2009
GREE029e	Compressor	First floor, room 121-OS	9/16/2009
GREE030e	Emergency generator	First floor, room 121-OS	9/16/2009
GREE031e	Condensing unit and tank	Site	9/16/2009
GREE032e	Backflow preventer	Site	9/16/2009
GREE033e	Exterior lighting	Exterior	9/16/2009
GREE034e	Condensing unit and exterior lighting	Site	9/16/2009
GREE035e	Exhaust fan	Exterior	9/16/2009

Facility Condition Analysis - Photo Log



GREE001A.jpg



GREE001E.jpg



GREE002A.jpg



GREE002E.jpg



GREE003A.jpg



GREE003E.jpg



GREE004A.jpg



GREE004E.jpg



GREE005A.jpg



GREE005E.jpg



GREE006A.jpg



GREE006E.jpg



GREE007A.jpg




GREE007E.jpg



GREE008A.jpg



GREE008E.jpg



GREE009A.jpg



GREE009E.jpg



GREE010A.jpg



GREE010E.jpg

Facility Condition Analysis - Photo Log




GREE011A.jpg



GREE011E.jpg



GREE012A.jpg



GREE012E.jpg



GREE013A.jpg



GREE013E.jpg




GREE014A.jpg



GREE014E.jpg



GREE015A.jpg



GREE015E.jpg



GREE016A.jpg



GREE016E.jpg



GREE017A.jpg



GREE017E.jpg




GREE018A.jpg



GREE018E.jpg



GREE019E.jpg



GREE020E.jpg



GREE021E.jpg



GREE022E.jpg

Facility Condition Analysis - Photo Log



GREE023E.jpg



GREE024E.jpg



GREE025E.jpg



GREE026E.jpg



GREE027E.jpg



GREE028E.jpg



GREE029E.jpg



GREE030E.jpg



GREE031E.jpg



GREE032E.jpg



GREE033E.jpg



GREE034E.jpg



GREE035E.jpg